

Technical Service Bulletin

Mazda North American Operations
Irvine, CA 92618-2922



Subject: PASSENGER-SIDE OUTER DOOR MIRROR GLASS TILTS DOWN	Bulletin No.: 09-037/23
	Last Issued : 11/15/2023

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red.

Previous TSBs:	Date(s) Issued:
09-037/23	10/18/23

APPLICABLE MODEL(S)/VINS

2024 CX-90 with VINS lower than JM3KK*****128554 (produced before August 12, 2023)

DESCRIPTION

Some customers may experience that the passenger-side outer door mirror glass tilts down when unlocking and opening the driver's door. This is caused by a door-electrical supply unit malfunction due to changes in the vehicle power conditions. To eliminate this concern, the control software of the door-electrical supply unit (passenger's side) has been modified.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify the customer concern.
2. Reprogram the DOOR_ESU_P with the Mazda Modular Diagnostic System (M-MDS), using Mazda Diagnostic And Repair Software (MDARS). **After that, the DOOR_ESU_D is automatically reprogrammed as well. Refer to MDARS DOOR ECU Reprogramming Procedure.**

NOTE:

- If the current calibration file name in the ECU FILENAME screen is the same as shown in the Calibration Files Information or with a later suffix, reprogramming is not necessary.
 - After the reprogramming, pending DTC P2610:00 [PCM] may be stored without the CHECK ENGINE light ON. Since this DTC may turn to a current DTC depending on operations after the reprogramming, clear DTC after all repair work done.
3. Clear any DTCs.
 4. Verify the repair by starting the engine and making sure the CHECK ENGINE light is OFF and no abnormal warning lights are ON.

NOTE: If any DTC should remain after performing a DTC erase, diagnose the DTC according to the instructions on MGSS.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

CALIBRATION

Module	Target Software file	
	Old	New
Door-ESU(P)	KMV6-66-S08-A	KMV6-66-S08-B

WARRANTY INFORMATION**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	64
Damage Code	9W
Part Number Main Cause	5555-67-5M0
Quantity	0
Operation Number / Labor Hours:	XXWFJXFX / 0.5 Hrs.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.