

# **Advanced Technical Information**

Bulletin #: 2331

Part ID: 9063

9

### VTS Remote Services Fail due to False 3G

#### **Vehicles Affected**

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Macan	As of 2019	95B	N/A	N/A
Panamera	As of 2012 up to 2016	970	N/A	N/A
718	As of 2017	982	N/A	N/A

### **Revision History**

Revision	Release Date	Changes
0	November 17, 2023	Original document

#### Condition

The workshop cannot commission the PCC/PVTS control unit using the PIWIS tester. Consequently, the customer will not be able to use VTS remote services. Sometimes VTS remote services that previously worked will stop working.

### **Technical Background**

When commissioning or using VTS, the PCC/PVTS control unit must connect to an active GSM network. Starting in 2022, 3G mobile networks are no longer active, so the ECU must find a 4G network. The issue occurs because the subject vehicle's PCC/PVTS control unit gets confused and looks for a 3G network instead of looking for a 4G network. Because of a bug, it stops looking for other networks and becomes stuck attempting to connect to the disabled 3G network.



## **Advanced Technical Information**

Bulletin #: 2331

Part ID: 9063

9

#### **Service Information**

The workshop must replace the PCC/PVTS control unit to fix this condition. The desired part number is 958.035.620.J. The ECU label should show software version 0924. (See figure 1. This is a 'good' part.)



Figure 1

If you receive this part with a software version lower than 0924, please submit a Parts Claims and Returns PRMS ticket to your Area Parts Support Specialist for further instructions. (See figure 2 for 'bad' part examples.)



Figure 2

#### Search Items

VTS, remote services, vehicle tracking, 3G sunset, Connect

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.