

Technical product information

Topic	Spurious DTC C12D5FA is evident in diagnostic address 00A5
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2072071/1
Level	EH
Status	Approval
Release date	

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
00A5 - Front sensor for drivers assistant systems	C12D5FA: Driver assistance systems control module Image processing processor not reacting		Intermittent
00A5 - Front sensor for drivers assistant systems	C12D5FA: Driver assistance systems control module Image processing processor not reacting		static

New customer code

Object of complaint	Complaint type	Position
vehicle service -> service, maintenance -> general inspection	service: process -> with determination of concern	
vehicle service -> vehicle diagnosis -> guided fault finding	control units, services -> with event log entry	
driver assist systems, convenience features -> image processing system -> image processing camera	component / consumables -> missing	front

Vehicle data

Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2024	E		*	*	*

Documents

Document name
master.xml

Spurious DTC C12D5FA is evident in diagnostic address 00A5

Customer statement / workshop findings

Workshop findings

- DTC C12D5FA (Driver assistance systems control module Image processing processor not reacting) with symptom code 221281 is evident within diagnostic address 00A5 - Front Sensor Driver Assistance System control unit
- The DTC was found during routine vehicle diagnostic interrogation

Technical background

In the event the spurious DTC is evident within diagnostic address 00A5 - Front Sensor Driver Assistance System control unit, the operative must refer to the following advice:

Do Not take any action unless an actual operational fault is present or a concern has been reported by the customer

Hint:

The DTC can be erased using ODIS however the DTC can in some cases return

Note:

Customers will not be aware of the DTC

No warnings will be evident within the DIP

No audible warnings will be evident

The DTC will not cause any system related operational issues

Production change

-

Measure

Refer to the Technical background section