#### **Technical Service Bulletin**



01-23-12 - Late Production - Update Programming Engine-Motor Control Module -J623-

Release date:

**Transaction No:** 

12/11/2023

2072378/1

# **Condition**

Applicable Vehicles						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	
Jetta	2020 – 2021	1.4T (DGXA, DJXA)	All	All	All	

Revision Table					
Instance Number	Published Date	Version Number	Reason for Update		
2072378/1	12/11/23	01-23-12	Original publication.		



# CAUTION

If software updates or flash campaign/actions are performed on a vehicle, a charger with at least 70A charging current MUST be used in order to avoid problems during software updates and flash campaign/actions.

#### **Customer Complaint:**

MIL-on with the following fault code stored in the Engine Control Module (ECM) Fault Memory:

DTC	Description
P242100	EVAP System Vent Valve Stuck Open



DO NOT diagnose or replace components due to the above fault <u>before</u> performing the update function as explained in this bulletin.



# OWNER INFORMATION ABOUT CONTROL MODULE TUNING\* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

*) "TUNING" is described as the addition of or modification of any coll Volkswagen vehicle to perform outside the normal parameters and sp	•
Volkswagen Group of America / Volkswagen Group Canada.	
Date:	
Dealer Number:	
Vehicle Identification Number:	
Repair Order Number:	
	Dealer stamp
I, owner or driver of the above identified	Volkswagen, confirm:
Tuning" as described above (especially power increasing modification performed on my vehicle.	ications) has NOT been
"Tuning" as described above has been performed on my vehicle and were modified or installed:	the following components
TUNING was performed by (Please provide Company name and telepho	ne number, if you wish us
to contact them):	
I understand that if my Control Module is determined to have been tuned the tuning of the Control Module (including adverse emissions conseque by VWGoA / VGC warranties.	
I am permitting an authorized Volkswagen Dealer to reflash (update) my doing so, I understand that this process will automatically overwrite (d delete any tuning program that was previously installed on the Control M vehicle.	lestroy) and permanently
By signing below, I fully acknowledge and understand that the tuning pro and VWGoA / VGC, will not be liable in any way for the loss of tuning da	•
Signature	of Customer

<sup>© 2023</sup> Volkswagen Group of America Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright intellectual gyagetry rights of VGoA Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, effectionic, mechanical, photocopying, recording, or or may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

#### **Technical Service Bulletin**



01-23-12 - Late Production - Update Programming Engine-Motor Control Module -J623-

Release date:

**Transaction No:** 

12/11/2023

2072378/1

# **Technical Background**

Monitoring strategy for FTIV diagnosis is too sensitive, causing erroneous DTCs.

## **Production Solution**

Not applicable – vehicle is out of production.

## **Service**

**Update-Programming Procedure:** 



## CAUTION

The Midtronics battery charger <u>must</u> be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process and should monitor the voltage for the duration of the update. The procedure may cancel itself if the hazard warning lights are not switched ON. The hazard warning lights prevent the system from switching to bus sleep mode during the update. ODIS-Service test should be updated to the latest GFF technical version 11.0.0 or higher and SW version 2.47.0 or higher.



## DANGER

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades. Keep hands and all objects away from Radiator Fan(s) during Update Process!



#### CAUTION

Prior to launching the ODIS Service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Diagnostic Hardware & Windows® - VHW-20-02 Change Power Options After Windows®10 Upgrade. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure. When using a VAS 6150/X or 6160/X tester in conjunction with a VAS 6154 wireless transmitter head for a flash procedure, connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure. VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.



01-23-12 - Late Production - Update Programming Engine-Motor Control Module -J623-

Release date:

**Transaction No:** 

12/11/2023



# NOTICE

To Update-Programming using Software Version Management (SVM), <u>review and follow</u> instructions in <u>Technical Bulletin Instance 2014603</u> "Software Version Management". The SVM process must be completed in its entirety, so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

Update the Engine/Motor Control Module -J623- using the SVM Unit code as listed in the table below:

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code
Jetta	1.4T		7401			
	DGXA		9945	04E 906 024 BB		
		04E 906 024	9970		0074	4D14
		BB	9971		9974	
			9972			
			9973			
			7400			
			9946	04E 906 024 BC	9974	4D14
		04E 906 024 BC	9970			
			9971			
			9972			
			9973			
			Z842			
		04E 906 024	6946	04E 906 024 AB	9974	
			9944			
		AB	9970			4D14
			9971			
			9972			



01-23-12 - Late Production - Update Programming Engine-Motor Control Module -J623-

Release date:

**Transaction No:** 

12/11/2023

	ı		T		
		9973			
		Z943	04E 906 024	2889	
	04E 906 024	Z961			
		0905			4D14
	BG	1057	BG		
		1520			
		2324			
		Z943	04E 906 024 BH	2890	
	04E 906 024 BH	Z961			
		0906			4D14
		1056			
		2048			
		2325			
		Z943			
	04E 906 024 BJ	Z961	04E 906 024 BJ	2891	
		0907			
		1055			4D14
		2049			
		2326			

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.



#### NOTICE

Ensure ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.



01-23-12 - Late Production - Update Programming Engine-Motor Control Module -J623-

Release date:

**Transaction No:** 

12/11/2023

# **Warranty**

Model(s) Year(s		ar(s) Eng. Code(s)		Trans. Code(s)	VIN Range From		VIN Range To	
Jetta	Jetta 2020 – 2021		1.4T ( DGXA)	All	All		All	
			SAGA	Coding				
Claim Type:		Use app	licable Claim Ty	pe <sup>1)</sup>				
Service Number:			Damage Code	нѕт			Damage Location Depends on Service No.)	
2470			0039			<b></b>		
Parts Manufacturer				Jetta 3ME			3ME <sup>2)</sup>	
Labor Operation 3): Charge Battery				27068950 = See Elsa for latest time units				
Labor Operation 3): Update Programming Engine/Motor Control Module -J623-				24705599 = 50 TU max.				
Causal Part:				24705599				
			Diagnos	tic Time 4)		<u>.</u>		
GFF Time expenditure			01500060 = Actual GFF print out				NO	
Road Test		012	01210004 = 10 TU		YES			
Technical Diagnosis			01320000 = 00 TU max.			NO		
Claim Commont	· Input "	As por To	ochnical Bullotin 20	072378" in commer	t coetio	n of \Mo		

1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.

<sup>2)</sup> Code per warranty vendor code policy.

Page 5 of 6 Plus attachment.

#### **Technical Service Bulletin**



01-23-12 - Late Production - Update Programming Engine-Motor Control Module -J623-

Release date:

**Transaction No:** 

12/11/2023

2072378/1

3) Labor Time Units (TUs) are subject to change with ELSA updates.

## **Required Parts and Tools**

Tool Description	Tool No:		
	GRX3000VAS		
Midtronics Battery Tester/Charger	or		
	MTRMSP0702 battery maintainer/charger		
VAC Diagnostia Tool	VAS 6150/X & VAS 6160/X and		
VAS Diagnostic Tool	ODIS Service with current online updates		

## **Additional Information**

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

<sup>&</sup>lt;sup>4)</sup> Documentation required per Warranty Policies and Procedures Manual.