

SIB 65 39 23

SERVICE ACTION: OTA MAP UPDATES DO NOT INSTALL - 120

□ THIS REPAIR IS MOBILE FRIENDLY

MODEL

| E-Series | Model Description | Production Date |
|----------|----------------------------|---|
| 120 | iX Sports Activity Vehicle | From February 15, 2023 to November 23, 2023 |

AFFECTED VEHICLES

- Vehicles which require this campaign to be completed will show it as "Open" when checked either in AIR, AWP, Campaign Summary, or Warranty Vehicle Inquiry.
- Please make sure you check your center's inventory as soon as possible. You can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.
- For centers that qualify, this Service Action repair is eligible to be performed via Mobile Assistance.

SITUATION

If regional navigational maps are downloaded into the vehicle over-the-air ("OTA"), they cannot be installed into the active Navigation.

Note: Maps downloaded via USB stick are not affected.

CAUSE

Unfavorable software in the head unit.

CORRECTION

Program the head unit.

PROCEDURE

Determine what is the vehicle's current I-level by either using AIR, or AWP (Aftersales Workplace) applications.

Based on the vehicle's current I-level, if necessary, program the vehicle to I-level I020-23-11-530 or higher using ISTA 4.45.1x (released Dec. 1, 2023) or higher.

- Connect the battery charger to the vehicle
- Connect the programming system to the vehicle (ISTA 4)
- Determine measures plan
- Accept and fully work through the measures plan with the control units to be programmed/encoded and enabled
- Follow the rework list
- Depending on the rework list, carry out a vehicle test and delete the fault memory if needed

After the programming has been fully completed, check functionality of the system.

<u>Note:</u> ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW-approved battery charger/power supply (SI B04 23 10).

For information on programming and coding with ISTA, refer to Dealer Universal Portal / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

CLAIM INFORMATION

Vehicle Programming and Encoding

Copyright ©2023 BMW of North America, Inc.

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

Select one of these open Technical Campaigns to perform and submit for updating the vehicle to the required I-level or higher when applicable.

Please be sure to also perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any other open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

As determined by the above, reimbursement for this Service Action will be via normal claim entry utilizing the work package information below that applies.

| Repair Code: | 0065460400 | I20 Program control units (head unit) |
|--------------|------------|--|
| | 0003700700 | 120 I Togram control units (neau unit) |

Below are the special flat rate labor operation code choices for this action.

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop

| Work Pkg | Labor Operation | Description (Plus work) | Labor Allowance |
|----------|-----------------|---|-----------------|
| # 1 | 00 75 760 | Programming and encoding the vehicle control units, includes Carrying out vehicle test (00 00 556/61 21 528) | 9 FRU |
| Or: | | | |
| #2 | 00 75 761 | Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair prior to or during this workshop visit (vehicle is already at the specified Target integration level or higher, no repair is necessary) | 1 FRU |

Or:

The vehicle arrives at your center and this Service Action shows open (No other Main work will be performed or claimed during this workshop visit)

| Work Pkg | Labor Operation | Description (Main work) | Labor Allowance |
|----------|-----------------|---|-----------------|
| # 3 | 00 75 200 | Programming and encoding the vehicle control units, includes Carrying out vehicle test (00 00 006/61 21 528) | 11 FRU |
| Or: | | | |
| # 4 | 00 75 201 | Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair prior to or during this workshop visit (vehicle is already at the specified Target integration level or higher, no repair is necessary) | 1 FRU |

Only one of the flat rate labor operation codes listed above can be used for claim submission/reimbursement purposes. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the Copyright ©2023 BMW of North America, Inc.

Vehicle Programming and Encoding – Additional Work (RO and Claim Comments Required)

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Repair Code in this bulletin together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the Repair Code listed in AIR together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

(*) Based on which one applies to your center, please refer to **SI B01 01 20 or B01 07 20** for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

FEEDBACK REGARDING THIS BULLETIN

| Technical Feedback | To submit feedback for the technical topic of this bulletin: Submit your | |
|--------------------|---|--|
| | feedback in the rating box at the top of this bulletin | |
| | To submit feedback for the CLAIMS section of this bulletin: Submit an IDS | |
| Warranty Feedback | ticket to the Warranty Department, or use the chat available in the | |
| | Warranty Documentation Portal | |
| Parts Feedback | To submit feedback for the PARTS section of this bulletin: Submit an IDS | |
| | ticket to the Parts Department | |

12/21/23, 9:15 AM