

## Technical Service Bulletin (TSB) Generic Key Fobs Shipped with Vehicle

<b>REFERENCE:</b>	<b>TSB:</b> 08-041-23 <b>GROUP</b> 08 - Electrical	<b>Date:</b>	February 4, 2023	<b>REVISION:</b>	-
<b>VEHICLES AFFECTED:</b>	<b>2023 (M1) Jeep Compass</b> This bulletin applies to vehicles built on or after September 29, 2022 (MDH 0929XX) and on or before November 19, 2022 (MDH 1119XX) equipped with a 2.0L I4 Turbo Diesel Engine (Sales Code EBT).	<b>MARKET APPLICABILITY:</b> <input type="checkbox"/> NA <span style="float: right;"><input type="checkbox"/> CH</span> <input type="checkbox"/> EE <span style="float: right;"><input type="checkbox"/> IAP</span> <input checked="" type="checkbox"/> SA <span style="float: right;"><input type="checkbox"/> MEA</span>			
<b>CUSTOMER SYMPTOM:</b>	Key FOBs are not specific to vehicle (during the delivery the customer was informed that they will need to return to dealer to change the key FOBs).				
<b>CAUSE:</b>	Incorrect key FOBs.				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 23-032, date of issue February 04, 2023. All applicable Sold RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

### REPAIR SUMMARY:

This bulletin involves replacing and programming both FOBs.

### CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-80-44-96	Replace and Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	ZZ	Service Action	

### SPARE PARTS:

Qty	Part No.	Description	Notes
2	7094815	FOB, Key Blank With Transmitter	Reuse Mechanical Key

### DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RSU VIN list, perform the Repair Procedure. **This RSU only applies to vehicles on the RSU VIN list.**

### SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

**REPAIR PROCEDURE:**

1. Pick up the vehicle key FOB (Fig. 1) .



**Fig. 1**  
**Key FOB Assembly**

- 1 - Mechanical Key (to be reused)
- 2 - Key FOB
- 3 - Mechanical Key Release Button

**NOTE: Do not discard the mechanical key. The mechanical key is to be reused with the new FOBs.**

2. Find the button for removal of the mechanical key on the back of the key FOB (Fig. 1) .
3. Press the button and remove the mechanical key completely from the key FOB (Fig. 1) . Discard key FOB.
4. Pick up a **new** key FOB and insert the mechanical key (Fig. 1) .
5. Repeat for the other new key FOB.
6. Perform the programming procedure on the two new key FOBs. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info> 08 Electrical / 8E Electronic Control Modules / Module, Radio Frequency (RF Hub) / Module Programming> Key Fob Programming.

**POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*