# Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:

DRIVER'S SIDE OUTER MIRROR GLASS VIBRATES WHEN DRIVING AT HIGH SPEED ON BUMPY ROAD Bulletin No.: 09-046/23

Last Issued : 12/19/2023

## BULLETIN NOTES APPLICABLE MODEL(S)/VINS

2024 CX-90 (produced before Septemeber 6, 2023)

### DESCRIPTION

Some customers may complain that the driver's side outer mirror glass vibrates when driving at high speeds at approximately 60 mph (100 km/hour) or more on bumpy roads such as road joints, coarse-grained paved roads or rough roads. This is caused by insufficient hardness of the adhesive tape between the outer mirror glass holder and the mirror glass. To eliminate this concern, the material of the adhesive tape between the outer mirror glass holder and the mirror glass has been improved and the tape location has been modified.

Customers having this concern should have their vehicle repaired using the following repair procedure.

#### REPAIR PROCEDURE

1. Verify the customer concern.

2. Replace the driver's side outer mirror glass with a modified one according to the instructions in MGSS (OUTER MIRROR GLASS REMOVAL/INSTALLATION).


#### NOTE for INSTALLATION:

- Refer to the procedure below and perform the installation in the correct order when installing the outer mirror glass.
- Images in the instructions show left side (same as right side).


**ATTENTION:** DO NOT press the mirror glass too hard during installation to avoid damaging the auto-dimming liquid crystal inside the glass.

Page 1 of 4

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing. a. Install the new pivot plate (1) to the outer mirror base.



b. Peel off the release papers on the new mirror glass holder.




Page 2 of 4

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


© 2023 Mazda North American Operations, U.S.A.

Bulletin No.: 09-046/23	Last Issued : 12/19/2023
-------------------------	--------------------------

c. Hook the tabs (1) of the outer mirror holder to the pivot plate (2) shown in the following image.



d. Hook the claws (1) of the the outer mirror holder to the pivot plate (2) shown in the following image.



3. Verify the repair.

Page 3 of 4

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

© 2023 Mazda North American Operations, U.S.A.

#### PARTS INFORMATION

Part Number	Description	Q'ty	Notes
KEY0-69-1GY	Glass & Holder (L), Mirror	1	with heater and BSM

NOTE: Use VIN to check the old part number in EPC.

#### WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A	
Symptom Code	83	
Damage Code	97	
Part Number Main Cause	****-69-1G7 or ****-69-1GY	
Quantity	1	
Operation Number / Labor Hours:	XXWJ6ARX / 0.2 Hrs (PHEV) XXWJ6DRX / 0.3 Hrs (MHEV H3T)	

Page 4 of 4

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

© 2023 Mazda North American Operations, U.S.A.