

| | | | | | |
|---------------------------|--|--------------|--------------------|--|------------------|
| REFERENCE: | TSB: 18-100-23 GROUP: 18 - Vehicle Performance | Date: | September 16, 2023 | REVISION: | 18-057-19 REV. B |
| VEHICLES AFFECTED: | 2019 (WK) Jeep Grand Cherokee This bulletin applies vehicles equipped with the 3.6L V6 24V VVT Engine UPG I W/ ESS (Sales Code ERC). | | | MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input checked="" type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input checked="" type="checkbox"/> IAP <input checked="" type="checkbox"/> EE <input type="checkbox"/> CH | |
| CUSTOMER SYMPTOM: | Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find one or more of the following Diagnostic Trouble Codes (DTCs) has been set: <ul style="list-style-type: none"> • **P0441 - EVAP Purge System Performance (for North America and Mexico markets only).** • P0456 - EVAP System Small Leak. NOTE: ** If DTC P0456 is present, use the wiTECH Small Leak Verification Test (SLVT) to determine if a leak is present in the system. ** | | | | |
| CAUSE: | PCM Software | | | | |

This bulletin supersedes Technical Service Bulletin (TSB) 18-057-19 REV. B, date of issue July 12, 2019, which should be removed from your files. All revisions are highlighted with ****asterisks**** which include an additional DTC and a note.

REPAIR SUMMARY:

This bulletin involves reprogramming the PCM with the latest available software.

CLAIMS DATA:

| Labor Operation No: | Labor Description | Skill Category | Labor Time |
|---------------------|---|-----------------------------------|------------|
| **18-19-06-HD | Module, Powertrain Control (PCM) - Reprogram (0 - Introduction) | 1 - Engine Repair and Performance | 0.3 Hrs.** |
| Failure Code | CC | Customer Concern | |

SPECIAL TOOLS/EQUIPMENT:

| Description | Ref. No. | Notes |
|----------------------|----------|-------|
| wiTECH or Equivalent | - | - |

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above or if the technician finds the DTC, perform the Repair Procedure.

REPAIR PROCEDURE:

Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process. If this flash process is interrupted/ aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.