STELLANTIS **Technical Service Bulletin (TSB)** Pitch and Roll are not Displayed on SRT Performance Pages PARTS & SERVICES November 22, 2023 **REVISION:** REFERENCE: **TSB:** 08-251-23 Date: **GROUP:** 08 - Electrical **VEHICLES** 2021 - 2023 (WD) Dodge Durango **MARKET APPLICABILITY:** This bulletin applies to vehicles built on or before December 12, 2022 AFFECTED: \boxtimes NA \times MEA (MDH 1212XX) equipped with SRT Performance Pages (Sales Code \times SA IAP JAV). ☐ EE CH **CUSTOMER Customers may experience: SYMPTOM:** Pitch and Roll are not displayed in the SRT Performance Pages Fig. 1.



Fig. 1
Pitch And Roll SRT Peformance Pages Screen

REPAIR SUMMARY:

CAUSE:

This bulletin involves using wiTECH to perform a Restore Vehicle Configuration.

Restore vehicle configuration needed.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-02-HZ	Module, Body Control (BCM) - Restore Vehicle Configuration (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

- 1. Using wiTECH, go to "Guided Diagnostics".
- 2. Pefrom a "Restore Vehicle Configuration". Follow all screen prompts.
- 3. Clear any DTCs that may have been set.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.