

Bulletin No.: PIT6096 Published date: 12/5/2023

Preliminary Information

PIT6096 110 / 120 Volt Power Outlet Inoperative

<u>Models</u>

| Brand: | Model: | | Model Years: | VIN: | | Engino | Transmissions: |
|----------------------------|------------------------|---|--------------|------|-----|---------|----------------|
| Di allu. | | | | from | to | Engine: | Transmissions. |
| Chevrolet | Silverado 2500/3500 HD | | 2020 - 2023 | All | All | All | All |
| GMC | Sierra 2500/3500 HD | | 2020 - 2023 | All | All | All | All |
| Involved Region or Country | | North America | | | | | |
| Additional Options (RPO) | | RPO KI4 120 Volt Power Outlet | | | | | |
| Condition | | Some customers may comment that the 110 /120 volt accessory power outlet(s) are inoperative. | | | | | |
| | | Please note that there is an in cab power outlet switch that MUST be turned on for the 110 /120 volt power outlet(s) to function. | | | | | |
| Cause | | The cause of this concern could be a low voltage condition. | | | | | |

Correction:

If normal SI diagnostics does not correct the condition, then disconnect the battery(ies) for several minutes and reconnect. Start the vehicle and turn on the in cab 110 / 120 volt power outlet switch. Then connect a suitable device to the 110 /120 volt power outlet and check to see if it now operates. If the power outlet now operates, then the cause is likely because the BCM determined there was a low battery condition and locked out the 110 /120 volt power outlet(s). Inspect the vehicle for any type of condition that could cause a low voltage concern like:

- Parasitic draw on the battery that may or may not cause a dead battery/no crank concern.
- Poor battery cable or main fuse block connections.
- A battery issue.
- Aftermarket equipment.

Repair any issues found.

Note: In some rare cases, if no issues are found and even if the battery passed the GR8/DCBS testing, the cause still could be a battery issue and may need to be replaced.

Warranty Information

For vehicles repaired under warranty use the appropriate labor operation code for the issue found.

Version History

| Version | 1 | |
|----------|--------------------------|--|
| Modified | 12/05/2023 - Created on. | |



© 2024 General Motors. All Rights Reserved.