



# Technical Service Bulletin

---

## 01 PSS Engine control unit drive system faults P060C00, and U041600

01 24 06 2072710/1 January 12, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, and A5 Sportback	2021 – 2024	All	DMSA Engine Code
Q5	2022 – 2024		

## Condition

This bulletin applies to MY22-24 A4, A5, Q5 vehicles only.

### Customer states:

- The EPC lamp lights up.
- “Drive system fault” appears in the instrument cluster.

### Workshop findings:

The following DTC are stored in the Engine Control Unit:

- “P060C00 – Internal Control Module Main Processor with Symptom Code DFCC 44160”
- “U041600 – Invalid Data Received From Vehicle Dynamics Control Module with Symptom Code DFCC 34193”

## Technical Background

Software issues within the Engine Control Unit.

## Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

## Service

1. Diagnose the vehicle according to the instructions listed below. If the customer’s vehicle condition matches the condition listed in the *Technical Background* of this PSS TSB, explain to the customer that a solution is expected to be available by the end of the 2nd quarter of 2024 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer’s concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).



# Technical Service Bulletin

---

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2072710**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.