

Oil Leakage on Cylinder Head Cover: Insert Micro-Self-Locking Screw (166/21)

Revision: This bulletin replaces bulletin Group 1 166/21, dated December 10, 2021.

Model Year: **As of 2019 up to 2023**

Model Lines: **Cayenne (9YA / 9YB)**

Equipment: **8-cylinder Otto engine (engine type: CVD)**

Concerns: **Oil leakage around the cylinder head cover**

Cause: The customer complains about an oil leakage in the engine compartment. "Oil sweating" or drops of oil forming in the cylinder head cover area is detected in the workshop.




Information

The measure described here relates to a potential oil leakage at the screws shown on the cylinder head cover. If the oil leak occurs at another location, the oil leakage must be found and remedied. This Technical Information (TI) does not apply in this case.




Example of an oil leakage

Action required: Clean the affected area thoroughly and replace the affected screws and adjacent screws with micro-self-locking screws.



Overview of potentially affected screw points, bank 1



Overview of potentially affected screw points, bank 2



Information

To clearly identify an oil leakage and avoid unnecessary repairs, always proceed as follows:

- Document the original complaint condition with meaningful photos
- Attach documentation to PCSS line.
- Clean the engine thoroughly
- Where applicable, spray large areas of the engine with leak search spray (“SpotCheck”) around the suspected leakage points
- Perform a test drive
- Check the engine for leaks and find the leak
- Produce photo documentation of the leakage point located
- Attach documentation to PCSS line.



Information

Definition and procedure for oil leakages:

- Oil sweating: Oil is visible; however, the amount of oil emerging is does not form drops of oil. There are no traces of oil on adjacent components. No further action is required in this case.
- Drops of oil: A significant amount of oil is clearly visible; the emerging oil forms drops of oil. There are also traces of oil on adjacent components. In this case, the oil leakage must be located and remedied.

Parts required if necessary



Information

The number of screws required depends on the respective leakage point on the cylinder head cover.

Parts Info:

Required parts:

Screw No.	Part No.	Designation – Location	Number
1	N 10451409	⇒ Internal hexagon round countersunk screw, self-locking, M6 x 16 – Cylinder head	As required
		or	
2	N 10599501	⇒ Countersunk screw M5 x 20 – Cylinder head	As required

		or	
3	PAF101243	⇒ Internal hexagon round oval-head screw – Cylinder head	As required

Preparatory work


Work Procedure: 1 Remove fuel collection pipe.
For instructions, see:
⇒ *Workshop Manual '243019 Removing and installing fuel collection pipe (V8 Turbo)'*

Replace affected and adjacent screws



Information

The surrounding screws around the leakage must in principle also be replaced with microencapsulated screws analogous to the example shown in the graphic
⇒ *Example of "adjacent screws"*.



Example of "adjacent screws"

- Work Procedure: 1 Unscrew the affected and adjacent screws.
- 2 Clean the affected area thoroughly.
 - 3 Blow out bores using compressed air.
 - 4 Screw in and tighten new micro-self-locking screws at the relevant position.
Check the following while doing this:
 - Screws for fuel collection pipe (item 1) **Initial tightening 7 Nm (5.2 ftlb.) Final tightening 10 Nm (7.4 ftlb.)** Also observe screw sequence. For instructions, see: ⇒ *Workshop Manual '243019 Removing and installing fuel collection pipe (V8 biturbo)'*
 - Screw for solenoid hydraulic valve VHS (item 2) **Tightening torque 5 Nm (3.7 ftlb.)**
 - Screws for pressure converter holder (item 3) **Tightening torque 10 Nm (7.4 ftlb.)**

Follow-up actions

Work Procedure: 1 Install fuel collection pipe.
For instructions, see:
⇒ *Workshop Manual '243019 Removing and installing fuel collection pipe (V8 Turbo)'*

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
15824931	Subsequent work on cylinder head	
15824932	Subsequent work on cylinder head	

PCSS encryption:

Location (FES5)	15820	Cylinder head cover
Damage type (SA4)	5043	Oil loss

References: ⇒ *Workshop Manual '243019 Removing and installing fuel collection pipe (V8 Turbo)'*

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2024 Porsche Cars North America, Inc.