



GROUP	MODEL
ELE	2023MY Sportage (NQ5, NQ5a) w/Theta III 2.5L GDI
NUMBER	DATE
319	February 2024

## TECHNICAL SERVICE BULLETIN

### 2.5L GDI THETA III ECU SOFTWARE UPGRADE FOR ISG OPERATION LOGIC

SUBJECT:

This bulletin provides information to upgrade the Engine Control Unit (ECU) software on some 2023MY Sportage (NQ5) vehicles equipped with a Theta III 2.5L GDI engine, produced from December 15, 2021 through July 17, 2023 and Sportage (NQ5a) vehicles equipped with Theta III 2.5L GDI engine, produced from January 12, 2022 through July 10, 2023, due to the possibility of an intermittent restart failure in rare circumstances with Idle Stop Go (ISG) enabled. The existing logic may prevent the vehicle from restarting automatically within a short time period (0.2 second) after entering "auto stop" mode and under certain engine and ambient conditions. However, if this occurs, the engine can be restarted by the driver after placing the gear shift selector to Park (P) or Neutral (N) and pressing the ENGINE START/STOP button. Follow the procedure outlined in this publication to upgrade the 'ENGINE' system software and improve the ISG logic to correct this concern on the applicable vehicle.



#### NOTICE

**A Technical Service Bulletin is a field fix repair program without customer notification that may be performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.**

A printed copy is for reference only; publication information can be updated at any time. Always refer to KGIS for the latest information. After logging in kdealer.com, the newest technical publications are listed in 'Service Releases' and has the latest service information that has been released.

**ECU Upgrade Procedure:**

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in this bulletin.

**Upgrade Event Name**

702. NQ5/NQ5A Theta 2.5GDI ISG Operation Logic Improvement

**NOTICE**

- Confirm a fully charged battery (12.3 volts or higher is necessary) is used or utilize a fully charged jump starter box connected to the battery.
- **Ensure the KDS GDS is sufficiently charged at 60% or higher prior to reflash.**
- All ECU upgrades must be performed with the ignition set to the 'ON' position unless otherwise stated.
- **Damaged VCI II units should not be used and promptly replaced.**
- Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.
- **DO NOT start the engine during ECU upgrade.**
- DO NOT turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- **When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.**
- ONLY use approved ECU upgrade software designated for the correct application.


**IMPORTANT**

It is recommended to ALWAYS check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. DO NOT reference the parts label affixed to the ECU.

SUBJECT:

## 2.5L GDI THETA III ECU ISG SW LOGIC IMPROVEMENT

**NOTICE**

Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer  security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.

**ROM ID INFORMATION TABLE:****Upgrade Event #702**

Model	System	Smart Key	ECU P/No.	ROM ID	
				Previous	New
NQ5 (FWD)	ECM	Yes	39100 2S210	NQDWD5GMAXXXL7A NQEWD5GMAXXXL7A NQEWD5GMAXXXL7B NQEWD5GMAXXXM1A	NQEWD5GMAXXXM1B
		No	39100 2S215	NQDWD5GKAXXXL7A NQEWD5GKAXXXL7A NQEWD5GKAXXXL7B NQEWD5GKAXXXM1A	NQEWD5GKAXXXM1B
Yes		39100 2S232	NQDWD5GMJXXXXL7A NQEWD5GMJXXXXL7A NQEWD5GMJXXXXL7B NQEWD5GMJXXXXM1A	NQEWD5GMJXXXXM1B	
No		39100 2S233	NQDWD5GKJXXXXL7A NQEWD5GKJXXXXL7A NQEWD5GKJXXXXL7B NQEWD5GKJXXXXM1A	NQEWD5GKJXXXXM1B	
NQ5a (FWD)	ECM	Yes	39100 2S226	NQEWN5GMAXXXL7A NQEWN5GMAXXXL7B NQEWN5GMAXXXM1A	NQEWN5GMAXXXM1B
		No	39100 2S231	NQEWN5GKAXXXL7A NQEWN5GKAXXXL7B NQEWN5GKAXXXM1A	NQEWN5GKAXXXM1B
Yes		39100 2S234	NQEWN5GMJXXXXL7A NQEWN5GMJXXXXL7B NQEWN5GMJXXXXM1A	NQEWN5GMJXXXXM1B	
No		39100 2S235	NQEWN5GKJXXXXL7A NQEWN5GKJXXXXL7B NQEWN5GKJXXXXM1A	NQEWN5GKJXXXXM1B	
NQ5a (AWD)					

*To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.*



**NOTICE**

**Prior to performing the ECU upgrade, be sure to check that the KDS is fully charged.**

1. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.

**NOTICE**


The ECU upgrade function on KDS operates wirelessly. It is not necessary to perform the upgrade via USB cable.



2. With the ignition ON, turn ON the KDS tablet. Select 'KDS' from the home screen.



3. Confirm communication with VCI (A) and then configure the vehicle (B) using the 'AUTO VIN' (C) feature.



4. Select 'ECU Upgrade'.



SUBJECT:

## 2.5L GDI THETA III ECU ISG SW LOGIC IMPROVEMENT

- The KDS will check the server for recently uploaded Events and then automatically download Upgrade Event #702. NQ5/NQ5A Theta 2.5GDI ISG Operation Logic Improvement.

### NOTICE

The vehicle must be identified in Vehicle Selection to download an Event for that vehicle.

After the download is complete, the program will shut down to install. Please wait until the program restarts.

Event	Status
271.QF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT	Downloading
273.TF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT	Ready

36%


Do not touch any system buttons while performing this function.

KDS screenshot shown above is for demonstration purposes only. Events shown in screenshot are not applicable to this bulletin.

- Select Auto Mode.

### CAUTION

Do NOT attempt to perform a Manual Mode upgrade UNLESS Auto Mode fails. Always follow the instructions given on the KDS in either Auto or Manual mode.



- Select 'ENGINE' system and applicable 'Event Group' (D) for the vehicle:

Event #702. NQ5/NQ5A Theta 2.5GDI ISG Operation Logic Improvement

ECU Upgrade

SPORTAGE(NQ5) > 2023 > G 2.5 GDI THETA III

System

ENGINE

Event Group

702.NQ5/NQ5A Theta 2.5GDI ISG operation logic improvement

NQ5 2.5GDI ULEV70 2/4WD : 39110-2S210

NQ5 2.5GDI ULEV70 2/4WD : 39110-2S215

TSB

- The ECU upgrade will begin, and the progress of the upgrade will appear on the bar graph. Upgrade part (1/2) (E) will download the upgrade event to the VCI-II. Upgrade part (2/2) (F) will upgrade the ECU.

### CAUTION

Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing ECU Upgrade.

**E**

23%

ECU Upgrading...(1/2)

ECU is in the process of being upgraded. Please wait a few minute.

**F**

6%


ECU Upgrading...(2/2)

ECU is in the process of being upgraded. Please wait a few minute.


- If a "Communication Fail" screen appears, verify that the VCI-II and KDS are communicating properly. Select 'OK' and restart the from step 4.

**NOTICE**


**If an error notice continues to appear or if the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.**




- When instructed on the KDS, turn the ignition OFF for ten (10) seconds then back on. Select 'OK' to continue.



- Once the upgrade is complete, select 'OK' to finalize the procedure.



- When prompted, select 'YES' to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.



- Start the engine to confirm normal operation of the vehicle.

## Manual Upgrade Procedure:

 NOTICE

The manual upgrade should ONLY be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition 'OFF' for about 10 seconds then place it back in the 'ON' position to reset the control unit BEFORE performing manual upgrade.

See table below for 'Manual Mode' passwords.

## Manual Mode ECU Upgrade Passwords

Menu	Password
NQ5 2.5GDI ULEV70 2/4WD: 39110-2S210	5751
NQ5 2.5GDI ULEV70 2/4WD: 39110-2S215	5751
NQ5 2.5GDI ULEV70 4WD: 39110-2S232	5753
NQ5 2.5GDI ULEV70 4WD: 39110-2S233	5754
NQ5a 2.5GDI ULEV70 2/4WD: 39110-2S226	5755
NQ5a 2.5GDI ULEV70 2/4WD: 39110-2S231	5756
NQ5a 2.5GDI ULEV70 4WD: 39110-2S234	5757

1. Within the ECU Upgrade screen displayed, select **Manual Mode**.
2. Select the '**ENGINE**' system under the System selection menu. Select **Upgrade Event #702** and select **Upgrade** to continue.
3. Select the appropriate control unit part number with reference to the ROM ID Information Table on page 3, and select **OK**.
4. Enter the appropriate password from the Manual Mode password table above and select **OK**.
5. The upgrade will begin and the progress of the upgrade will appear on the bar graph.
6. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Select **OK**.
7. Once the upgrade is complete, select **OK** to finalize the procedure.
8. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.
9. Start the engine to confirm proper operation of the vehicle.

SUBJECT:

**2.5L GDI THETA III ECU ISG SW LOGIC IMPROVEMENT****AFFECTED VEHICLE RANGE:**

Model	Production Date Range
Sportage (NQ5)	December 15, 2021 to July 17, 2023
Sportage (NQ5a)	January 12, 2022 to July 10, 2023

**REQUIRED TOOL:**

Tool Name	Figure	Comments
KDS		Kia Diagnostic System

**WARRANTY INFORMATION:****N Code: D94 C Code: ZZ3**

Model	Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
NQ5 NQ5a	W	39100 2S210	0	Theta 2.5L GDI ISG Operation Logic Improvement	39100F01	0.3 M/H	N/A	0