



Preliminary Information

PIT6113 Updates Failing On K73 Telematics Control Module Via SPS Programming

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
BrightDrop	Zevo 600	2023 - 2024	All	All	All	All
BrightDrop	Zevo 400	2024	All	All	All	All
Cadillac	LYRIQ	2023 - 2024	All	All	All	All
Chevrolet	Colorado	2023	All	All	All	All
Chevrolet	Blazer EV	2024	All	All	All	All
Chevrolet	Silverado EV	2024	All	All	All	All
GMC	Canyon	2023	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UE1
Condition	Technicians may comment that they cannot update the K73 Telematics Control Module via SPS programming. The update will fail in approximately 12 minutes.
Cause	This is caused by trying to update the K73 Telematics module with the same update that it currently has installed.

Correction:

Do not replace any components.

If you experience this concern while programming the K73 Telematics Control Module, then the module is up to date and no further action is required.

Note: If you experience this issue while following the latest version of [PIT6065](#), the software is up to date and you can move on to the next module on the list to program.

Version History

Version	1
Modified	01/18/2024 - Created on.



