



GROUP	MODEL
GEN	2023-2024MY Forte (BDm)
NUMBER	DATE
099	February 2024

TECHNICAL SERVICE BULLETIN

SUBJECT:

SERVICE ACTION: TIRE MOBILITY KIT INSPECTION & REPLACEMENT/REPAIR (SA556)

This bulletin provides information to inspect, and if necessary, replace the Tire Mobility Kit (TMK) sealant can or sealant can cap on certain 2023-2024MY Forte (BDm) vehicles produced from March 01, 2023 through November 30, 2023 that are currently registered in the state of AK, CO, IA, ID, IL, IN, KS, ME, MI, MN, MO, MT, ND, NE, NH, NY, OH, SD, UT, VT, WA, WI, and WY. Lower ambient temperatures can create a vacuum effect inside the TMK sealant can, causing the sealant can cap to open, resulting in the tire sealant leaking. Follow the procedure outlined in this publication to inspect, and if necessary, replace the sealant can or sealant can cap on the applicable vehicle. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.



NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on KDealer+ (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on KDealer+ (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.


This issue number is SA556.

Inspection Procedure:

1. Open the trunk lid.
2. Remove the luggage board (A).




3. Remove the Tire Mobility Kit (TMK) sealant can (B).



- If sealant has not leaked from the TMK can (B) (OK), proceed to step 4.



- If sealant has leaked from the TMK sealant can (NG), replace the sealant can (B), take one (1) clear KVID photo and proceed to 'Repair Procedure' step 5.



Claim labor op 230M11R2

ⓘ IMPORTANT

If leaked sealant has penetrated the inflator bag, test the inflator (C) for proper operation. If inflator and/or other damaged parts require replacement due to leaked sealant, follow normal warranty procedures and attach a KVID photo of the damaged component to the warranty claim.




SUBJECT:

TIRE MOBILITY KIT INSPECTION & REPLACEMENT/REPAIR (SA556)

4. Remove sealant can (B) from the bag and position horizontally so the spout is facing downward.

- If sealant has **not** leaked from the sealant can cap (D) (**OK**), proceed to the 'Repair Procedure'.
- If sealant has leaked from the sealant can cap (D) (**NG**), replace the sealant can (B), **take one (1) clear KVID photo** and proceed to 'Repair Procedure' step 5.



Claim labor op 230M11R2

Repair Procedure:

1. Remove the sealant can (A) from the bag.
2. Twist the sealant can cap (B) counterclockwise to remove from the sealant can (A).




Note: Discard old sealant can cap (B).

3. Install the new sealant can cap (B) provided in the repair kit (PN 52932 M7000QK).

4. Insert the sealant can (A) and leaflet (C) in the new provided bag (D).

5. Insert the sealant can ensuring the **yellow** cap (E) is facing upright and take one (1) clear KVID photo.

6. Reinstall all removed parts in reverse order of removal.





SUBJECT: TIRE MOBILITY KIT INSPECTION & REPLACEMENT/REPAIR (SA556)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
Forte (BDm)	March 01, 2023 to November 30, 2023

REQUIRED PART:

Part Name	Part Number	Figure	Qty.
Sealant Can	52932 AA300QQK		1
Repair Kit	52932 M7000QQK		1

Note: The replacement part numbers will require a VIN entry for parts ordering. DO NOT order these parts for stocking purposes, related to this Service Action. Supply is very limited. Until supply stabilizes, please confirm part availability before scheduling customers. Please be sure to expedite warranty claim filing.

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	52933 AA120	0	(SA556A) TMK Inspection + Repair	230M11R1	0.3 M/H	52932 M7000QQK	1
			(SA556A) TMK Inspection + Replacement	230M11R2	0.2 M/H	52932 AA300QQK	1
V	N/A	0	(SA556B) TMK Inspection + Repair	TBD	TBD	TBD	0
			(SA556B) TMK Inspection + Replacement	TBD	TBD	TBD	0

Note: A total of up to two (2) KVID photos are required for claim submission.

*A KVID photo of the leaking sealant can is required to claim Labor Op 230M11R2.

**A KVID photo showing the installation of the sealant can ensuring the yellow cap (E) faces upright is required for ALL Labor Op's. Failure to provide the required KVID photos will result in claim rejection or chargeback. Use sublet code 'X1' with a maximum allowed amount of \$30.00 per vehicle to clean leaked sealant from the trunk area.

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA556 when accessing the KDealer+ system.

