

51 Water sloshing sound is heard while driving

51 24 28 2061754/4 February 15, 2024. Supersedes Technical Service Bulletin Group 51 number 22-23 dated January 7, 2022 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
A5 Sportback, and S5 Sportback	2017 – 2023	All	Not Applicable	
RS 5 Sportback	2019 2021 – 2023			

Condition

REVISION HISTORY				
Revision	Date	Purpose		
4	-	Revised header (Added Model Year) Revised <i>Warranty</i> (Corrected SRT)		
3	01/07/2022	Revised header (Added Models and Model Years)		
2	04/20/2021	Revised header (Added Models)		

Customer states:

- They hear a sound like water 'sloshing' when the vehicle is driving, cornering, or braking.
- The origin of the noise is described as coming from the floor area.

Workshop findings:

Water is found to have accumulated in the cavities contained in the side sills.

Technical Background

It is possible over time for water to accumulate in the side members and sills but the water is not able to drain as needed. The accumulated water is unable to reach the normal drainage because the sill cavity sound absorber blocks its flow. This accumulated water creates a 'sloshing' noise when the vehicle moves.

Production Solution

Improvements to the body structure components have been implemented in production to prevent water accumulation and allow for normal drainage.



Service

 Detach the underbody trim until the plugs for the side member are accessible. If water has already accumulated in the sill areas water will flow from these plug openings (Figure 1).



Figure 1. Access to the side member plugs.

2. Figure 2 shows the opening where water generally enters this space.




Figure 2. Water entrance point.

3. Fastener position number 4 shown in Figure 3 is the opening through which a modification to the sound absorber will be made.



Figure 3. Sill trim fastener openings.



4. Figure 4 shows the location of the sound absorber marked 'A'.




Figure 4. Location of the sound absorber.

5. Figure 5 shows a closer view of the sound absorber to be modified in the cut-away image.




Figure 5. Hole through which the sound absorber will be accessed.



6. Figure 6 shows a cut-away view of the sound absorber from the rear.



Figure 6. Side member cavity sound absorber.

Figure 7 shows a drawing of the sound absorber. The blue dot marked 'D' corresponds with a point through which a hole 8mm – 10mm in diameter will be made.
 This hole will allow for a normal flow of any accumulated water to reach the normal drainage and exit the sill cavity. The method for creation of this hole follows.




Figure 7. 8mm – 10mm hole to be made through the sound absorber.



8. From a steel rod 8mm – 10mm in diameter fabricate a tool as shown in figure 8. Bend the end of it in an 'L' shape 50mm long.

Heat the bent end of the rod to approximately 500 $^{\circ}$ C (~932 $^{\circ}$ F).




Figure 8. Heating the fabricated tool.

9. Guide the heated rod into opening number 4 from Figure 3 and melt a hole in the sound absorber in position 'D' from figure 7 (Figure 9).



Figure 9. Making the hole in the sound absorber.

10. Figure 10 shows a drawing of the operation performed and the correct positioning.




Figure 10. Correct positioning of the heated rod.



11. Apply cavity preservative or anti corrosion wax to the area in the cavity having been modified. Use a sprayer VAG 1379, VAG 1538 or equivalent generic sprayer to carry out this operation.

Ensure that the drain function of the draining plugs on the front and rear of the side members are fully functional and not damaged (Figure 11).



Figure 11. Drain plug on rear of the side member.

12. Figure 12 shows the drain plug on the front of the side member.



Figure 12. Drain plug on the front of the side member.

13. Reassemble the underbody and sill trim.

Warranty

Claim Type:	 110 up to 48 Months/50,000 Miles. If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.
Service Number:	5145

Page 6 of 9



Damage Code:	0050		
Labor Operations:	Loosen and refasten underbody trim and modify right and left sound absorbers	5145 5099	100 TU
	Body seal coat cavity	5101 7501	See SRT with associated operations
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2061754/4		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

The part numbers mentioned in this TSB are different than the ones listed in ETKA. Only use parts listed in this TSB, this includes superseding part numbers!				
Part Number	Part Description	Quantity		
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA		
D 330KD2A1 Or alternatively: D 321M16M2	Montraum- Conservierungsmen South de protection Corps Creus And	0.3		
	Cavity Preservative			





Anti-Corrosion Wax

Tool Number VAG 1379 or equivalent generic sprayer Spray Gun



VAG 1538

(Or alternative generic sprayer)



Suction Feed Spray Gun

Additional Information

All parts and service references provided in this TSB (2061754) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.