



SIB 66 03 24

2024-02-22

DELIVERY STOP: REMOTE CONTROL PARKING

This Service Information Bulletin (Revision 1) replaces SI B66 03 24 **dated February, 2024.**

What's New:

- Model- production date range updated
- Cause, Correction, Procedure, Claim information added

<input type="checkbox"/>	THIS REPAIR IS MOBILE FRIENDLY
--------------------------	--------------------------------

MODEL

E-Series	Model Description	Production Date
F95	X5 M Sports Activity Vehicle	February 2, 2024 – February 15, 2024
F96	X6 M Sports Activity Coupe	February 7, 2024 – February 14, 2024
G05	X5 Sports Activity Vehicle	January 28, 2024 – February 17, 2024
G06	X6 Sports Activity Coupe	February 1, 2024 – February 16, 2024
G07	X7 Sports Activity Vehicle	January 26, 2024 – February 17, 2024
G70	7 Series Sedan & i7 Sedan	January 12, 2024 – February 21, 2024

AFFECTED VEHICLES

Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.

Please make sure you check your dealer inventory as soon as possible. As of February 16, 2024, you can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

SITUATION

BMW AG has issued a Delivery Stop (effective February 15, 2024) on certain Model Year 2024 BMW vehicles that were produced between January 12, 2024, and February 12, 2024.

Do not deliver to a customer, a New, Certified Pre-Owned or Used vehicle subject to a Delivery Stop, until the vehicle is repaired. Do not use or sell replacement equipment/parts subject to a Delivery Stop.

CAUSE

A quality check showed that the Remote-Control Parking token was not activated in the current software for the vehicles affected.

CORRECTION

Program and code the BCP (Basic Central Platform) with ISTA 4.46.1x or higher.

PROCEDURE

Determine what is the vehicle's current I-level by either using AIR or the AWP applications, and when applicable:

Program the vehicle using **ISTA 4.46.1x** or higher (released late February, 2024, pending verification).

Model	Target Integration level
F95, F96, G05, G06, G07	S18A-24-03-525 or higher
G70	G070-24-03-525 or higher

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW-approved battery charger/power supply (SI B04 23 10) when performing programming.

For information on programming and coding with ISTA, refer to DealerSpeed / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

CLAIM INFORMATION

Vehicle Programming and Encoding

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

Select one of these open Technical Campaigns to perform and submit for updating the vehicle to the required I-level or higher.

Please be sure to also perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any other open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

As determined by the above, reimbursement for this Service Action will be via normal claim entry utilizing the work package information below that applies.

Repair Code:	0061380800	---
---------------------	-------------------	-----

Below are the special flat rate labor operation code choices for this action.

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop.

Work Pkg	Labor Operation	Description (Plusposition work)	Labor Allowance
# 1	00 75 882	BCP remote parking - Programming and encoding the vehicle control units, includes Carrying out vehicle test (00 00 556/61 21 528)	8 FRUs
Or:			
# 2	00 75 883	Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair prior to, or during this workshop visit (vehicle is already at the specified Target integration level or higher, no repair is necessary)	1 FRU

Or:

The vehicle arrives at your center and this Action shows open (No other Main work will be performed or claimed during this workshop visit).

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 3	00 75 292	BCP remote parking - Programming and encoding the vehicle control units, includes Carrying out vehicle test (00 00 006/61 21 528)	9 FRU (G70) 10 FRU (All others)
Or:			

Copyright ©2024 BMW of North America, Inc.

# 4	00 75 293	Programming and encoding the vehicle control units was performed in conjunction with another campaign/repair prior to, or during this workshop visit (vehicle is already at the specified Target integration level or higher, no repair is necessary)	1 FRU
-----	-----------	--	-------

Only one of the flat rate labor operation codes listed above can be used for claim submission/reimbursement purposes. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B66 03 24 WP 1), unless otherwise required by State law.

Vehicle Programming and Encoding – Additional Work (RO and Claim Comments Required)

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Repair Code in this bulletin together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the Repair Code listed in AIR together with the corresponding labor operation codes and their flat rate unit (FRU) allowance(s), including the diagnosis* that applies.

(* Based on which one applies to your center, please refer to **SI B01 01 20** or **B01 07 20** for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topics of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

