



GROUP	MODEL
FUE	2022-2023MY Carnival (KA4)
NUMBER	DATE
062 (Rev 1, 02/22/2024)	December 2022

TECHNICAL SERVICE BULLETIN

Subject:

SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118 AND THROTTLE BODY FREEZING (SA514)

NOTICE

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black bar in the margin area. Refer to claim instructions on pages 2 & 10.

This bulletin provides the procedure to update the software logic of the Engine Control Module (ECM) system on some 2022-2024MY Carnival (KA4) vehicles produced from January 4, 2021 through October 26, 2022, which may exhibit an MIL "ON" with DTC P2118. The throttle body plate may freeze after a cold soak in very cold temperatures, possibly causing the vehicle to go into "limp-home" mode. Once the vehicle is warmed up, the throttle body performs normally. Follow the procedure outlined in this publication to apply the improved logic to the 'Engine' system using the KDS ECU Upgrade function as described in this bulletin. For confirmation that the latest reflash has been applied to a vehicle you are working on, verify the ROM ID using the table on pages 3-5 of this bulletin. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.

DTC Description:

P211800: Throttle Actuator Control Motor Current Range/Performance

NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on KDealer+ (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on KDealer+ (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA514.

SUBJECT:

SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118 AND THROTTLE BODY FREEZING (SA514)

ECU Upgrade Procedure:

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in this bulletin.

Upgrade Event Name

712.KA4 LAMBDA 3.5GDI ENGINE MIL ON DTC (P2118 & P00B7) JUDGMENT LOGIC IMPROVEMENT

Revised Publication - Dealer Claim Instructions

- Any vehicle updated with the previous SW Event #637 on or before 2/15/24, will need to use the previous Op Code 220128R0 when submitting the claim.
- Vehicles updated with the new SW Event #712 on or after 2/22/24, will need to use the new provided Op Code 220128R1 when submitting the claim.


NOTICE

- Confirm a fully charged battery (12.3 volts or higher is necessary) is used or utilize a fully charged jump starter box connected to the battery.
- **Ensure the KDS is sufficiently charged at 60% or higher prior to reflash.**
- All ECU upgrades must be performed with the ignition set to the 'ON' position unless otherwise stated.
- **Damaged VCI II units should not be used and promptly replaced.**
- Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.
- **DO NOT start the engine during ECU upgrade.**
- DO NOT turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- **When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.**
- ONLY use approved ECU upgrade software designated for the correct application.

IMPORTANT

It is recommended to ALWAYS check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. DO NOT reference the parts label affixed to the ECU.

NOTICE

Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer  security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.

SUBJECT:

SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118 AND THROTTLE BODY FREEZING (SA514)

ROM ID INFORMATION TABLE:

Upgrade Event #712


Model	Model Year	IMMO 	ECU P/No.	ROM ID	
				Previous	New
KA4	2023	Yes	39110 3N683	GKA 3NUOHF000M03 GKA 3NUOHF100M03 GKA 3NUOHF200M03 GKA 3NUOHF300M03 GKA 3NUOHF400M03	GKA 3NUOHF500M03
		No	39110 3N684	GKA 3NUOHE000M03 GKA 3NUOHE100M03 GKA 3NUOHE200M03 GKA 3NUOHE300M03 GKA 3NUOHE400M03	GKA 3NUOHE500M03
		Yes	39110 3N685	GKA 3NUOHF000ML3 GKA 3NUOHF100ML3 GKA 3NUOHF200ML3 GKA 3NUOHF300ML3 GKA 3NUOHF400ML3	GKA 3NUOHF500ML3
		No	39110 3N686	GKA 3NUOHE000ML3 GKA 3NUOHE100ML3 GKA 3NUOHE200ML3 GKA 3NUOHE300ML3 GKA 3NUOHE400ML3	GKA 3NUOHE500ML3
		Yes	39110 3N687	GKA 3NUOHK000M03 GKA 3NUOHK100M03 GKA 3NUOHK200M03 GKA 3NUOHK300M03 GKA 3NUOHK400M03	GKA 3NUOHK500M03
			39110 3N688	GKA 3NUOHK000ML3 GKA 3NUOHK100ML3 GKA 3NUOHK200ML3 GKA 3NUOHK300ML3 GKA 3NUOHK400ML3	GKA 3NUOHK500ML3
	2022	Yes	39110 3N121 39110 3N196	GKA 0NUOHF000M03 GKA 0NUOHF100M03 GKA 0NUOHF200M03 GKA 0NUOHF300M03 GKA 0NUOHF400M03 GKA 0NUOHF500M03 GKA 0NUOHF600M03 GKA 0NUOHF700M03 GKA 0NUOHF800M03 GKA 0NUOHF900M03	GKA 0NUOHFA00M03
		No	39110 3N122 39110 3N197	GKA 0NUOHE000M03 GKA 0NUOHE100M03 GKA 0NUOHE200M03 GKA 0NUOHE300M03 GKA 0NUOHE400M03 GKA 0NUOHE500M03 GKA 0NUOHE600M03 GKA 0NUOHE700M03 GKA 0NUOHE800M03 GKA 0NUOHE900M03	GKA 0NUOHEA00M03



SUBJECT:

SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118 AND THROTTLE BODY FREEZING (SA514)

Upgrade Event #712 *(continued)*

Model	Model Year	IMMO 	ECU P/No.	ROM ID							
				Previous	New						
KA4	2022	Yes	39110 3N506	GKA ONUOHF000ML3	GKA ONUOHFA00ML3						
				GKA ONUOHF100ML3							
		GKA ONUOHF200ML3									
		GKA ONUOHF300ML3									
GKA ONUOHF400ML3											
GKA ONUOHF500ML3											
GKA ONUOHF600ML3											
GKA ONUOHF700ML3											
GKA ONUOHF800ML3											
GKA ONUOHF900ML3											
No	39110 3N507	GKA ONUOHE000ML3	GKA ONUOHE100ML3	GKA ONUOHE200ML3	GKA ONUOHE300ML3	GKA ONUOHE400ML3	GKA ONUOHE500ML3	GKA ONUOHE600ML3	GKA ONUOHE700ML3	GKA ONUOHE800ML3	GKA ONUOHE900ML3
GKA ONUOHE200ML3											
GKA ONUOHE300ML3											
GKA ONUOHE400ML3											
GKA ONUOHE500ML3											
GKA ONUOHE600ML3											
GKA ONUOHE700ML3											
GKA ONUOHE800ML3											
GKA ONUOHE900ML3											
Yes	39110 3N651	GKA ONUOHK000M03	GKA ONUOHK100M03	GKA ONUOHK200M03	GKA ONUOHK300M03	GKA ONUOHK400M03	GKA ONUOHK500M03	GKA ONUOHK600M03	GKA ONUOHK700M03	GKA ONUOHK800M03	GKA ONUOHK900M03
GKA ONUOHK200M03											
GKA ONUOHK300M03											
GKA ONUOHK400M03											
GKA ONUOHK500M03											
GKA ONUOHK600M03											
GKA ONUOHK700M03											
GKA ONUOHK800M03											
GKA ONUOHK900M03											
Yes	39110 3N652	GKA ONUOHK000ML3	GKA ONUOHK100ML3	GKA ONUOHK200ML3	GKA ONUOHK300ML3	GKA ONUOHK400ML3	GKA ONUOHK500ML3	GKA ONUOHK600ML3	GKA ONUOHK700ML3	GKA ONUOHK800ML3	GKA ONUOHK900ML3
GKA ONUOHK200ML3											
GKA ONUOHK300ML3											
GKA ONUOHK400ML3											
GKA ONUOHK500ML3											
GKA ONUOHK600ML3											
GKA ONUOHK700ML3											
GKA ONUOHK800ML3											
GKA ONUOHK900ML3											

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.

SUBJECT:

SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118 AND THROTTLE BODY FREEZING (SA514)

NOTICE

Prior to performing the ECU upgrade, be sure to check that the KDS is fully charged.

1. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.

NOTICE


The ECU upgrade function on KDS operates wirelessly. It is not necessary to perform the upgrade via USB cable.




2. With the ignition ON, turn ON the KDS tablet. Select 'KDS' from the home screen.



3. Confirm communication with VCI (A) and then configure the vehicle (B) using the 'AUTO VIN' (C) feature.



4. Select 'ECU Upgrade'.



SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118 AND THROTTLE BODY FREEZING (SA514)

SUBJECT:

- The KDS will check the server for recently uploaded Events and then automatically download Upgrade Event #712.

NOTICE

The vehicle must be identified in Vehicle Selection to download an Event for that vehicle.

After the download is complete, the program will shut down to install. Please wait until the program restarts.

Event	Status
271.QF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT	Downloading
273.TF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT	Ready

36%

Do not touch any system buttons while performing this function.

KDS screenshot shown above is for demonstration purposes only. Events shown in screenshot are not applicable to this bulletin.

- Select Auto Mode.

CAUTION

Do NOT attempt to perform a Manual Mode upgrade UNLESS Auto Mode fails. Always follow the instructions given on the KDS in either Auto or Manual mode.

Auto Mode Manual Mode

- Select 'ENGINE' system and applicable 'Event Group' (D) for the vehicle:

712.KA4 LAMBDA 3.5GDI ENGINE MIL ON DTC (P2118 & P00B7) JUDGMENT LOGIC IMPROVEMENT

CARNIVAL(KA4) > 2023 > G 3.5 GDI LAMBDA III

System

ENGINE PSD

Event Group

KA4 Lambda 3.5GDI +IMMO/SMK (23MY) : 39110-3N688

KA4 Lambda 3.5GDI +IMMO/SMK (22MY) : 39110-3N121(SBC)

KA4 Lambda 3.5GDI +IMMO/SMK (22MY) : 39110-3N196(SBW)

KA4 Lambda 3.5GDI -IMMO (22MY) : 39110-3N122(SBC)

KA4 Lambda 3.5GDI -IMMO (22MY) : 39110-3N197(SBW)

D

TSB

- The ECU upgrade will begin, and the progress of the upgrade will appear on the bar graph. Upgrade part (1/2) (E) will download the upgrade event to the VCI-II. Upgrade part (2/2) (F) will upgrade the ECU.

CAUTION

Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing ECU Upgrade.

E

23%

ECU Upgrading...(1/2)

ECU is in the process of being upgraded. Please wait a few minute.

F

6%

ECU Upgrading...(2/2)

ECU is in the process of being upgraded. Please wait a few minute.




SUBJECT:

SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118 AND THROTTLE BODY FREEZING (SA514)


9. If a "Communication Fail" screen appears, verify that the VCI-II and KDS are communicating properly. Select 'OK' and restart the procedure from step 4.

NOTICE


If an error notice continues to appear or if the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.




10. When instructed on the KDS, turn the ignition OFF for ten (10) seconds then back on. Select 'OK' to continue.



11. Once the upgrade is complete, select 'OK' to finalize the procedure.



12. When prompted, select 'YES' to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.



13. Start the engine to confirm normal operation of the vehicle.

SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118 AND THROTTLE BODY FREEZING (SA514)

Manual Upgrade Procedure:

NOTICE

The manual upgrade should **ONLY** be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition 'OFF' for about 10 seconds then place it back in the 'ON' position to reset the control unit BEFORE performing manual upgrade.

See table below for 'Manual Mode' passwords.

Manual Mode ECU Upgrade Passwords

Menu	Password
KA4 Lambda 3.5GDI ULEV 70 (24MY) : 39110-3N693	3693
KA4 Lambda 3.5GDI ULEV 70 (24MY) : 39110-3N694	3964
KA4 Lambda 3.5GDI ULEV 70 (24MY) : 39110-3N695	3695
KA4 Lambda 3.5GDI ULEV 70 (24MY) : 39110-3N696	3696
KA4 Lambda 3.5GDI ULEV 70 (24MY) : 39110-3N697	3067
KA4 Lambda 3.5GDI ULEV 70 (24MY) : 39110-3N698	3698
KA4 Lambda 3.5GDI +IMMO/SMK (23MY) : 39110-3N683	3639
KA4 Lambda 3.5GDI -IMMO (23MY) : 39110-3N684	0364
KA4 Lambda 3.5GDI +IMMO/SMK (23MY) : 39110-3N685	5863
KA4 Lambda 3.5GDI -IMMO (23MY) : 39110-3N686	3586
KA4 Lambda 3.5GDI +IMMO/SMK (23MY) : 39110-3N687	7863
KA4 Lambda 3.5GDI +IMMO/SMK (23MY) : 39110-3N688	2335
KA4 Lambda 3.5GDI +IMMO/SMK (22MY) : 39110-3N121(SBC)	9999
KA4 Lambda 3.5GDI +IMMO/SMK (22MY) : 39110-3N196(SBW)	9699
KA4 Lambda 3.5GDI -IMMO (22MY) : 39110-3N122(SBC)	8322
KA4 Lambda 3.5GDI -IMMO (22MY) : 39110-3N197(SBW)	9739
KA4 Lambda 3.5GDI +IMMO/SMK (22MY) : 39110-3N506	6350
KA4 Lambda 3.5GDI -IMMO (22MY) : 39110-3N507	7510
KA4 Lambda 3.5GDI +IMMO/SMK (22MY) : 39110-3N651	1973
KA4 Lambda 3.5GDI +IMMO/SMK (22MY) : 39110-3N652	2348

SUBJECT:

**SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118
AND THROTTLE BODY FREEZING (SA514)**

1. Within the ECU Upgrade screen displayed, select **Manual Mode**.
2. Select the '**ENGINE**' system under the System selection menu. Select **Upgrade Event #712** and select **Upgrade** to continue.
3. Select the appropriate control unit part number with reference to the ROM ID Information Table on pages 3-4, and select **OK**.
4. Enter the appropriate password from the Manual Mode password table above and select **OK**.
5. The upgrade will begin and the progress of the upgrade will appear on the bar graph.
6. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Select **OK**.
7. Once the upgrade is complete, select **OK** to finalize the procedure.
8. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.
9. Start the engine to confirm proper operation of the vehicle.



SUBJECT: SERVICE ACTION: ECM LOGIC UPDATE FOR DTC P2118 AND THROTTLE BODY FREEZING (SA514)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
Carnival (KA4)	January 4, 2021 to October 26, 2022

REQUIRED TOOL:

Tool Name	Figure	Comments
KDS		Kia Diagnostic System

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	39110 3N683	0	(SA514) ECM Logic Improvement	220128R1 (See Message Below)	0.4 M/H	N/A	0

Dealer Claim Instructions: Any vehicle updated with the previous SW Event #637 on or before 2/15/24, will need to use the previous Op Code 220128R0 when submitting the claim. Vehicles updated with the new SW Event #712 on or after 2/22/24, can submit the claim with the new provided Op Code 220128R1 above.

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA514 when accessing the KDealer+ system.

