

4. Place vehicle into: **Accessory mode**. See owner's manual.
 - a. Software update will be cancelled if attempted with the vehicle in the **IGN ON** position.
5. Allow the IFCU to fully boot up and then connect USB-C thumb drive to USB cable.
6. Update will start automatically. Follow prompts shown on the IFCU screen.
 - a. See (Infotainment Control Unit (IFCU) Support Resources) for video.
7. After update is completed, cycle the ignition and repeat Step 1 to confirm Skyline™ OS has updated to (Software version 240002111D).

NOTE

Delete Skyline™ OS folder from thumb drive or use a different thumb drive for the Amplifier software.

8. Unzip Amplifier folder and place file into the root directory of a USB-C thumb drive.
9. Place vehicle into: **Accessory mode**. See owner's manual.
10. Allow the IFCU to fully boot up and then connect USB-C thumb drive to USB cable.
11. Update will start automatically, follow prompts shown on the IFCU screen.
 - a. See (Infotainment Control Unit (IFCU) Support Resources) for video.

Credit Procedure

NOTE

Enter M1625 into comment section of claim.

Submit a warranty claim per Table 4.

In the event additional time is required to complete the update, use 8888 up to two hours and file as an additional labor line in the same event of the claim. Add detailed notes to the claim outlining the need for the additional time. If more than two hours is needed, please make sure to obtain an authorization from Tech Service prior to filing the claim.

Repair times for the IFCU and Amplifier updates are combined, and we have removed overlapping time for downloading the software to the USB-C thumb drive. Since downloads to the USB-C thumb drive are only required once for the IFCU and Amplifier individually, the repair time is reflected accordingly.

Table 4. IFCU and Amplifier Software Update

ITEM	DATA
Claim Type	PRD/MC/DEM - PDI/Standard claim
Problem Part Number	70901090A (DOM) 70901092A (HDI) 70901093A (ROW)
Quantity	Leave blank
Labor Code ⁽¹⁾	1754
Labor Time	0.6 hours
Customer Concern Code	9203
Condition Code	1754
<i>(1) Download may be required</i>	

Dealers that have been credited 0.4 hours on claims for M1625 will receive an additional 0.2 hours per claim on a manual credit issued in the coming weeks. No further action required by the dealership.