

Technical product information

Topic	New Continental GT and GTC - Window drop glass operation
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 723 Volkswagen (Anhui) Automotive CO (6723),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2070497/7
Level	EH
Status	Approval
Release date	

Event memory entries

Diagnostic address	Event memory entry	Fault type	Fault status
0052 - Passenger's door electronics	B148754: Window regulator motor no basic setting		Intermittent
00BB - Rear drivers side door electronics	B148754: Window regulator motor no basic setting		Intermittent
00BC - Rear passenger side door electronics	B148754: Window regulator motor no basic setting		Intermittent
0042 - Driver's door electronics	B148754: Window regulator motor no basic setting		Intermittent

New customer code

Object of complaint	Complaint type	Position
body fixtures and fittings -> window opening/closing, window heating -> window return at door-closing	functionality -> without function / defect	rear right
body fixtures and fittings -> window opening/closing, window heating -> window drop at door-opening	functionality -> defective function sequence	front left
body fixtures and fittings -> window opening/closing, window heating -> window drop at door-opening	functionality -> defective function sequence	rear left
body fixtures and fittings -> window opening/closing, window heating -> window drop at door-opening	functionality -> defective function sequence	front right
body fixtures and fittings -> window opening/closing, window heating -> window return at door-closing	functionality -> without function / defect	front left
body fixtures and fittings -> window opening/closing, window heating -> window return at door-closing	functionality -> without function / defect	rear left
body fixtures and fittings -> window opening/closing, window heating -> window return at door-closing	functionality -> without function / defect	front right
body fixtures and fittings -> window opening/closing, window heating -> window drop at door-opening	functionality -> defective function sequence	rear right

Vehicle data

New Continental GT and GTC

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2018	E		*	*	*
3S3*	2019	E		*	*	*
3S3*	2020	E		*	*	*
3S3*	2021	E		*	*	*
3S3*	2022	E		*	*	*
3S3*	2023	E		*	*	*
3S3*	2024	E		*	*	*
3S4*	2019	E		*	*	*
3S4*	2020	E		*	*	*
3S4*	2021	E		*	*	*
3S4*	2022	E		*	*	*
3S4*	2023	E		*	*	*
3S4*	2024	E		*	*	*

Documents

Document name
master.xml
newglasssetgt.pdf
newglasssetsheetgtc.pdf
retailerglassresetprocedureforgtgcintables.pdf

Customer statement / workshop findings

- Incorrect operation / function of the front and / or rear window drop glass
- Front and / or rear drop glass fails to open/close or attempts to close and re-opens once contact has been made between the glass and applicable seal
- DTC for window regulator motor no basic setting B148754 evident within any of the 4 window control modules (diagnostic address 42, 52, BB and BC) for loss of basic settings

Technical background



IMPORTANT NOTE: Aftermarket window tinting can affect the operation of the windows, please advise customers the onward instructions should not be applied until all aftermarket tinting has been removed

TPI revision history



CAUTION

The operative must always ensure the latest version of this TPI is obtained from Elsa pro using the applicable VIN as TPI versions can change without notice

TPI 2070497/7

- Note added at the beginning of the Measure section to instruct operatives to complete all steps in the exact order shown
- Changes have been added after step 16 as detailed below



Should the issue still be evident the operative must raise a new DISS query or respond via the previously opened DISS query and await feedback before conducting any further work ensuring the following question is answered and included within the DISS query

Question:

Did the drop door glass operational issue occur when opening or closing the door

Or

Whilst operating the applicable window?



NOTICE

NOTE TO PRODUCT SUPPORT: In the event a DISS query is received with a complaint relating to drop glass operational issues after the instructions within this TPI have been conducted, please second level the DISS query to the Body and Trim Senior Engineer and await feedback before responding to the retailer

Production change

The Bentley continuous improvement policy has been implemented within the manufacturing process, the required improvements have been utilised within this TPI

Measure



VERY IMPORTANT: To eliminate a repeat repair the instructions within the Measure section and attached PDF instructions must be conducted on the front and rear drop door glass - left and right hand side to completion

ALL steps MUST be conducted from step 1 through to 16 (DO NOT IGNORE ANY OF THE STEPS)

ALL STEPS MUST BE CONDUCTED TO COMPLETION IN THE EXACT ORDER

1) Referring to Rep.Gr 27 - Carry out a 12 Volt battery test "WARRANTY TEST" or "ORIG. VW-BATT. TEST"



NOTICE

VERY IMPORTANT: Save an image of the battery printout as this will be required to be attached to a new or existing DISS query, should any issues be evident with the 12 volt battery/system this should be rectified before proceeding any further

- In the event there was an issue with the 12 volt battery and the drop door glass issue is now resolved no further action is required

However

In the event the drop glass issue is still evident after the confirming the 12 volt battery is to specification the operative should conduct the onward instructions to completion



Before proceeding with the onward instructions the following window closing time results are required to be attached to a new or existing DISS query

VERY IMPORTANT: Do not proceed with the time measurement request instructions unless the battery is confirmed to be within specification (battery test) a 12 volt battery charger must also be installed as per Rep.Gr 27

Passenger side front and rear

Hint: The window closing time should be 4 seconds

- Measure the time (in seconds) it takes to close the front and rear windows from fully open to the fully closed position
- Record the time

Passenger side front = seconds

Passenger side rear = seconds

Comments

Driver side front and rear

Hint: The window closing time should be 4 seconds

- Measure the time (in seconds) it takes to close the front and rear windows from fully open to the fully closed position

Driver side front = seconds

Driver side rear = seconds

Comments

Section 1 - Door control module identification/update instructions

NOTICE

The control modules should all be at 'D' suffix or all at 'J' suffix, replacement of 'D' level control modules to 'J' level does not fix the problem, replacement of control modules should not be conducted without permission via DISS, in the event the control modules were replaced without permission all applicable Warranty claims will be cancelled

- In the event that a control module is suspected as being faulty the operative must request permission via DISS before replacing any parts
- Do not under any circumstances combine 'D' suffix control modules with 'J' suffix parts all four control modules must all have the same suffix



Hint: In the event the software is not at the levels shown in Reference table 1,2,3 and 4 the operative must conduct the applicable software updates within Section 1 and/or Section 2 and then conduct Section 3

However

In the event the software is at the correct levels as shown in Reference table 1,2,3 and 4 the operative must conduct Section 3 only

2) Check and if necessary update the applicable door control modules as follows:

CAUTION

Should the control modules **NOT** be at the latest levels as shown in Reference table 1 and 2 please conduct the two separate software updates within Section 1 and Section 2 to completion before proceeding with Section 3

However

In the event the software levels are to specification as shown in Reference table 1 and 2 please only conduct the software update within Section 2 before proceeding with Section 3

D suffix control modules - Reference table 1

Door control module	Part number	Software version	Target data container
0042 – Drivers door	4M1.959.953.D	0189	V03.935.344.TP
0052 – Passenger door	4M1.959.952.D	0189	V03.935.344.TQ
00BB – Rear driver's door	4M1.959.955.D	0189	V03.935.344.TR
00BC – Rear passenger door	4M1.959.955.D	0189	V03.935.344.TS

J suffix control modules - Reference table 2

Door control module	Part number	Software version	Target data container
0042 – Drivers door	4M1.959.953.J	0430	V03.935.349.CM
0052 – Passenger door	4M1.959.952.J	0430	V03.935.349.CN
00BB – Rear driver's door	4M1.959.955.J	0430	V03.935.349.CP
00BC – Rear passenger door	4M1.959.955.J	0430	V03.935.349.CQ

Software update - Front and rear door control modules

- The closed-circuit voltage of the vehicle must be at least 12.5 V during the update. Connect a suitable battery charger to the vehicle. For further information refer to the Repair manual
- During the update switch off all unnecessary consumers (ventilation, seat heater, interior illumination etc) ensure the main light switch is set to 'off' and leave the driver's door open
- Because of the highest transmission stability you **MUST** use the diagnosis interface VAS 6154 (WiFi diagnostic tool) **ONLY** in USB operation or the cable-connected VAS 5055 for the reprogramming (updating) of control modules. If these units are not available, the diagnosis interface VAS 5054 (A) can also be used in USB mode
- Do Not under any circumstances use a Bluetooth connection to conduct the reprogramming (updating) of any control modules

3) Referring to Figure 1 - Within the Special functions tab - Select SVM - Code Input (Point A)

- Select Perform test (Point B)




Figure 1

4) Referring to Figure 2 - Enter SVM code 370FTM01




Figure 2

- When prompted enter your global user ID and password
- Follow all on screen prompts to continue through the procedure, the identification data will be transferred

5) The required control modules will be automatically updated one by one, starting with 0042 – Door electronics Drivers side (Figure 3)




Figure 3

6) Once the update is complete the summary screen will be shown in Figure 4, this confirms completion of the required updates




Figure 4

7) Recheck the Door control module versions against the Reference tables 1 and 2 (depending on Part number/Software version)

Section 2 - Software update - Rear door control modules 00BB and 00BC (short drop function elimination)

NOTICE

The software update eliminates the rear window short drop function

Hint: In the event the software is not at the levels shown in Reference table 1,2,3 and 4 the operative must conduct the applicable software updates within Section 1 and/or Section 2 and then conduct Section 3

However

In the event the software is at the correct levels as shown in Reference table 1,2,3 and 4 the operative must conduct Section 3 only

8) Referring to Figure 5 - Within the Special functions tab - Select SVM - Code Input (Point A)

• Select Perform test (Point B)




Figure 5

9) Referring to Figure 6 - Enter the SVM code **370WAD01**




Figure 6

- When prompted enter your global user ID and password

- Follow all on screen prompts to continue through the procedure, the identification data will be transferred
- 10) The control modules will automatically be updated one by one, starting with 00BB (Driver rear) and then 00BC (passenger rear)
- 11) Recheck the Door control module versions against the Reference tables 3 and 4 (depending on Part number/Software version)

Reference table 3

Door control module	Part number	Software version	Target data container
00BB - Rear driver's door	4M1959955D	0189	V03935413CW
00BC - Rear passenger door	4M1959955D	0189	V03935413CX

Reference table 4

Door control module	Part number	Software version	Target data container
00BB - Rear driver's door	4M1959955J	0430	V03935405MS
00BC - Rear passenger door	4M1959955J	0430	V03935405MT

Section 3 - Rectification/check instructions

12) Conduct a thorough check of all Window/door seals for the following:

- Damage
- Splits
- Tears
- Misalignment
- Incorrectly fitted/located
- Drop glass seal deformation (see Figures 9 and 10 as examples)



Figure 9



Figure 10

NOTE: Any issues found with the window seals must be rectified before conducting the remaining steps

13) VERY IMPORTANT: Referring to the attached PDF instruction the operative must conduct all steps to completion before continuing from step 14

! NOTICE

Please ensure all steps are followed within the attached glass check/measurement PDF documents, the operative should be aware there is (x1) document for New Continental GT and (x1) document for New Continental GTC please ensure the correct document is used depending on vehicle type



Ensure all required measurements are attached to a new or existing DISS query

! NOTICE

If not already done so, review eAcademy Digital Learning HUB videos on Glass Setting Procedures for GT/GTC before proceeding to ensure accurate and repeatable measurements are being made

Log into eAcademy - Select/open Digital Learning HUB - All content - Technical information - Continental GT & GT Convertible (2017+) Technical Information

- The operative must review the (x3) videos which are available on the Digital Learning HUB (see example shown in Figure 9 of all videos which must be reviewed)




Figure 9

14) VERY IMPORTANT - Referring to Rep.Gr 64 - Side glass - To initialise

CAUTION

When conducting step 15 extra care must be taken to ensure the interior trim is suitably protected, any water which enters the vehicle due to a leak must be dried / cleaned immediately

Hint: Ensure all windows, sunroof and convertible roof (where applicable) are fully closed before conducting the water leak check

15) Conduct a water leak check to ensure that water is not leaking into the vehicles interior

- Water leaks must be resolved before returning the vehicle to the customer

16) Conduct a short road test to check for any wind noise related issues

CAUTION

Wind noise issues must be resolved before returning the vehicle to the customer



Should the issue still be evident after conducting steps 1 through to 16 (including the software update) the operative must raise a new DISS query or respond via the previously opened DISS query and await feedback before conducting any further work ensuring the following question is answered and included within the DISS query

Question:

Did the drop door glass operational issue occur when opening or closing the door

Or

Whilst operating the applicable window?

NOTICE

NOTE TO PRODUCT SUPPORT: In the event a DISS query is received with a complaint relating to drop glass operational issues after the instructions within this TPI have been conducted, please second level the DISS query to the Body and Trim Senior Engineer and await feedback before responding to the retailer

Warranty accounting instructions

Warranty type 110 or 910

Damage service number 64 38

Damage code 0012

Time to update door control modules

Labour

Labour operation code 01 51 00 00

Time As per ODIS log (Must not exceed 50 TU)

Time to conduct initial checks

Labour operation code 64 38 02 00

Time 30 TU

Time to conduct window seal checks

Labour operation code 57 63 01 01 (Use 99 index until 08/02/24)

Time 20 TU

Time to conduct the front glass set procedure

Labour operation code 64 40 15 00 (Use 99 index until 08/02/24)

Time 140 TU (per side)

Time to conduct the rear glass set procedure

Labour operation code 64 75 15 00 (Use 99 index until 08/02/24)

Time 170 TU (per side)

Water leak test

Labour operation code 64 38 01 99 (Use this code when conducting the water leak test)

Time 20 TU

Post repair road test

Labour operation code 01 21 00 01

Time 30 TU

Parts information

Reference ETKA where required



BENTLEY

Retailer glass reset procedure for GT/GTC





- Introduction Page 3
- Front quarter glass adjuster reset Page 4
- Front door regulator adjuster reset Pages 5, 6 & 7
- Rear quarter regulator adjuster reset Pages 8, 9 & 10
- Measuring front glass intrusion into front division bar Page 11
- Z Axis height adjustment on front drop glass Page 12
- Waistrail measurement checking/resetting Pages 13, 14 & 15
- Window entry into cant rail/convertible roof seal Page 16
- Final Checks Page 17
- Glass set measurement sheets Page 18 & 19



BENTLEY

Introduction

In instances of multiple window drop concerns it has been found that to achieve Glass set specifications some adjusters are being adjusted far out of specification.

In some cases since not all adjusters are visible, there is a possibility that the adjusters can be set to their maximum inboard/outboard and induce excess tension in the regulators and affect the angle the windows enter the seals.

There is free play built into the front and rear regulators, therefore as the windows are being held in place by the cant rail/convertible roof seals when closed, this may not be apparent when measuring as per ELSAPRO. However, these extreme adjustments can cause issues with how the windows enter the cant rail/convertible roof seals or how the front and rear glasses interlock with each other, in some cases this can cause the seals to pinch and cause an anti trap condition leading to window reversal.

The following procedure should be applied to reset the regulator adjusters to factory delivered specification and then fine tune any adjustments from there in line with ELSA specifications. **To do this, the drop glass window should be removed first to prevent damage during adjuster resetting** and access to all 8 adjusters is needed so front door and rear quarter panel trims will require removal.

If not already done so, review E-Academy videos on Glass Setting Procedures for GT/GTC before proceeding to ensure accurate and repeatable measurements are being made.

Alex Broadbent VT/QQ



BENTLEY

- Front quarter glass adjuster reset

Front Quarter glass adjuster Item 1

Measurement between bottom of mounting washer and division bar frame, is 12.5mm.

To reset this adjuster without removing the quarter glass, loosen the lock nut, screw the adjuster all the way in clockwise until it bottoms out on the frame, then unscrew anti clockwise 4 complete turns then set height and profile to ELSA specification before moving on to the next step.



Image for reference, glass does not require removal from vehicle




Alex Broadbent VT/QQ



BENTLEY

- Front door regulator adjuster reset



Regulator adjusters X1 X2

Measure from top of mounting washer to frame

X1 = 4mm

X2 = 4.5mm

Regulator adjusters Y1 Y2

Measure from top of mounting washer to frame

Y1 = 14mm

Y2 = 10mm

Reset all 4 adjusters as described in the following slides, then continue to reinstall and set front drop glass to ELSA specifications before moving on to the next step.



Regulator adjusters Y1 Y2

Measurement from top of mounting washer to frame

Y1 = 14mm, To reset this adjuster without removing the front regulator, fully screw in clockwise until hard stop, then unscrew 12 turns anticlockwise



Y2 = 10mm, To reset this adjuster without removing the quarter glass fully screw in clockwise until hard stop, then unscrew 8.5 turns anticlockwise

- Front door regulator adjuster reset

Y1

Images for reference, regulator does not require removal from vehicle

Y2





Regulator adjusters X1 X2


Measure from top of
mounting washer to
frame

X1 = 4mm, To reset
this adjuster without
removing the
regulator fully screw
in clockwise until
hard stop, then
unscrew 4 turns
anticlockwise


X2 = 4.5mm, To
reset this adjuster
without removing
the regulator
fully screw in
clockwise until hard
stop, then unscrew
4 turns
anticlockwise

X1

Images for reference, regulator does
not require removal from vehicle




X2




- Front door regulator adjuster reset

Alex Broadbent VT/QQ

- **Measuring front glass intrusion into front division bar**



When reinstalling front drop glass ensure tape is applied at 10mm from front edge and align this with the previously set quarter glass division bar.



Example of incorrect fitment:
10mm intrusion into division bar seal not achieved. Only 6mm seen, front and rear side glasses will be too far rearwards, potentially clash condition between rear of rear glass and cant rail/roof seals

- Z Axis height adjustment on front drop glass





Z-Axis height should only be adjusted by the 4mm Allen key adjusters as per ELSAPRO

Example: Front drop glass Z axis not adjusted correctly. Bottom of tape was level with waist rail seal, after slackening pinch bolt (3 in bottom left image) front drop glass lowered 14mm to where pen marked line is.

Z-axis adjusters (bottom middle and right images) had not been used, pinch bolt had been slacked and glass lifted out of the regulator to achieve specification. This has a knock on effect of altering the 10mm division bar intrusion seen in previous slide as glass is loose and can be accidentally moved in X-axis.

This also creates a risk that the window will bottom out on the cant rail seals rather than the regulator bump stops meaning that the glass can raise further as the seals soften over time and affect end stop learning.






Rear Regulator adjusters 1, 2, 3

Adjust the rear window regulator adjusters at the following points as shown in the following page

Before resetting adjusters remove the 3 13mm lock nuts (1-3 in image) to allow adjusters to be fully screwed in without damaging the regulator, Also ensure black closing panel (see page 12) is not stopping the regulator from moving when performing these adjustments.

- Rear quarter regulator adjuster reset





BENTLEY

Adjuster 1

fully screw in clockwise until hard stop, then unscrew 9.5 turns anticlockwise to achieve 12mm gap as seen below



Adjuster 2


fully screw in clockwise until hard stop, then unscrew 9.5 turns anticlockwise to achieve 12mm gap as seen below



- Rear quarter regulator adjuster reset

Adjuster 3

fully screw in clockwise until hard stop, then unscrew 1 turn anticlockwise to achieve 20mm gap as seen below



Images for reference, regulator does not require removal from vehicle

Alex Broadbent VT/QQ



- Rear quarter regulator adjuster reset


After resetting all 3 adjusters leave the locking nuts loose to allow vertical movement.

Ensure closing panel (item 3) is installed and 10mm nuts (item 2) are tightened to set regulator height before tightening adjuster locking nuts (item 1-3 in image on page 10). Ensure regulator is bottoming out on bump stops when measuring/setting glass height in Z-axis


Proceed with adjusting rear quarter glass into ELSA specification

IMPORTANT

10mm nuts (item 2) must be loosened when adjusting the 3 regulator adjusters to allow the regulator to move. Retighten and check measurements after each adjustment is made





- **Wastrail measurement checking/resetting**




Images show a poor setting.
Circa 6mm at front edge (near wing mirror)
closing up to 2mm at the rear edge.


2mm at rear edge would have been set to achieve specified flush/2mm underflush profile condition between front and rear glasses, the rear quarter glass mirrors this taper condition. This potentially increases the risk of false anti trap as rear window/seal does not engage with front window at the correct angle. Suggested to set to specification on problem vehicles as per next slide. If both windows are set between 4-6mm then the flush/2mm underflush profile can be easily achieved.



- **Wastrail measurement checking/resetting**



Set waist rail gapping to between 4-6mm as mentioned in Glass setting guide videos on E-Academy and also check for parallelism along front and rear windows to door/quarter. 50mm from edge of Waistrail seal, roughly underneath the Bentley wings.




- **Wastrail measurement checking/resetting**

When setting front to rear window profile and waist rail measurements ensure that the front window does not move outboard excessively when the rear window closes as this will increase current draw on the rear motor during the period where it is monitoring for it's end stop, excess current draw in this zone can cause a false anti-trap scenario.


There does need to be some tension between the front and rear glass to seal against the drop glass seal, zero mm of movement is best.

If more tension is required to resolve a wind noise or water ingress then aim for no more than 0.25mm of outboard movement.


RHF window, front window closed, rear window open. Note gap



RHF window, front window closed, rear window closed. Note gap, over 0.25mm outboard movement, this is incorrect



Window entry into cant rail/convertible roof seal



Windows should enter cant rail seal smoothly, making contact with inboard edge first and then be pushed outboard (green square).

Too far inboard increases the risk of the cant rail seal pinching, too far outboard will clash with cant rail brightware (red squares). For front door, poor door profile is a major contributing factor here and should be checked/adjusted if window found to be entering seal incorrectly.

Front window examples showing correct operation

Final checks

After all adjustments have been made and recorded in tables from ELSA workshop manual section “**Side glass - To check**”. Door ECU basic settings must be relearnt. Ensure battery is fully charged and passes VAS6161 Warranty/VW-Orig battery test with result “Good Battery”, voltage should be above 12.5V.

Test window operation in all scenarios, e.g. global open/close, individual window switches, driver door switches, convenience open/close (where applicable), short drop functions when opening/closing doors and with convertible roof open/closed if working on a GTC.

Finally, ensure vehicle still passes water ingress test and does not have excessive wind noise, any further adjustments must remain within ELSA specifications.

Complete and attach to DISS ticket

Side glass measurements GT				
Interlock (Z-Axis)	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
A 50 mm from division bar	Front quarter glass	7.5 mm $\pm$ 1 mm		
B 150 mm from division bar	Front of door drop glass	8 mm $\pm$ 1 mm		
C 50 mm from rear of door drop glass	Rear of door drop glass	8 mm $\pm$ 1 mm		
D 50 mm from rear drop glass division bar	Front of rear quarter glass	8 mm $\pm$ 1 mm		
E 50 mm from rearmost section of rear drop glass	Rear of rear quarter glass	8 mm $\pm$ 1 mm		
Interlock (X-Axis)	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
4 50 mm from the top of the window	Rear door quarter glass strip to front door drop glass edge	11 mm $\pm$ 1 mm		
5 50 mm from the waistrail seal	Rear door quarter glass strip to front door drop glass edge	11 mm $\pm$ 1 mm		
Profile (Y-Axis)	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
1 50 mm from division bar	Front quarter glass	10 mm $\pm$ 1 mm		
2 150 mm from division bar	Front of door drop glass	10 mm $\pm$ 2 mm		
3 50 mm from rear of door drop glass	Rear of door drop glass	10 mm $\pm$ 2 mm		
6 50 mm from rear drop glass division bar	Front of rear quarter glass	10 mm $\pm$ 2 mm		
7 50 mm from rearmost section of rear drop glass	Rear of rear quarter glass	10 mm $\pm$ 2 mm		
8 50mm forwards of rear of front drop glass (waist rail gap)	Rear of door drop glass	5mm $\pm$ 1mm		
9 50mm rearward of front of rear drop glass (waist rail gap)	Front of rear quarter glass	5mm $\pm$ 1mm		
Profile (Y-Axis)	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
4 50mm from top of division bar	Front drop glass to rear quarter glass	+0 mm / – 2 mm		
5 50mm from bottom of division bar	Front drop glass to rear quarter glass	+0 mm / – 2 mm		

Complete and attach to DISS ticket

Side glass measurements GTC				
Interlock (Z-Axis)	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
1 50 mm from division bar	Front quarter glass	7.5 mm ± 1 mm		
2 100 mm from division bar	Front of door drop glass	8.5 mm ± 1 mm		
3 50 mm from rear of door drop glass	Rear of door drop glass	8.5 mm ± 1 mm		
6 50 mm from rear drop glass division bar	Front of rear quarter glass	8.5 mm ± 1 mm		
7 100 mm from where the hood meets the brightware	Rear of rear quarter glass	10 — 16mm		
Interlock (X-Axis) Roof Up	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
4 50 mm from the top of the window	Rear door quarter glass strip to front door drop glass edge	11 mm ± 1 mm		
5 50 mm from the waistrail seal	Rear door quarter glass strip to front door drop glass edge	11 mm ± 1 mm		
Interlock (X-Axis) Roof Down	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
4 50 mm from the top of the window	Rear door quarter glass strip to front door drop glass edge	11 mm ± 1 mm		
5 50 mm from the waistrail seal	Rear door quarter glass strip to front door drop glass edge	11 mm ± 1 mm		
Profile (Y-Axis)	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
1 50 mm from division bar	Front quarter glass	10 mm ± 1 mm		
2 100 mm from division bar	Front of door drop glass	14 mm ± 2 mm		
8 50mm forwards of rear of front drop glass (waist rail gap)	Rear of door drop glass	5mm ± 1mm		
9 50mm rearward of front of rear drop glass (waist rail gap)	Front of rear quarter glass	5mm ± 1mm		
Profile (Y-Axis) Roof Up	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
4 50mm from top of division bar	Front drop glass to rear quarter glass	+0 mm / – 2 mm		
5 50mm from bottom of division bar	Front drop glass to rear quarter glass	+0 mm / – 2 mm		
Profile (Y-Axis) Roof Down	Vehicle Position	Dimension -X-	Before adjustment	After adjustment
4 50mm from top of division bar	Front drop glass to rear quarter glass	+0 mm / – 2 mm		
5 50mm from bottom of division bar	Front drop glass to rear quarter glass	+0 mm / – 2 mm		