



| | |
|--------|--------------------------|
| GROUP | MODEL |
| ELE | 2024MY Sorento (MQ4a) |
| NUMBER | DATE |
| 334 | March 2024 |

TECHNICAL SERVICE BULLETIN

SUBJECT: SERVICE ACTION: WIRELESS POWER CHARGER OPERATION LOGIC IMPROVEMENT (SA563)

This bulletin provides information to improve the wireless power charger (WPC) (also referred to as wireless phone charger) operation logic on certain 2024MY Sorento (MQ4a PE) vehicles produced from December 7, 2023 through February 20, 2024. The WPC controller can switch from 'standby mode' to 'active mode' potentially causing the 12V auxiliary battery to discharge while the vehicle is parked. If this occurs, the vehicle might not be able to be started. Follow the procedure outlined in this publication to upgrade the WPC software on the applicable vehicle. For confirmation that the latest reflash has been applied to a vehicle you are working on, verify the ROM ID using the table on page 3 of this bulletin. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.



NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on KDealer+ (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on KDealer+ (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA563.

ECU Upgrade Procedure:

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in this bulletin.

| Upgrade Event Name |
|---|
| 726.MQ4a PE WPC Operation Logic Improvement |

NOTICE


- Confirm a fully charged battery (12.3 volts or higher is necessary) is used or utilize a fully charged jump starter box connected to the battery.
- **Ensure the KDS GDS is sufficiently charged at 60% or higher prior to reflash.**
- All ECU upgrades must be performed with the ignition set to the 'ON' position unless otherwise stated.
- **Damaged VCI II units should not be used and promptly replaced.**
- Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.
- **DO NOT start the engine during ECU upgrade.**
- DO NOT turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- **When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.**
- ONLY use approved ECU upgrade software designated for the correct application.

IMPORTANT


It is recommended to ALWAYS check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. DO NOT reference the parts label affixed to the ECU.

Note: When connecting the external battery pack, in-vehicle operation built-in CAM might be issued by impossible charging amount sensing of the battery sensor.

[Connect the negative \(-\) terminal to the battery as shown below.](#)




NOTICE

Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer  security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.

ROM ID INFORMATION TABLE:

Upgrade Event #726

| Model | System | IMMO  | ECU P/No. | ROM ID | |
|---------|--------|--|-------------|------------------------------|------|
| | | | | Previous | New |
| MQ4a PE | WPC | Yes | 95560 P2600 | 1.10 1.20 1.30 1.40 | 1.50 |

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.

[NOTE]

- ECU upgrade function on KDS is basically operating in wireless communication as Wi-Fi direct. Also, it's possible to be performing via USB cable between Tablet PC and VCI-II.
- Before start ECU upgrade, must make certain that the battery of Tablet PC is sufficiently charged.

NOTICE

Prior to performing the ECU upgrade, be sure to check that the KDS is fully charged.

1. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.

NOTICE


The ECU upgrade function on KDS operates wirelessly. It is not necessary to perform the upgrade via USB cable.




2. With the ignition ON, turn ON the KDS tablet. Select 'KDS' from the home screen.



3. Confirm communication with VCI (A) and then configure the vehicle (B) using the 'AUTO VIN' (C) feature.



4. Select 'ECU Upgrade'.



SUBJECT: WIRELESS POWER CHARGER OPERATION LOGIC IMPROVEMENT (SA561)

- The KDS will check the server for recently uploaded Events and then automatically download Upgrade Event #726.

NOTICE

The vehicle must be identified in Vehicle Selection to download an Event for that vehicle.

After the download is complete, the program will shut down to install. Please wait until the program restarts.

| Event | Status |
|---|-------------|
| 271.QF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT | Downloading |
| 273.TF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT | Ready |

36%

Do not touch any system buttons while performing this function.

KDS screenshot shown above is for demonstration purposes only. Events shown in screenshot are not applicable to this bulletin.

- Select Auto Mode.

CAUTION

Do NOT attempt to perform a Manual Mode upgrade UNLESS Auto Mode fails. Always follow the instructions given on the KDS in either Auto or Manual mode.

Auto Mode Manual Mode

OTA management version update

- Select the 'WPC' system under the System selection menu.

Select 'TSB' (D) to confirm that the latest update is available (if applicable).

Select upgrade Event #726. MQ4a PE WPC Operation Logic Improvement and select 'Upgrade' to continue.

ECU Upgrade

SORENTO(MQ4A) > 2024 > G 2.5 T-GDI THETA III

System

WPC

TSB

726.MQ4a PE WPC operation logic improvement

MQ4a WPC +NFC : 95560-P2600

- The ECU upgrade will begin, and the progress of the upgrade will appear on the bar graph. Upgrade part (1/2) (E) will download the upgrade event to the VCI-II. Upgrade part (2/2) (F) will upgrade the ECU.

CAUTION

Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing ECU Upgrade.

E

23%

ECU Upgrading...(1/2)

ECU is in the process of being upgraded. Please wait a few minute.

F

6%

ECU Upgrading...(2/2)


ECU is in the process of being upgraded. Please wait a few minute.




- If a "Communication Fail" screen appears, verify that the VCI-II and KDS are communicating properly. Select 'OK' and restart the from step 4.

NOTICE


If an error notice continues to appear or if the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.




- When instructed on the KDS, turn the ignition OFF for ten (10) seconds then back on. Select 'OK' to continue.



- Once the upgrade is complete, select 'OK' to finalize the procedure.



- When prompted, select 'YES' to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.



- Start the vehicle and confirm the WPC is operating properly by placing a Qi compatible phone on the charging pad and confirm the charging indicator light illuminates.



Manual Upgrade Procedure:**NOTICE**

The manual upgrade should **ONLY** be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition 'OFF' for about 10 seconds then place it back in the 'ON' position to reset the control unit BEFORE performing manual upgrade.

See table below for 'Manual Mode' passwords.

Manual Mode ECU Upgrade Passwords

| Menu | Password |
|-----------------------------|----------|
| MQ4a WPC +NFC : 95560-P2600 | 2602 |

1. Within the ECU Upgrade screen displayed, select **Manual Mode**.
2. Select the **'WPC'** system under the System selection menu. Select **Upgrade Event #726** and select **Upgrade** to continue.
3. Select the appropriate control unit part number with reference to the ROM ID Information Table on page 3, and select **OK**.
4. Enter the appropriate password from the Manual Mode password table above and select **OK**.
5. The upgrade will begin and the progress of the upgrade will appear on the bar graph.
6. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Select **OK**.
7. Once the upgrade is complete, select **OK** to finalize the procedure.
8. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.
9. Start the engine to confirm proper operation of the vehicle.

SUBJECT: WIRELESS POWER CHARGER OPERATION LOGIC IMPROVEMENT (SA561)

AFFECTED VEHICLE RANGE:

| Model | Production Date Range |
|-------------------|---------------------------------------|
| Sorento (MQ4a PE) | December 7, 2023 to February 20, 2024 |

REQUIRED TOOL:

| Tool Name | Figure | Comments |
|-----------|---|-----------------------|
| KDS |  | Kia Diagnostic System |

WARRANTY INFORMATION:

N Code: N99 C Code: C99

| Claim Type | Causal P/N | Qty. | Repair Description | Labor Op Code | Op Time | Replacement P/N | Qty. |
|------------|-------------|------|--|---------------|------------|-----------------|------|
| V | 95560 P2500 | 0 | (SA563) Wireless Power Charger Logic Improvement | 240A13R0 | 0.3 M/H | N/A | 0 |

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA563 when accessing the KDealer+ system.

