

# 97 Radiator fans, alarm, wipers not working: P048000, P048100, U063200, U063300, U10F300, U10A300, P10EF00

97 24 07 2073305/1 March 9, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
Q7	2017 - 2023	<b>A</b> 11	Not Appliaghte	
SQ7	2020 - 2023	All	Not Applicable	

## Condition

### **Customer statement:**

The radiator fans run constantly.

#### OR

The windshield wipers do not work.

### Workshop findings:

One or more of the following DTCs may be logged as static or intermittent in the following control units:

### Engine electronics J623 (address word 0001):

P048000 Cooling Fan 1 Control Circuit
P048100 Cooling Fan 2 Control Circuit
P10EF00 Function limitation due to radiator fan failure
U063200 Lost Communication With Fan 1
U063300 Lost Communication With Fan 2

### Electronic central electrics J519 (address word 0009):

**U10A300** Wiper Motor Control Module, no communication

### Comfort module J393 (address word 0046):

U10F300: Alarm horn for anti-theft warning system no communication

### **Technical Background**

On vehicles manufactured within a specific period, wire damage/chaffing may occur on circuits routed through the plenum chamber. Sometimes, this damage may only be visible under the harness wrapping.

### Page 1 of 4

© 2024 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



# **Production Solution**

Optimized process.

# Service

### 

In rare cases, only a LIN DTC may be present for an affected circuit. This TSB applies if the affected system has a LIN wire which is routed through the plenum chamber.

- 1. Check the affected circuit for high resistance, open circuits ,and short circuits using a DVOM.
- 2. Moving/flexing the wiring harness throughout the plenum chamber will aid in locating the area of concern.
- Repair affected wires using wiring harness repair set VAS1978.



Figure 1. No external damage to the wiring harness can be seen.

Page 2 of 4

© 2024 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

- Wrap the repaired wiring harness using fabric adhesive tape N 10592002.
  - If the wire strands are not clean and shining, the wire MUST be cut back and lengthened as needed.




Figure 2. The damaged wire is only visible once the wrapping has been removed.

# Warranty

Claim Type:	• 110 Up to 48 Months/50,000 Miles.			
	<ul> <li>G10 for CPO Covered Vehicles – Verify Owner.</li> </ul>			
	<ul> <li>If the vehicle is outside of any warranty, this Technical Service Bullet informational only.</li> </ul>			
Service Number:	9713			
Damage Code:	0015			
Labor Operations:	Remove and install cowl panel trim	6644 1900	See SRT with associated operations	
	Check wiring harness	9709 0199	See SRT with associated operations	

© 2024 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



	Repair wiring harness (depending on number of defective wires)	9709 41xx	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2073305/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## **Required Parts and Tools**

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.			
Part Number	Part Description Quantity		
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA	
N 10592002	Cloth adhesive tape	.1	

Tool Number	Tool Description
VAS 1978 B	Wire harness repair set
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10)

# **Additional Information**

All parts and service references provided in this TSB (2073305) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

<sup>© 2024</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.