

<b>REFERENCE:</b>	<b>TSB:</b> 08-018-24 <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	January 13, 2024	<b>REVISION:</b>	-
<b>VEHICLES AFFECTED:</b>	<b>2022 (LX) Chrysler 300</b> This bulletin applies to vehicles equipped with a Deluxe Security Alarm (Sales Code LSD).			<b>MARKET APPLICABILITY:</b>	
				<input checked="" type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
<b>CUSTOMER SYMPTOM:</b>	<b>Customers may experience one or more of the following:</b> <ul style="list-style-type: none"> <li>Alarm going off randomly at night.</li> <li>Alarm going off at parking.</li> <li>Tilt function not working properly.</li> </ul>				
<b>CAUSE:</b>	<b>Intrusion Transceiver Module (ITM) Software.</b>				

**REPAIR SUMMARY:**

This bulletin involves performing a Restore Vehicle Configuration and updating the ITM with the latest available software.

**CLAIMS DATA:**

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-20-16-94	Module, Intrusion Transceiver - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	CC	Customer Concern	

**The dealer must use failure code CC with this Technical Service Bulletin.**

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

**SPECIAL TOOLS/EQUIPMENT:**

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

## REPAIR PROCEDURE:

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. Reprogram the ITM with the latest available software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Using the wiTECH, navigate to the Vehicle Preparations menu on the side bar under Activities.
3. Select and perform the routine "Restore Vehicle Configuration". Follow the on-screen instructions.
4. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.
5. Turn the ignition OFF and remove the key from the ignition.
6. Lock and close all doors to allow the Vehicle Theft Security System (VTSS) to go from pre-arm to armed status and then wait one minute before proceeding.
7. Disarm the VTSS.
8. Clear all DTCs that may have been set in the ITM.

## POLICY:

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*