



# Service Information

Offboard Diagnostic Information System Service (ODIS Service)

Number: VOS-24-21

Subject: ID.4 ECM Coding/Software Configuration Error - Hotfix Instructions

Date: Mar. 1, 2024

**Important:**

**We recommend installation of this hotfix on one diagnostic device ONLY. Hotfix must be removed immediately after performing the procedure.**

## 1.0 – Introduction

The hotfix applies to the **ID.4**:

**Control module coding/software configuration DA 0001 Engine electronics coding/software configuration NOT OK**

**After the DA 0019 replacement the ECM loses coding, fault code P064F00: Unauthorized Software/Calibration Detected**

**may remain active/static and will not clear.**

➤ **Additional instructions for the technician.**

With Hotfix installed, with the vehicle key placed at the reader coil antenna in center console. Under special functions, run Function clearing system (FES) choosing option to recreate / restore function on AW “0019”, then run test plan 0025 – VKMS adaptation. Once completed run ctrl module software configuration on AW “0001”. Verify the ECM is now coded, and static ECM faults will clear.

**!! The Hotfix must be removed after performing the diagnostic procedure. !!**



# Service Information

---

## 2.0 – Prerequisite

ODIS Service **Diagnostic Content version 2.49.6** must be installed.

To confirm the installed diagnostic content version in ODIS Service, go to: **Info > Versions**.

## 3.0 – Download Hotfix

1. Open a **Web Browser** on the diagnostic device and logon to **vwhub.com**
2. Navigate through **Elsa2Go>Service References>Software/Hardware Updates**
3. Search for **VOS-24-21 ID.4 ECM coding/software Zip File**
4. Click the **ID.4 ECM coding/software Zip File** and **Save** it to your Windows desktop.
5. Close your browser.


(continued)




# Service Information

Browse to the desktop and double-click the **ID.4 ECM coding/software Zip File** to open it.

6. Right click the file (example only) name and select **Copy**:



7. Right click anywhere on the Windows desktop and select **Paste**. This file icon (example) must appear on the desktop:




*(continued)*




# Service Information

## 4.0 – Install Hotfix into ODIS Service

1. Open ODIS Service (“Run as Administrator”)
2. Expand the **Data** submenu and click **Download** (under **Hotfix**):



3. Click **Continue**:




(continued)




# Service Information

4. A Directory Selection window will appear. Browse to and **highlight the Hotfix file**, then click **Select Folder**:



5. Click **OK**:



6. Perform the diagnostic procedure.

## ***Important:***

***The Hotfix must be removed after performing the procedure. Failure to do so will cause other vehicle diagnostics sessions to malfunction.***


(continued)




# Service Information

## 5.0 – Uninstall the Hotfix from ODIS Service

1. Select **Erase** (under Hotfix), then **Continue**:



2. Click **OK** and close ODIS Service:



**Please contact Diagnostic Tester Software Support by phone at 888-896-1298 or email [softwaresupport@vw.com](mailto:softwaresupport@vw.com) with any questions or concerns.**