

Subject:

CONNECTED VEHICLE SYMPTOM TROUBLESHOOTING

Service Alert No.: SA-017/24

Last Issued : 03/14/2024

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous SAs:	Date(s) Issued:				
SA-009/23	10/23/23, 08/28/23, 08/15/23, 07/05/23, 06/12/23, 05/24/23, 04/25/23, 03/28/23, 03/01/23 and 02/06				
SA-017/22	12/13/22, 10/10/22, 08/25/22, 05/06/22, 04/04/22				
SA-013/21	12/22/21, 10/13/21, 09/14/21, 05/11/21, 04/27/21, 03/15/21, 02/22/21, 02/08/21 and 02/02/2021				
SA-031/20	12/09/20,11/30/20, 11/06/20, 10/28/20, 06/16/20, 06/05/20, 06/01/20, 05/18/20, 04/14/2020, 04/02/20, 03/11/20 and 02/27/20				

APPLICABLE MODEL(S)/VINS:

2019-2024 Mazda3	2021-2023 CX-9	2024 CX-90
2020-2024 CX-30	2022-2023 MX-30	2024 MX-5
2021-2024 CX-5	2023-2024 CX-50	2025 CX-70

DESCRIPTION

Some customers may complain about any of the following:

- 1. Infotainment Center Display does not provide the Authorization Code (OTP) during the MyMazda App Connected Vehicle enrollment.
- 2. Remote function(s) inoperative.
 - Engine Start / Stop
 - Door Lock / Unlock
 - · Lights ON / OFF
 - Climate Control

3. MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\".

Page 1 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Index

- MAZDA CONNECT Indication
- Remote Engine Start Will Not Function
- · Remote Engine Start Function Will turn engine OFF
- Deactivation Mode

MAZDA CONNECT Indication

TAL Weaker 1 2 3 Downlid Radio com Nowl 93.1 JACK FM 93.1 JACK FM Want			
Indication	Explanation		
Mazda3, CX-30, CX-50, MX-30	Radio waves are not being received. Move to a location with good reception.		
	Weak reception.		
	Good Receptioin		
	Strong reception.		
	Currently conducting an operation check of the communication unit. If this condition continues, consult an Authorized Mazda Dealer.		
0	Currently conducting an operation check of the onboard communication unit. NOTE: Communication is not possible during this display.		
CX-5, CX-50, CX-9, MX-30 Mazda3, CX-30 built July 1, 2021 and later	The communication function is temporarily disabled due to infotainment system setting.		
	 No CV Contract Deactivation Mode Connected Service contract has ended 		

Page 2 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	(Subscription expired) • TCU has not been initialized, go to SA-004/21
Vehicles built before July 1, 2021	Customer deactivated Connected Services (Opt-Out) eMDCS Warranty Vehicle Inquiry will show Campaign CSP04 Status Open
CX-5, CX-50, CX-9, MX-30 Mazda3, CX-30 built July 1, 2021 and later Connected Services Disabled message appears at engine start up	Connected Services disabled (box unchecked) System Settings Language Gracenote Database Update Use Gracenote Database Album Art Connected Services Software Update System Information Enable Connected Services (box checked) to prevent message appearing at engine start up. System Settings Language Gracenote Database Update Use Gracenote Database Album Art Connected Services Software Update System Settings Language Connected Services Software Update System Information Note: If customer Opted-Out (CSP04), advise customer to keep Connected Services box checked. The vehicle will not transmit data.
Connected Vehicle Maintenance Mode	Connected Vehicle Maintenance Mode enabled. Go to MGSS SERVICE CAUTIONS FOR VEHICLES WITH TELEMATICS COMMUNICATION SYSTEM to disable Maintenance Mode.
to access this Embedded Communications Restricted mode to exit and return to normal system operation.	NOTE: Connected Vehicle Maintenance Mode is unnecessary if the customers vehicle is in Deactivation Mode .

Page 3 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Remote Engine Start Will Not Function under the following conditions

ltem	Condition			
1	Remote Engine Start function is not available on EV and PHEV (inline 4) models. See SA-038/23			
2	Vehicle battery voltage low			
3	Automatic Transmission shift position except "P"			
4	Vehicles equipped with manual transmission			
5	Vehicle speed above 3 mi/h (5 km/h)			
6	Brake pedal switch malfunction			
7	Engine has been running by remote engine start function			
8	Engine started by remote engine start more than 2 consecutive times while the vehicle is not driven. The vehicle must be driven 1-mile or 24-hours must pass from the last successful Remote Engine Start for the use count to reset.			
9	2021 Mazda3, 2021 CX-30, CX-50, MX-30: Vehicle's electrical control area network (CAN) is in "Sleep Mode"			
10	A registered key is detected in the vehicle			
11	Brake pedal switch detects brake application			
12	Low fuel warning			
13	Engine starts, then turns OFF due to abnormal high engine rpm detected. (Engine rotation over 3000 rpm continued for more than 0.2[s])			
	No engine rpm detected after sending engine start request. (Engine rotation 0 rpm continued for more than 0.2[s])			
15	When the CAN data signal for engine shut off is present (e.g.: door ajar signal)			
16	After 10 second maximum cranking time			
17	Burglar alarm status is "Alarm" and "Alarm stand by" (CAUTION - DO NOT enable, see Theft- Deterrent System section in SA-012/20)			
18	Room fuse blown/missing			
19	Connected Vehicle Maintenance Mode enabled (Restricted Transmitting Mode in MDARS)			

Page 4 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	Embedded Communications Restricted The embedded communication device and infotainment display functions have been restricted. After the diagnosis and/or repair is complete, utilize the same procedure used to access this Embedded Communications Restricted mode to exit and return to normal system operation.
	Vehicle is parked (stored) for approximately 1 week or longer or in deep sleep mode. Drive the vehicle for a few miles to recover.
21	DTC Stored
22	Aftermarket Remote Engine Start accessory installed.
	Mazda Remote Engine Start (BCKA-V7-620) accessory installed (No MyMazda app remote engine start function).
23	Mazda Remote Engine Start (RES) Removal a. Remove the Mazda Remote Engine Start (RES) accessory module. b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM- RELATED PARTS PROGRAMMING [(US)]
24	First remote control attempt fails, second attempt works fine. Go to TSB 16-002/20.
25	CSP04 Status Open

Remote Engine Start Function <u>Will</u> turn engine OFF under the following conditions

Item	Condition		
1	Vehicle door(s) opened		
2	Vehicle trunk opened		
3	Vehicle hood opened		
4	Ignition switch push button "ON" detected		
5	Remote engine STOP request		
6	Brake pedal switch detects brake application		
7	DTC Stored		
8	Engine will stop running automatically after 15 minutes for safety, security and emissions.		

Page 5 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Deactivation Mode

- Deactivation Mode Temporary Suspension 6/16/2023 (6/11/2023 retail date and later)
- Vehicles retailed before 6/11/2023 and in Deactivation Mode will remain in Deactivation mode.

NOTE:

- Customer/Dealer can activate CV services anytime via MyMazda app
 - Customer There might be a slight delay in making the backend connection since it was temporarily deactivated.
 - Dealer Go to Repair Procedure -> TCU Activation
- When TCU is in Deactivation Mode, infotainment Over-the-Air (OTA) Connectivity Master Unit (CMU) software
 update is not possible (disabled).
- Prior to Retail Date, the TCU is active.

Deactivation Mode Status Check:

		Reception Icon Shows normal strength
	TCU Active	FM Notation 1:2:3 Downlid Radio com Now/ 93.1 JACK FM 93.1 JACK FM - Playing What We Want
Infotainment Center Display	 TCU in Deactivation Mode No CV Contract One Time Passcode (OTP) is processing 	FM Notes 12.02 ///////////////////////////////////
		No CV Contract
Mazda Connected	TCU CV Contract Status 1. Go to Mazda	Login ID : Department : Name : DANIEL G Connected Vehicle Information Search Screen Not found Top Contract Reference Vehicle Status Reference Vehicle Communication Line Status Reference (UTC-07:00) Pacific Daylight Time Not found
Vehicle	Connected Vehicle	Search Condition
Viewer	Viewer (MCVV)	VIN JM3TCBEY0M0xxxxxxx
(MCVV)	2. Enter VIN and then select	Clear Customer First Customer Last Communication
	"Search"	Select VIN Customer First Customer Last Year and Model Body Color Line Status Warning Condition Monitor
		CV Contract Active

Page 6 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-017/24

	Cogin ID : digonzale Department : Name : DANIEL G	Top Contract Reference Vehicle Status Reference Vehicle Communication Line Status Reference		
	Ecosem	(UTC-07:00) Pacific Daylight Time 🔻		
	Connected Vehicle Information Search Screen			
	Search Condition VIN [7MJ/VABXY9PN1			
	VIN [7/M/VABXY9PN1 9 Search Clear			
	Ealers Visu Customer First Customer Last Verview Model Body Color	Communication Warning Condition Monitor		
	Select 7MMVABXY9PN1 DANIEL C MEDIDIAN ZIRCON SAND	Opened V		
	EDITION AWD METALLIC			
	1. Go to Mazda Connected Vehicle Viewer (MCVV)			
	Login ID : dgonzale Top Contract Reference Vehicle Status Ref Department : Name :	erence Vehicle Communication Line Status Reference (UTC-07:00) Pacific Daylight Time 💌		
	Connected Vehicle Information Search Screen			
	Search Condition			
	VIN Clear			
	Contemport Elect Constantiant I and Very and	Communicatio Unamine Condition		
	Select VIN Customer First Customer Last Tear and Body Color Name Model Body Color	n Line Status Warning Monitor		
	Back			
	2. Select "Vehicle Communication Line Status Reference			
	3. Enter VIN and then select "Search"			
	Login ID : diponzale Top Contract Reference Vehicle 5 Department : Name :	Ratus Reference Vehicle Communication Line Status Reference		
	Vehicle Communication Line Status Search Screen	7		
TCU Activation	Search Condition			
Status Check	VN Clear	/		
	VIN Vehicle Communication Line Status Yes	ar and Model Body Color		
	Status Request Date Status Detail			
	TCU in Deactivation Mode (Status	-> Closed)		
	Login ID : Top Contract Reference Vehicle macros	Status Reference Vehicle Communication Line Status Reference (UTC 47.00) Pacific Daylight Time		
	Vehicle Communication Line Status Search Screen			
	Search Condition VIN JA1094064P0			
	D fearch Clear			
	Vitik Vehicle Communication Line Status Vitik Status Request Date Status Detail	Year and Model Body Color		
	Direct China	WO W PREMUM PLUS MACHINE GRAY METALLIC		
	One Time Passcode (OTP) is processing (State	us -> Open Requested)		

Page 7 of 44


CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	Login ID : Department : Name :		Тор	Contract Reference	Vehicle Status Reference	Vehicle Communication Line Status Reference TC-07:00) Pacific Daylight Time
	Vehicle Communication Line Status Search Screen					
	Search Condition	mmyabay9	7			
		mmvacaya				
	P Search Clear					
	VIN	Vehicle Communica Status		itatus Detail	Year and Model	Body Color
	7MMVA8XY9	Open Requested			TURBO MERIDIAN EDITION	ZIRCON SAND METALLIC
						,
		TCU Activ	ve (Statu	ıs -> Ope	ned)	
	Cogin ID : Department : Name :		Top Contrac	ot Reference Vehi	ole Status Reference V	Ahicle Communication Line Status Reference
	mairoa				(UTC-47	.00) Pacific Daylight Time 🔹
	Vehicle Communication L	ine Status Search Screen				
	Search Condition					
	VN (#100,064%)					
	Disech Char					
	VIN	Vehicle Communici	the second s		Year and Model	Body Color
		Status	Request Date St.	tatus Detail		
	JANDRADBEPO	Opened	02/05/2023 C 18/25 0	Open Completed 2023 EV 10:05:2023 PKG 18:25	PWD W PREMUM PLUS	MACHINE GRAY METALLIC

REPAIR PROCEDURE

CAUTION: DO NOT swap TCU with another vehicle as the TCU is VIN locked after activation. A TCU swap with another vehicle will disable Connected Services on both vehicles.

Repair Flowchart



Page 8 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

↓	↓	↓
Check Campaign Status	Enrollment	Check Campaign Status
↓	↓	↓
Remote Function Troubleshooting	OTP Troubleshooting	Customer deactivate Connected Services (Opt-Out)
		No reception

PREPARATION:

1. Confirm that the Telematics Communication Unit (TCU) is at the latest software level. Go to Telematics Communication Unit (TCU) Updates

2. Go to eMDCS Vehicle Inquiry and confirm the following campains are not shown or closed:

- CSP06
- CSP07
- SSPC7
- DRW41

3. Go to eMDCS Vehicle Inquiry and confirm CSP04 is not shown.

4. If Hotline assistance is needed, please fill out the Dealer Connected Vehicle Questionnaire before contacting Hotline. The questionnaire collects data needed by Hotline agent.

5. In most cases, the customer will not leave their device with you for troubleshooting, therefore a connected vehicle take-over is necessary. Use your personal device or dealer supplied device for troubleshooting. Go to **Enrollment**.

• At customer pick-up, inform customer to re-enroll into Connected Services as a new primary user.

6. Confirm the customer's phone and vehicle have good to strong reception during the concern as shown in the table below.



• If the reception icon shows "X", the TCU is deactivated. Enrollment is not possible. Go to TCU Activation.



Page 9 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

- Customer/Dealer can activate CV services anytime via MyMazda app
 - Customer There might be a slight delay in making the backend connection since it was temporarily deactivated.
 - Dealer Go to TCU Activation
- If the reception icon shows " \ ", move the vehicle to an area with a clear view of the sky.



- If the reception is weak, move the vehicle to a location where the reception is good to strong as shown in the table, then try to get the Authorization Code and/or operate the remote functions before proceeding to the Repair Procedure if there is still an issue.
- If the reception is good to strong, proceed to Connected Vehicle Troubleshooting below.

NOTE: Vehicles stored for long periods may loose GPS clock sychronization. If the vehicle is stored for a long period, test drive the vehicle to give the GPS clock time to sychronize before enrolling or testing connected vehicle functions.


Index

- 1. Unable to create a MyMazda account
- 2. Remote function(s) inoperative
- 3. No One Time Pass Code (OTP)
- 4. Connected vehicle reception strength icon shows "X" or "\"
- 5. MyMazda App displays incorrect tire pressures (Except CX-5 and CX-9)
- 6. Unable to activate Connected Services (2019 Mazda3)
- 7. Software Update Error (2020 Mazda3)
- 8. Functions inoperative (2021-> CX-30, CX-50, Mazda3 and MX-30)
- 9. First remote control attempt fails, second attempt works fine
- 10. Engine turns off when opening door
- 11. Low Tire pressure will not clear after correcting tire pressue
- 12. MyMazda App does not display tire air pressures (CX-5, CX-9)
 - MCVV One Time Passcode (OTP) Troubleshooting
 - TCU Activation
 - Customer Opt-Out
 - Educational Videos
 - Resources

	Connected Vehicle Troubleshooting						
	Symptom	Action					
1			1. Text " Start " to 1-949 518-0058 (Twilio SMS for Mazda)				

Page 10 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 11 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

			Go to the MyMazda App INBOX -> ACTIVITY HISTORY -> to view reason for remote function failure.
	Check Campaign Status		6 7 7
		enabled (box -> System Set Services. System Settings Language (Use Caacenote Database (Ornected Service Software Hoterators) 2. Use MDAF check for DT stored? (Yes - 1 norma	abase Album Art

Page 12 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	 3. Confirm TCU software version. Go to Telematics Communication Unit (TCU) Updates 4. Disconnect battery for 30 seconds and then reconnect (KAM reset). NOTE: Test drive vehicle after battery disconnect to allow the GPS clock to sychronize before retrying Authorization Code. 5. Perform one of the following: Customer: Un-enroll Connected Services, then re-
	 enroll into Connected Services, ther re- enroll into Connected Services as a new primary user. Dealer: Perform customer take- over enrollment for test confirmation, then at customer pick-up, inform customer to re- enroll into Connected Services as a new primary user. Fill out Dealer Connected Vehicle Questionnaire
	7. Contact Hotline for additional technical support if needed.
Remote Climate Control only available on EV and PHEV	No action needed. See SA-038/23
Only a single remote request can be made per 60-second period	Customer needs to wait 60 seconds for the initial request cycle to be completed to make the second request.
Remote Transmitter Key(s) in the vehicle	Do not leave keys in vehicle.
1. Aftermarket Remote Engine Start accessory installed. 2. Mazda Remote Engine Start (BCKA-V7-620) accessory installed.	 Remove the aftermarket accessory. The customer can use either the Mazda Remote Engine Start accessory or the MyMazda app function. Cannot use both.
	Mazda Remote Engine Start (RES) Removal a. Remove the Mazda Remote Engine Start (RES) accessory module. b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)].


Page 13 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	TCU in "deep sleep" mode due to vehicle being parked for a long period.	Advise customer to drive the vehicle as normal (at least several miles) and the Connected Services should start working again.
	Low fuel	Advise customer that Remote Engine Start may start vehicle temporarily, but vehicle will turn off automatically when the fuel level is low to conserve the remaining fuel.
	Vehicle is equipped with Manual Transmission	Advise customer that vehicles with a manual transmission do not have the Remote Engine Start/Stop function capability.
	Engine started with key transmitter instead of MyMazda App.	Advise customer they will see an error message when attempting to make a Remote Engine Off request if they initially turned on vehicle with a physical key (instead of through their MyMazda app).
3	MGSS -> warranty Veh. Inq. 3. Update the Telematics Commu software version. Go to Telematic 4. 2019 Mazda3 only - Update the latest software version. Go to MGS 5. Check TCU activation status. a. Go to MAZDA CONNEC b. Select Entertainment c. Select Source List and th • FM • AM • SiriusXM d. Check the Connected Ve • Reception strength i active and ready for	/ Special Service Programs. Go to nication Unit (TCU) to the latest s Communication Unit (TCU) Updates. e Connectivity Master Unit (CMU) to the SS -> MAZDA CONNECT Updates.


Page 14 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.




Page 15 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 16 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 17 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Go to MCVV OTP Troubleshooting
2. Use MDARS to ID the vehicle and check for DTC's stored. Are DTC(s) stored?
 Yes - Go to MGSS and perform normal DTC diagnostics. No - Perform ODR Data Collection Procedure, then go to step 3.
 3. Confirm TCU software version. Go to Telematics Communication Unit (TCU) Updates 4. 2019 Mazda3 Only - Confirm CMU software version is at 11012 or later. 5. Retrieve MAZDA CONNECT CMU log data. Go to MGSS -> Infotainment
-> MAZDA CONNECT CMU Data Retrieval 6. Perform "Activating Remote Control by Smart Phone" (links TCU to BCM) 7. Clear DTC(s). NOTE: If DTC 2050:55 is stored, go to SA-003/20 to clear DTC. 8. Check TCU Remote Service Flag
 Information Remote Service Flag Information 1101 go to step 9. Remote Service Flag Information 0000 go to step 10.
 9. Disconnect 12V battery for 5-10 minutes, then retry connected vehicle enrollment. NOTE: Test drive vehicle after battery disconnect to allow the GPS clock to sychronize before retrying Authorization Code. 10. Fill out Dealer Connected Vehicle Questionnaire 11. Contact Hotline for additional technical support if needed.

Page 18 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

4 MAZDA CONNECT connected vehicle reception strength icon shows "X"	Deactivation Mode	Customer/Dealer can activate CV services anytime via MyMazda app • Customer - There might be a slight delay in making the backend connection since it was temporarily deactivated. • Dealer - Go to TCU Activation
connected vehicle services.	Customer deactivate Connected Services (Opt-Out))	 Go to eMDCS Vehicle Inquiry. Does eMDCS show CSP04 status closed? Yes - Customer opt-out. No action needed. No - CSP04 is not shown. Go to next Action below.
	No reception	 Check for DTCs. Are there any DTC's stored? Yes: Go to MGSS for normal DTC diagnosis. No: Go to next step. Confirm TCU software version. Go to Telematics Communication Unit (TCU) Updates 2019 Mazda3 Only - Confirm CMU software version is at 11012 or later. Disconnect battery terminal for 5-10 minutes, then test drive the vehicle. Is the reception strength signal normal? Yes: Repair complete. No: Go to next step. Perform TCU activation. Go to SA- 004/21. Is the reception strength signal normal? Yes: Repair complete. No: Go to next step. Compare Tel antenna No. 1 signal strength with good known vehicle near by. Go to DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)] Functional Inspection / Adjustment -> Navigation System Inspection

Page 19 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

			Good - Contact Hotline for technical support
5	Except CX-5 and CX-9 MAZDA CONNECT and/or MyMazda App displays incorrect tire pressures after battery disconnect and/or infotainment CMU software update.	Incorrect calendar entry (month/ day/year) after a battery disconnect or infotainment system software update.	Go to SA-002/21
6	 2019 Mazda3 only The customer is not able to activate Connected Services via the MyMazda app after CSP06 completion. MAZDA CONNECT connected vehicle reception strength icon is missing or shows unsubscribed after CSP06 completion. 	Improper telematics communication unit (TCU) software.	Go to CSP07 Repair instructions.

Page 20 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	10. detects 11 Construction Construction Static Child Paying their We from		
7	 2020 Mazda3 only Infotainment center display does not provide the Authorization Code Infotainment center display "Software Update Error" message 	Enrollment error	Go to SSPC1
8	 2021 Mazda3, CX-30, CX-50, and MX- 30 functions inoperative Vehicle Status Alert Remote Engine Start / Stop Remote Door Lock / Unlock Remote Hazard Lights ON / OFF Vehicle Finder (vehicle location mapping function is available) 	Vehicle's electrical control area network (CAN) is in "Sleep Mode"	ng f f f f f f f f f f f f f
9	 First remote control attempt fails, second attempt works fine. Engine Start / Stop Door Lock / Unlock Lights ON / OFF 	Improper telematics communication unit (TCU) software.	Go to TSB 16-002/20.
10	Engine turns off when customer	Normal Operation	Advise that, for customer's safety and

Page 21 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	opens vehicle door.		security, vehicle is designed to shut-off automatically when the vehicle door is opened.
11	 Low Tire pressure will not clear after correcting tire pressue. Vehicle status is inaccurate. 	MyMazda App is not real time.	 Customer must go to MyMazda app's Inbox and read/open all the messages related to the low tire pressure alert, then the "Low tire pressure" alert will clear from MyMazda app's Health Report Message will clear after next drive cycle.
12	CX-5, CX-9 The MyMazda App does not display tire air pressures	CX-5 and CX-9 Normal Operation	No action Needed

	_	Mazda Connected Vehicle Viewer (MCVV) One Time Passcode (OTP) Troubleshooting (Vehicles built after July 1, 2021 (20 TCU, AT&T)						
OTP Request		CVV Vehicle Communication Line Status Referent tatus	Next Step					
		New Vehicle Inventory (TCU no enrollment ever) Status: Opened Status Detail: Open Completed (with no date) Vehicle Communication Line Atatus Vehicle Communication Line Atatus Status Detail Opened Opened Opened Opened Opened		OTP request successful. If not, go to No One Time Passcode (OTP) -> OTP Troubleshooting -> Step 2.				
	2	Status: Open Requested		400S19				

Page 22 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 23 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


Service	Alert No.:	SA-017/24
---------	------------	-----------

	Status: Open Flag Setting Status Detail: Request Fa			IG-ON.
				If not:
	Status	Request Date	Status Detail	a. Disconnect 12V
6	Open Flag Setting Requested	10/12/2022 23:01	Request Failed 10/12/2022 23:51	battery 5-10 minutes, then
	10. Obtain : 1:3 1 2 2 3	1200.em NGC TM Wildt		b. go to No One Time Passcode (OTP) -> OTP
Π	Status: Open Flag Setting	Requested		Troubleshooting -
	Status Detail: Flag Setting			> Step 2.
	Vehicle Communic Status	ation Line Atatus Request Date	Status Detail	
7	Open Flag Setting Requested	10/12/2022 23:01	Flag Setting Failed 10/12/2022 23:51	
	10. (Mark + 2.)	12.00,ee Nort FM Weet		
Π	TCU has history of enrolln	nent		
	Status: Opened			
	Status Detail: Open Comp	pleted (with c	late)	
	Vehicle Communio Status	cation Line Atatus Request Date	Status Detail	OTP request successful.
8	Opened	10/12/2022 23:01	Open Completed 10/12/2022 23:51	If not, go to No One Time Passcode (OTP) -> OTP
	10. Quark + 2.3 Image: State of the state of t	12:00,em		Troubleshooting -> Step 2.

TCU Activation


Page 24 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 25 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 26 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

5. Select "SCAN VIN"	9:59 and S E2 C ADD VEHICLE C ADD
6. Select "SCAN" Note: You can also manually enter the VIN if preffered. Select "ENTER VIN"	9:59

Page 27 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

7. Select "NEXT"	10:00 Image: Second vision X SCAN VIN
8. Select "VALIDATE"	10:00

Page 28 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	10:01 .1 🕆 🖾
	< ADD VEHICLE
9. Select "NEXT"	Validate Your VIN VIN Validation Result Win Validation Result Available Available VIN: JM3KKDHC9R1 is available and Connected Services compatible. Tay Next' to input vehicle information. RETRY VALIDATE
10. Enter Vehicle Name and select local dealer. Then select "SUBMIT"	10:01 .nl < €0


Page 29 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

11. Select "ENROLL"	10:02 II < € 60 ADD VEHICLE VEHICLE NAME CX-90 'VIN JM3KKDHC9R1 Success Success You have successfully added your vehicle (VIN: JM3KKDHC9R1) and it is Connected Service compatible. Do you want to enroll now? Do you want to enroll now? ENROLL MUNTINGTON BEACH MAZDA 16600 Beach Bid., Huntington Beach, CA 92647 SUBMIT SUBMIT
12. Select "START"	10:02 III SE

Page 30 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 31 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

15. You will receive a message saying "Connectivity is Complete"; however, it is actually <u>not complete</u> . OK to close this window. Go to next step.	10:03 п1 Ф ЕЭ SELECT VEHICLE Connectivity is Complete 2024 CX-90 3.3 S PREM AWD JM3KKDHC9R1101223 Date 08/01/2023 Time 10:03 AM Details Connected Services enrollment.	
16. Turn the ignition OFF for 10 minutes or longer.	START STOP ENGINE	
17. Turn the ignition ON.	START STOP ENGINE	
18. Check the Connected Vehicle reception strength icon:		
 Reception strength icon shows normal strength. TCU is now active. Proceed to Enrollment. 	Donal Radio com Nowl 93.1 JACK PM 93.1 JACK FM - Playing What We Want	

Page 32 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


Reception strength icon shows "X". TCU activation is still processing. Repeat steps 16 -18.
Note:
This step may need to be repeated a few times until normal strength is shown.
If steps 16-18 was repeated several times with no change, disconnect 12V battery for 5-10 minutes, then recheck reception strength icon.

ODR Data Collection Procedure



Page 33 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 34 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-017/24	Last Issued : 03/14/2024

	Collecting d X	0	R VIN: JM3KFADM8M		R 🗰 14V 🚍	=
	Collecting diagnostic information					
	Collecting diagnostic information					
7. Wait for collection to complete.		47s				
					Next	
					Next	
	Quick Check X Toolbox A Collecting d++ X	0	🖨 VIN: JM3KFADM8M	<u>a</u> (6	1 14V	Ξ
	Collecting diagnostic information					
	Complete					
8. Confirm that the ODR collection has	Collecting diagnostic information succeeded.					
been successful. Select "Next" to exit.			-		Next)
					\smile	

Page 35 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-017/24	Last Issued : 03/14/2024
------------------------------	--------------------------

Activating Remote Control by Smart Phone (links TCU to BCM)

NOTE: This procedure cannot be performed if the key transmitter power saving function is enabled. See SA-040/20.

	Menchyne er lys Menchiel
	C b
	634 - X24
1. Connect MDARS.	21 F 36 61,600 60 60 60
	1004_91(1) 1004_91/2 20 HS 191 PM PM PM PG
	x x
	tas BTCs. 🚾 Communication Error 🔜 Na-Communication or Hot Equipped 🧰 CHCN even 🔤 BTC Hot Supported
 2. Use MDARS to verify if the Telematics Control U > Run > TCU). Is the TCU at the latest software level? 	nit (TCU) is at the latest software level (Toolbox > Software Update
 Yes: Go to step 3. No: Update TCU software, then go to step 3 	
3. Select the following: a. Toolbox b. Repair icon c. MAZDA CONNECT d. Activating Remote Control by Smart Phone e. RUN.	Tracking A<
4. Follow the on-screen instructions and wait for process to complete.	
NOTE: If the Activating Remote Control by Smart Phone shows "Incomplete", the possible causes are:	
a. The advanced key is not in the vehicle. b. The connected Vehicle Maintenance Mode is	

Page 36 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

enabled. c. The Key transmitter power saving function is enabled. d. The pacemaker radio wave interference prevention function is enabled.	Control by Smart Phone System is checking the correct ECU was installed. Process 1 Running 5%
	Next
	Activating Remote Control by Smart Phone Complete System checked the correct ECU was installed. Sent new TCU information to a control center. Please clear the DTC. After clear DTC, quick check will run automatically. Please confirm there is no DTC. Next
5. Select Quick Check (A), then start the engine and select the DTC Clear icon (B). CAUTION: If the engine is not started, DTC P2610 is stored and cannot be erased.	Active dependence and publication fails Active dependence and publication fails Active dependence and publication fails Active dependence and publications Active dependence and publications

TCU Software Version Check

1. Press and hold the Volume knob, then press and hold the Entertainment and Favorite buttons at the same time for 3-5 seconds and the Factory/ Service Inspection screen will appear.	CX-5 and CX-9	Except CX-5 and CX-9
---	---------------	----------------------

Page 37 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

2. Select Service Information.	Factory/Service Inspection Diagnostic Test Functional Inspection/Act Service Information Device Program Update End Diag Mode		
3. Select TCU Linked information.	Service Information Connected Device Information Backup Restore Personal Information Deletion TCU Linked Information		
 4. Scroll down to TCU Software Version and confirm the software version is up to date. Go to Telematics Communication Unit (TCU) Updates Is the TCU software version correct? Yes: TCU Software Version Check is complete. No: Go to Telematics Communication Unit (TCU) Updates to update the TCU software version. 	TCU Linked Information CMU Chip Serial No. TCU TEL Number TCU MEID TCU Software Version Connection Server Flag Information	: A E A I E Q A M F I : 5 2 5 6 2 0 1 3 2 0 : 3 5 7 6 9 1 0 9 9 5 7 2 3 2 : 00010020 (CX-5, CX-9) : 00010004 (Mazda3, CX-30) : Public Server : 1111	

TCU Remote Service Flag Information Check

1. Press and hold the Volume knob, then press and hold the Entertainment and Favorite buttons at the same time for 3-5 seconds and the Factory/Service Inspection screen will appear.	CX-5 and CX-9	Except CX-5 and CX-9
--	---------------	----------------------

Page 38 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		S/C	
2. Select Service Information.	Factory/Service Insp Diagnostic Test Functional Inspection Service Informatic Device Program Upd End Diag Mode	n/Adjustment on	
3. Select TCU Linked information.	Service Information Connected Device Info Backup Restore Personal Information TCU Linked Inform	Deletion	
	TCU Linked Informat		
	TCU MEID TCU Software Version	: 0001000	1
	Connection Server	: Public	Server
4. Scroll down to Remote Service Flag Information.	Flag Information	: 0 0 0 0	
Is the Remote Service Flag Information 1101 or	Remote Service Flag Info		1 - 1111 - 1111
0000?		: 11	
• 1101 - Disconnect 12V battery for 1 hour,		0	pr
then retry connected vehicle enrollment.	TCU Linked Informat		
• 0000 - Contact Hotline for technical support.	TCU MEID	: 0001000	1
	Connection Server	: Public	
	Flag Information	: 0 0 0 0	
	Remote Service Flag Info	ormation: 0000 - 000	00 - 0000 - 0000
		: 00	

Page 39 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-017/24	Last Issued : 03/14/2024
------------------------------	--------------------------

Customer Opt-Out

Some customers may request to stop data communication from their vehicle. Use this procedure to manually deactivate the TCU.




Page 40 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

		No - MCVV shows no customer enrollment Go to next step 3.	
3.	Enroll into Connected Vehicle services. Note: This step can be performed by dealer or customer.	 Go to Connected Vehicle Owner's Manual: Registering Vehicle Information Registering Connected Service After enrollment, go to step 4. 	
4	After enrollment, using the MyMazda App, delete VIN.	2:34 II C II C III C III BATTERY (BEV) 19 miles No Notifications STOP START CHARCE CHARCE C IIII C IIII C IIIII C IIIIII C IIIIIIIIII	
		a. From the main screen, select menu.	


Page 41 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 42 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Page 43 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Educational Videos

Overview Using MyMazda App In-car Wi-Fi hotspot MyMazda remote Notifications Saftey features

Resources Connected Vehicle Online Enrollment Information

- 1. Installing the MyMazda APP
- 2. Registering Your User Information
- 3. Registering Vehicle Information
- 4. Registering Connected Service

SA-015/23 - MAZDA CONNECTED SERVICES - FREQUENTLY ASKED QUESTIONS (FAQ)

Dealer Connected Vehicle Questionnaire Connected Services Owner's Manual MAZDA CONNECT and MAZDA CONNECTED SERVICES USER GUIDE MAZDA CONNECTED VEHICLE VIEWER (MCVV) USER GUIDE MAZDA CONNECT ESSENTIALS (30076WBT) MAZDA CONNECT & CONNECTED SERVICES FOCAL POINT (30093FOC) MAZDA CONNECTED SERVICES SMART CARDS MAZDA CONNECTED SERVICES: CUSTOMER OUTREACH

Page 44 of 44

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.