

## Field campaign

Topic	Pre Delivery Inspection (PDI) Coolant fan operation check (SC24/08)
Market area	United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2073357/3
Campaign number	ED01
Note	
Type	
US code	

## Vehicle data

### New Continental GT / GTC and New Flying Spur - W12 only

#### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2024	E		*	*	*
3S4*	2024	E		*	*	*
ZG2*	2024	E		*	*	*

#### Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SCB	*	*	*	R	C	012241	015388		

## Documents

Document name
master.xml
sc2408vinlist.pdf

---

## Notes

▼ [Repair instructions](#)

### Technical background

The correct operation of the cooling fan is required to be checked / confirmed

The coolant fan connector must be checked to confirm the connector is located correctly within the keeper, a further check is also required to confirm the coolant fan electrical connection is plugged in / connected

#### ⚠ DANGER

The radiator cooling fan can START at any time! SERIOUS injury can result! Do Not attempt to touch, rotate or spin the cooling fan

#### [Revision history - 2073357/3](#)

Checks have been added to confirm the coolant fan connector is located within the keeper, a further check is also required to confirm the coolant fan electrical connection is plugged in / connected

### Remedy

The instructions within the work section must be conducted during the Pre Delivery Inspection (PDI)

#### ⚠ DANGER

The radiator cooling fan can START at any time! SERIOUS injury can result! Do Not attempt to touch, rotate or spin the cooling fan

### Customer notification

The instructions within this Service Campaign should be conducted during the Pre Delivery Inspection (PDI)

Please inform your new and used car sales department, to ensure all vehicles are checked and repaired immediately

### Warranty accounting instructions

Warranty type 710 or 790

Damage service number ED01

Damage code 00 66

#### Time to conduct step 1

#### Labour

Labour Operation Code 97 09 01 01 (Use 99 index until 02/05/24)

Time 10 TU

#### Labour

#### Time to monitor the coolant temperature / fan operation

Labour Operation Code 01 50 00 00

Time As per the ODIS log (Must not exceed 30 TU)

#### Time to conduct the instructions provided by Product Support via the open DISS query (Cooling fan not spinning / operating)

#### ⓘ NOTICE

The Labour Operation code below must only be claimed if permission has been granted from Product Support via a technical DISS query

Labour Operation Code 01 51 00 00

Time As per the ODIS log (Must not exceed 50 TU)

### Genuine parts

Not applicable

### Parts supply

Not applicable

### Parts despatch control

Not applicable

## Repair instructions

▲ [Notes](#)

### Technical background

The correct operation of the cooling fan is required to be checked / confirmed

The coolant fan connector must be checked to confirm the connector is located correctly within the keeper, a further check is also required to confirm the coolant fan electrical connection is plugged in / connected

#### ⚠ DANGER

The radiator cooling fan can START at any time! SERIOUS injury can result! Do Not attempt to touch, rotate or spin the cooling fan

#### [Revision history - 2073357/3](#)

Checks have been added to confirm the coolant fan connector is located within the keeper, a further check is also required to confirm the coolant fan electrical connection is plugged in / connected

### Check

If the vehicle is not already listed as repaired in the 'Repair history' section of Elsa Pro, check for the presence of the applicable paint completion mark (depending on scenario) as detailed within the identification section

In the event the campaign has not been applied, please carry out the required work in accordance with these instructions

### Genuine parts

Not applicable

### Work

**⚠ DANGER**

The radiator cooling fans can START at any time! SERIOUS injury can result! Do Not attempt to touch, rotate or spin the cooling fan

**ⓘ NOTICE**

Ensure the vehicle is parked in a well ventilated area

**ⓘ NOTICE**

Ensure suitable exhaust extraction is fitted to the vehicle

**ⓘ NOTICE**

Ensure the vehicle is not parked in an area which is close to flammable materials

**⚠ CAUTION**

Before starting this procedure the engine coolant must be cold (ambient temperature)

1) With the ignition switched off - Check the coolant fan connector is located correctly within the keeper as shown in Figure 1



Hint: Figure 2 shows the connector not located correctly within the keeper, in this scenario the connector must be fitted into the keeper as shown in Figure 1




Figure 1




Figure 2



In the event the connector was not located within the keeper please raise a technical DISS query ensuring a photograph of the issue is attached

- Referring to Figure 3 - Check the coolant fan electrical connection is plugged in / connected



Figure 3



In the event the coolant fan electrical connection was not plugged in / not connected please raise a technical DISS query ensuring a photograph of the issue is attached - Continue with all remaining instructions

2) Connect a suitable 12 volt battery charger to the vehicle - Refer to Rep.Gr 27

- Connect a suitable diagnostic machine to the vehicle
- Carry out a Guided Fault Finding check (GFF)

3) Referring to Figure 4 - Select A/C MAX as shown



Figure 4

- Select the Measured values shown in Figure 5 - IDE00025 - IDE04083 and IDE00380
- Allow the engine to idle until the coolant temperature (IDE00025) is between 90 and 93 Degrees Celsius (Point A)

Read measured values

Measured value name	ID	Value
▼ Coolant temperature	IDE00025	92 °C
---	MAS00184	
▼ Coolant temperatures	IDE04083	
▼ Supported measurement values	MAS03306	
Coolant temperature sensor 1	MAS03426	installed
Coolant temperature sensor 2	MAS03427	installed
Coolant temperature sensor 1	MAS03426	91 °C
Coolant temperature sensor 2	MAS03427	91 °C
▼ Coolant fan 1, activation	IDE00380	
---	MAS00194	38.27 %

Point A is indicated by a red arrow pointing to the 92 °C value for IDE00025. Point B is indicated by a red arrow pointing to the 38.27 % value for IDE00380.

Figure 5

- Referring to (Point B) the operative should monitor (IDE00380) Coolant fan 1, activation

**NOTICE**  
The Coolant fan 1, activation should be a minimum of 15%

**DANGER**  
The radiator cooling fans can START at any time! SERIOUS injury can result! Do Not attempt to touch, rotate or spin the cooling fan

4) Referring to Figure 6 (Rear of radiator cowl) - Whilst the engine running - Visually check the cooling fan is spinning / operating

**NOTICE**  
Whilst the engine is running the operative should observe the operation of the fan for a total of 60 seconds Hint: The fan will start and stop depending on engine coolant temperature



Figure 6

**Question:**

Is the fan spinning / operating whilst the engine is running?

**Yes the fan is spinning / operating whilst the engine is running** - Apply a yellow paint completion mark on the radiator top hose (Figure 7) no further action is required

**Hint:** The yellow paint mark also confirms step 1 was conducted




Figure 7

Or

**No the fan is not spinning / operating whilst the engine is running** - Conduct the remaining steps to completion

- 5) Switch off the engine immediately and allow the engine to cool down
- 6) Raise a technical DISS query ensuring the following is attached:
  - Clear video showing the fan is not spinning / operating
  - Clear video showing the requested ODIS Measured values
  - Diagnostic log (saved online) which includes all of the requested Measured values (Figure 5)

**NOTICE**  
**IMPORTANT NOTE TO PRODUCT SUPPORT ON RECEIPT OF A QUALIFYING DISS QUERY:**

**The DISS query MUST be second levelled to the Powertrain Senior Engineer, please wait for a response from the Powertrain Senior Engineer before responding to the retailer operative**

- 7) Conduct the repair instructions (once received from Product Support via the open DISS query)
- 8) Confirm the fan is spinning / operating to specification whilst the engine is running - Repeat steps 2,3 and 4
- 9) Apply a red paint completion mark on the radiator top hose (Figure 8)

Hint: The red paint mark also confirms step 1 was conducted



Figure 8

#### Identification

Yellow paint completion mark on the radiator top hose confirms the fan is spinning / operating (Figure 7)

Red paint completion mark on the radiator top hose confirms the initial fan operation check and the software update were both conducted (Figure 8)

## INTERNAL

SCBDG4ZG5RC012180	SCBDT4ZG3RC014201	SCBDT4ZG5RC014524	SCBDT4ZG2RC014769	SCBDT4ZG2RC015064
SCBDG4ZG1RC012239	SCBBB6ZG0RC014209	SCBBB6ZG7RC014532	SCBBB6ZG5RC014772	SCBCT2ZGXRC015068
SCBCT2ZG5RC012241	SCBCT2ZG9RC014221	SCBDT4ZGXRC014535	SCBBB6ZG0RC014775	SCBDT4ZG2RC015081
SCBCG2ZG1RC012273	SCBCT2ZG8RC014226	SCBCT2ZG1RC014536	SCBCT2ZGXRC014776	SCBBB6ZG7RC015082
SCBBB6ZG7RC012487	SCBDG4ZG8RC014229	SCBDT4ZG9RC014543	SCBDT4ZG6RC014791	SCBDT4ZG8RC015098
SCBDT4ZG0RC012535	SCBCT2ZG1RC014231	SCBCT2ZG0RC014544	SCBCT2ZG8RC014792	SCBDT4ZG6RC015116
SCBCT2ZG8RC012542	SCBCG2ZG1RC014234	SCBDG4ZG9RC014546	SCBCG2ZG6RC014794	SCBDT4ZG8RC015120
SCBDG4ZG1RC012970	SCBDG4ZG7RC014240	SCBBB6ZG9RC014547	SCBCT2ZG5RC014801	SCBDT4ZG5RC015124
SCBDT4ZG6RC013057	SCBDT4ZG5RC014247	SCBCT2ZG8RC014548	SCBDT4ZG1RC014813	SCBDT4ZG2RC015128
SCBBB6ZG1RC013103	SCBDG4ZG3RC014252	SCBDT4ZG6RC014550	SCBDT4ZG9RC014817	SCBBB6ZG5RC015131
SCBBB6ZG6RC013176	SCBCG2ZG9RC014255	SCBDT4ZG0RC014558	SCBCG2ZG9RC014823	SCBDT4ZG4RC015132
SCBDT4ZG3RC013372	SCBCT2ZG6RC014306	SCBCT2ZG9RC014560	SCBCG2ZG2RC014825	SCBBB6ZG2RC015135
SCBBB6ZG2RC013384	SCBDG4ZG5RC014320	SCBBB6ZG8RC014569	SCBBB6ZG8RC014829	SCBCT2ZG5RC015138
SCBBB6ZG4RC013550	SCBCT2ZG1RC014326	SCBCT2ZG7RC014573	SCBDT4ZG1RC014844	SCBDT4ZG3RC015140
SCBCT2ZG0RC013569	SCBDT4ZG5RC014328	SCBBB6ZG7RC014577	SCBBB6ZGXRC014847	SCBBB6ZG8RC015141
SCBDG4ZG8RC013601	SCBCG2ZG3RC014333	SCBBB6ZG0RC014579	SCBCT2ZG2RC014853	SCBDG4ZG7RC015145
SCBDT4ZG4RC013686	SCBCT2ZG7RC014346	SCBCG2ZGXRC014586	SCBCT2ZGXRC014860	SCBCT2ZG6RC015147
SCBCT2ZG9RC013750	SCBDG4ZG7RC014349	SCBDT4ZG6RC014595	SCBBB6ZG4RC014861	SCBDT4ZG6RC015150
SCBCT2ZG9RC013764	SCBCT2ZG5RC014359	SCBDG4ZG6RC014603	SCBDG4ZG8RC014862	SCBDT4ZG0RC015158
SCBCT2ZG8RC013870	SCBCT2ZG6RC014368	SCBCG2ZGXRC014605	SCBBB6ZGXRC014864	SCBCT2ZG9RC015160
SCBBB6ZG9RC013883	SCBDT4ZG8RC014369	SCBDG4ZG3RC014607	SCBBB6ZG3RC014866	SCBDT4ZG5RC015172
SCBDT4ZG5RC013888	SCBDT4ZGXRC014373	SCBCT2ZG9RC014610	SCBCT2ZG2RC014867	SCBCT2ZG4RC015177
SCBCT2ZG6RC013897	SCBCG2ZG5RC014379	SCBDG4ZG5RC014611	SCBDT4ZG6RC014869	SCBCT2ZG8RC015179
SCBDT4ZG6RC013902	SCBDT4ZG9RC014381	SCBCG2ZG0RC014614	SCBDT4ZG3RC014876	SCBDT4ZG4RC015180
SCBDG4ZG3RC013912	SCBDG4ZG0RC014385	SCBCT2ZG4RC014630	SCBBB6ZG1RC014882	SCBBB6ZG0RC015182
SCBCT2ZG2RC013914	SCBCT2ZG8RC014386	SCBDT4ZG9RC014641	SCBDT4ZG5RC014894	SCBCT2ZGXRC015183
SCBCT2ZGXRC013918	SCBDT4ZG5RC014393	SCBBB6ZG7RC014644	SCBCG2ZG0RC014905	SCBDT4ZG1RC015184
SCBDG4ZG9RC013932	SCBCT2ZG0RC014396	SCBCT2ZG3RC014649	SCBCT2ZG3RC014909	SCBDT4ZG0RC015189
SCBCG2ZG6RC013953	SCBDT4ZG6RC014399	SCBBB6ZG6RC014652	SCBDT4ZG1RC014911	SCBBB6ZG7RC015194
SCBDT4ZG4RC013994	SCBCG2ZG3RC014400	SCBDG4ZGXRC014653	SCBCT2ZGXRC014924	SCBDT4ZG5RC015205
SCBCG2ZG2RC013996	SCBCG2ZG9RC014403	SCBDT4ZG2RC014657	SCBDT4ZG3RC014926	SCBDT4ZG0RC015208
SCBCT2ZG4RC014000	SCBDT4ZG6RC014404	SCBCT2ZG6RC014659	SCBBB6ZG8RC014927	SCBDT4ZG9RC015224
SCBDG4ZG4RC014003	SCBCT2ZG3RC014408	SCBDT4ZG4RC014661	SCBDT4ZG2RC014934	SCBBB6ZG3RC015225
SCBDT4ZG6RC014015	SCBCT2ZG5RC014412	SCBCT2ZG1RC014665	SCBCT2ZG8RC014940	SCBDG4ZG9RC015227
SCBCT2ZG8RC014016	SCBDT4ZG4RC014417	SCBDT4ZG5RC014667	SCBCT2ZG5RC014944	SCBBB6ZG9RC015231
SCBDG4ZG6RC014018	SCBDT4ZG4RC014420	SCBDT4ZG4RC014675	SCBDT4ZG9RC014946	SCBCT2ZG8RC015232
SCBCT2ZG7RC014024	SCBDT4ZG1RC014424	SCBCT2ZG8RC014677	SCBCT2ZG2RC014948	SCBBB6ZG4RC015248
SCBDT4ZG8RC014033	SCBDT4ZG9RC014431	SCBDT4ZG1RC014679	SCBBB6ZG8RC014958	SCBDT4ZG3RC015249
SCBDT4ZG5RC014037	SCBCT2ZG9RC014445	SCBDG4ZG8RC014683	SCBDT4ZG7RC014959	SCBDT4ZG8RC015263
SCBCT2ZG6RC014063	SCBDT4ZG7RC014458	SCBBB6ZGXRC014685	SCBCT2ZG4RC014966	SCBBB6ZG2RC015264
SCBCT2ZGXRC014065	SCBDG4ZG7RC014464	SCBDT4ZG4RC014692	SCBBB6ZG9RC014967	SCBDG4ZG3RC015272
SCBDT4ZG5RC014071	SCBDT4ZG8RC014467	SCBBB6ZG2RC014695	SCBCT2ZG6RC014970	SCBBB6ZG0RC015277
SCBDT4ZG4RC014076	SCBDT4ZGXRC014471	SCBCT2ZG5RC014698	SCBDG4ZGXRC014989	SCBDG4ZG2RC015280
SCBDT4ZG0RC014107	SCBCT2ZG0RC014477	SCBDG4ZG3RC014705	SCBDT4ZG4RC014997	SCBCT2ZG3RC015283
SCBDT4ZG2RC014111	SCBCT2ZG7RC014489	SCBCT2ZG2RC014707	SCBCG2ZG2RC014999	SCBDT4ZG5RC015284
SCBCT2ZG8RC014114	SCBDT4ZG5RC014491	SCBDT4ZGXRC014714	SCBBB6ZG5RC015002	SCBBB6ZG9RC015293
SCBDG4ZG2RC014128	SCBBB6ZGXRC014492	SCBBB6ZG6RC014716	SCBBB6ZG8RC015009	SCBCT2ZG5RC015298
SCBDT4ZG3RC014134	SCBBB6ZG3RC014494	SCBCT2ZG2RC014724	SCBCT2ZG5RC015012	SCBDG4ZG4RC015300
SCBDT4ZG9RC014137	SCBBB6ZG5RC014495	SCBBB6ZG7RC014725	SCBBB6ZG5RC015016	SCBCT2ZG3RC015302
SCBCG2ZG3RC014140	SCBBB6ZG9RC014497	SCBBB6ZG2RC014731	SCBDT4ZG8RC015019	SCBBB6ZG8RC015303
SCBDT4ZG0RC014141	SCBBB6ZG5RC014500	SCBCT2ZG6RC014743	SCBCT2ZG8RC015022	SCBDT4ZG6RC015312
SCBDT4ZGXRC014146	SCBBB6ZG9RC014502	SCBBB6ZG0RC014744	SCBDG4ZG4RC015023	SCBCT2ZGXRC015314
SCBDT4ZG0RC014155	SCBBB6ZG0RC014503	SCBCT2ZGXRC014745	SCBCT2ZG1RC015024	SCBBB6ZG1RC015319
SCBDT4ZG6RC014161	SCBDT4ZGXRC014504	SCBDT4ZG1RC014746	SCBDG4ZG1RC015027	SCBDT4ZG7RC015321
SCBCG2ZG8RC014165	SCBBB6ZG4RC014505	SCBDT4ZG7RC014752	SCBBB6ZG3RC015032	SCBDT4ZG5RC015334
SCBDT4ZG5RC014166	SCBBB6ZG8RC014507	SCBDT4ZG4RC014756	SCBBB6ZG7RC015034	SCBDT4ZG4RC015342
SCBDT4ZG7RC014170	SCBBB6ZG8RC014510	SCBBB6ZG2RC014759	SCBCT2ZG6RC015035	SCBBB6ZG6RC015347
SCBDT4ZG3RC014179	SCBBB6ZG1RC014512	SCBDT4ZG6RC014760	SCBCG2ZG7RC015050	SCBBB6ZG8RC015348
SCBDT4ZG0RC014186	SCBCT2ZG6RC014516	SCBCT2ZG8RC014761	SCBDG4ZG8RC015056	SCBDT4ZG8RC015358
SCBCT2ZG4RC014188	SCBBB6ZG0RC014520	SCBDT4ZG5RC014765	SCBCG2ZG1RC015061	SCBCT2ZG6RC015388
SCBCG2ZGXRC014197	SCBCG2ZG6RC014522	SCBCT2ZG9RC014767	SCBCT2ZG0RC015063	