



Technical Service Bulletin

91 ConBox: Wireless Audi Smartphone Interface (CarPlay / AndroidAuto) inop

91 24 95 2073333/3 April 4, 2024. Supersedes Technical Service Bulletin Group 91 number 24-88 dated March 22, 2024 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5, RS 5 Sportback, A6, A6 allroad, S6, RS 6 Avant, A7, S7, RS 7, A8, S8, e-tron GT, RS e-tron GT, Q7, SQ7, Q8, SQ8, RS Q8, Q8 e-tron, Q8 Sportback e-tron, SQ8 e-tron, SQ8 Sportback e-tron	2024	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Service</i> (added additional steps) Revised <i>Warranty</i> (updated labor ops)
2	02/22/2024	Revised <i>Service</i> (added bus sleep cycle)
1	03/12/2024	Initial publication

Customer states:

- The Audi Smartphone Interface [ASI] (Apple CarPlay [ACP] / AndroidAuto [AA]) cannot be paired to the phone wirelessly.
- The phone tiles under the ASI menu are grayed out (see Figure 1).



Technical Service Bulletin



Figure 1: wASI connections grayed out.

- When using a wired ASI connection, the system works as expected.
- The 5GHz Wi-Fi network is not broadcast by the vehicle.

Workshop findings:

- No Relevant DTCs are stored.

Technical Background

The wireless Audi Smartphone Interface requires the 5GHz Wi-Fi network in the vehicle to communicate and stream its content from the phone to the MMI.

Due to a configuration issue, the 5GHz Wi-Fi may not be available in some vehicles, preventing wASI from functioning.


A wired Audi Smartphone Interface connection is not affected by this issue.

Production Solution

Not applicable.

Service

1. Please execute the “*Check control module configuration*” test plan under Guided Functions for the Emergency Call Module and Communication Unit (ConBox) -J949- (address word 0075).



Technical Service Bulletin

2. Delete all Audi Smartphone Interface (ASI) connections from the vehicle.
3. After a bus sleep cycle, the correct functionality should be reestablished.

NOTICE
Parts replacement does not solve this issue. Claims for replaced parts will be subject to review.

Warranty

Claim Type:	<ul style="list-style-type: none"> 110 Up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	9145		
Damage Code:	AC39		
Diagnostic Time:	GFF	0150 0010	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol (Max 75 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2073333/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2073333**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or



Technical Service Bulletin

transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.