

TECHNICAL SERVICE BULLETIN Slipping, Harsh Engagement, Various Diagnostic Trouble Codes (DTCs) Built On Or Before 20-Dec-2021

24-2092

11 April 2024

This bulletin supersedes 22-2281. Reason for update: revised part list

Model:

	8F35 transmission		
2019-2021 Transit Connect	Built on or before 20-Dec-2021		

Issue: Some 2019-2021 Transit Connect vehicles built on or before 20-Dec-2021 and equipped with the 8F35 transmission may exhibit transmission slipping concerns, harsh engagements and various clutch <u>DTC</u>s. Some vehicles may also have torque converter clutch <u>DTC</u>s. This may be due to worn needle bearings in the output planet carrier assembly. To correct the condition, follow the Service Procedure to overhaul the transmission and replace the planetary gearset.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2019-2021 Transit Connect
- Built on or before 20-Dec-2021
- 8F35 transmission
- · Clutch DTCs, transmission slipping and harsh engagements

Parts

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description	
JM5Z-7N473- C	1	1	1	Output Planetary Carrier	
JM5Z-7153-D	1	1	1	Overhaul Seal Kit	
JM5Z-7A019- A	1	1	1	Output Planetary Sun Shell	
CCPZ-3B477- G	2	2	1	Axle Wheel Hub Nut	
W520203- S442	2	1	4	Tie Rod Nut	
W520515- S442	2	1	4	Ball Joint Nut	
W719924- S439	2	1	4	Ball Joint Bolt	
W715618- S437	4	1	4	Torque Converter Nut	
W717349- S442	1	1	4	Roll Restrictor Bolt	
W500545- S900	1	1	4	Roll Restrictor Bolt	
AE5Z-4B422- A	2	2	1	Axle Retaining Circlip	
YS4Z-3N324- AA	1	1	1	Right Halfshaft Retaining Strap	

W520102- S442	2	1	4	Right Halfshaft Retaining Strap Nut	
JM5Z-7B164- A	5	5	1	Clutch Plate	
JM5Z-7B442- E	5	5	1	Clutch Plate	
9L8Z-7G100- B	1	1	1	Manual Shaft Roll Pin	
JM5Z-7G100- B	As Needed	As Needed	1	Roll Pin - Park Pawl Guide	
JM5Z-7G007- A	As Needed	As Needed	1	Solenoid Retainer Clip	
TA-29	As Needed	As Needed		Motorcraft® Ultra Silicone Sealant	
ZC-30-A	As Needed	As Needed		Motorcraft® Gasket Remover	
ZC-31-B	As Needed	As Needed		Motorcraft® Metal Surface Prep Wipes	
PM-4-A	As Needed	As Needed		Motorcraft® Metal Brake Parts Cleaner (Compliant With Low Volatile Organic Compound Requirements As Required In Some USA States)	
PM-4-B	As Needed	As Needed		Motorcraft® Metal Brake Parts Cleaner (Not Compliant With Volatile Organic Compound Requirements)	
VC-13-G	As Needed	As Needed		Motorcraft® Yellow Concentrated Antifreeze/Coolant (All Markets Except Canada)	
CVC-13-G	As Needed	As Needed	Motorcraft® Yellow Concentrated Antifreeze/Coolant (Canada Only)		
VC-13DL-G	As Needed	As Needed	Motorcraft® Yellow Prediluted Antifreeze/Coolant (All Markets Except Canada)		
CVC-13DL-G	As Needed	As Needed	Motorcraft® Yellow Prediluted Antifreeze/Coolant (Canada Only)		
XT-12-QULV	As Needed	As Needed		Motorcraft® MERCON® ULV Automatic Transmission Fluid	

Parts - Parts To Inspect And Replace Only If Necessary

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description	Note
9L8Z-7L027- A	Only If Necessary	Only If Necessary	1	Magnet	Do not replace the baffle assembly if only the magnet needs to be replaced
JM5Z- 7A103-D	Only If Necessary	Only If Necessary	1	Transmission Fluid Pump	
JM5Z-7902- S	Only If Necessary	Only If Necessary	1	Torque Converter (2.0L)	
JX6Z-7H322- A	Only If Necessary	Only If Necessary	1	Coolant Bypass Valve	

Claim Quantity refers to the total number of individual pieces required to repair the vehicle.

Package Order Quantity refers to the amount of the service part number package(s) required to repair the vehicle.

Number In Package refers to the number of individual pieces included in a service part number package.

As Needed indicates the amount of the part may vary and/or is not a whole number. Parts can be billed out as non-whole numbers, including less than 1.

Only If Necessary indicates the part is not mandatory.

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2019-2021 Transit Connect 2.0L Duratec: Retrieve DTCs, Inspect And Overhaul Transmission Following The Service Procedure Includes Time To Back-Flush Fluid Cooler And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	242092A	16.4 Hrs.
2019-2021 Transit Connect 2.0L Duratec: Retrieve DTCs, Inspect And Overhaul Transmission Following The Service Procedure Includes Time To Back-Flush Fluid Cooler, Flush The Torque Converter And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	242092B	17.5 Hrs.

Repair/Claim Coding

Causal Part:	7N473	
Condition Code:	D4	

Service Procedure

- Connect the appropriate diagnostic scan tool to the <u>DLC</u>. Retrieve and record all <u>DTC</u>s.
- **2.** Were any of following <u>DTC</u>s retrieved: P0730, P0757, P2701, P0752, P2700, P0771, P2704, P0751, P0756, P2700, P2701, P0727, P0741 and/or P1744?
 - (1). Yes proceed to Step 3.
 - (2). No this article does not apply. Refer to WSM, Section 307-01 for normal diagnostics.
- 3. Remove the transmission. Refer to WSM, Section 307-01.
- 4. Overhaul the transmission utilizing the updated output planet carrier assembly. Refer to WSM, Section 307-01.
 - (1). The service overhaul seal kit contains seals and gaskets. Match all of the removed seals and gaskets. Some seals and gaskets in the kit will not be required for certain models. Discard any unused components.
 - (2). Clean all of the internal components thoroughly. Replace any friction material which may have embedded metal pieces.
- 5. Were any of the following torque converter <u>DTC</u>s retrieved during Step 1: P0741, P1741, P1744, P1743?
 - (1). Yes proceed to Step 6.
 - (2). No proceed to Step 7.
- 6. Inspect the pump stator to input shaft bushing. Is the bushing worn?
 - (1). Yes replace the transmission fluid pump and the torque converter. Refer to <u>WSM</u>, Section 307-01. Proceed to Step 8.
 - (2). No reuse the transmission fluid pump. Proceed to Step 7.
- 7. Perform the torque converter flush and cleaning procedure. Refer to WSM, Section 307-01.
- 8. Disassemble and clean the main control valve body. Refer to WSM, Section 307-01.
 - (1). If the transmission had any burnt clutch material, thoroughly inspect and verify the controlling <u>CIDAS</u> valves and torque converter control valves move freely.
- 9. Perform a transmission fluid cooler back-flush and cleaning. Refer to WSM, Section 307-01.
- **10.** Reinstall the transmission. Refer to <u>WSM</u>, Section 307-01.
- 11. Reprogram the PCM using the latest software level of the FDRS scan tool.

NOTE: Advise the customer this vehicle is equipped with an adaptive transmission shift strategy which allows the vehicle's computer to learn the transmission's unique parameters and improve shift quality. When the adaptive strategy is reset, the computer will begin a relearning process. This relearning process may result in firmer than normal upshifts and downshifts for several days.

© 2024 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.