

TECHNICAL SERVICE BULLETIN

24-2104

10 April 2024

Sta-Bar Disconnect Service Required Message In The Instrument Panel Cluster, With DTCs C103A, C1A99, C1B03, C1B07, C1B14 And/Or B1A67

This bulletin supersedes 23-2400. Reason for update: to update the Parts List

Model:

Ford 2021-2023 Bronco

Markets: Published by Ford North America

Issue: Some 2021-2023 Bronco vehicles may encounter a **Sta-bar Disconnect Service Required** message in the <u>IPC</u> and an illuminated warning light with any of the following <u>DTCs</u> stored in the <u>CHCM</u>: C103A, C1A99, C1B03, C1B07, C1B14 and/or B1A67. To correct the condition, follow the Service Procedure to address water intrusion and reprogram the <u>CHCM</u> using the latest software version of the <u>FDRS</u> scan tool.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2021-2023 Bronco
- Equipped with a factory front stabilizer bar disconnect
- Sta-bar Disconnect Service Required message in the IPC
- Any of the following DTC stored in the CHCM: C103A, C1A99, C1B03, C1B07, C1B14 and/or B1A67

Parts

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description
MB3Z-5482-X	1	1	1	Front Stabilizer Bar Disconnect
NB3Z-5482-B	1	1	1	3.0L Front Stabilizer Bar Disconnect
W720940-S440	4	1	4	Front Stabilizer Bar Nut
W520214-S440	2	1	2	Stabilizer Bar Mounting Nut
W721449-S439	2	1	4	Stabilizer Bar Mounting Bolt
W721041-S439	2	1	4	Stabilizer Bar Mounting Stud
MB3Z-2B325-EM	1	1	1	Wire Harness - Stabilizer Bar Disconnect
MB3Z-2B325-B	1	1	1	3.0L Wire Harness - Stabilizer Bar Disconnect
MB3Z-2B325-EL	1	1	1	Wire Harness - Body
W717376-S439B	4	1	4	Skid Plate Bolts

Parts - Parts To Inspect And Replace Only If Necessary

Service Part Number	Claim Quantity	Package Order Quantity	Number in Package	Description	
XG-12	Only If Necessary (1 possible)	Only If Necessary	1	Motorcraft® Electrical Grease	
KU2Z- 14S411- AAA	Only If Necessary (1 Possible)	Only If Necessary	1	CHCM - Service Pigtail Connector	
MB3Z-14D663-A	Only If Necessary (1 Possible)	Only If Necessary	1	Chassis Control Module	

Claim Quantity refers to the total number of individual pieces required to repair the vehicle.

Package Order Quantity refers to the amount of the service part number package(s) required to repair the vehicle.

Number In Package refers to the number of individual pieces included in a service part number package.

As Needed indicates the amount of the part may vary and/or is not a whole number. Parts can be billed out as non-whole numbers, including less than 1.

Only If Necessary indicates the part is not mandatory.

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2021-2023 Bronco: Retrieve DTCs, Inspect And Apply Electrical Grease Following The Service Procedure, Includes Time To Reprogram The CHCM (Can Be Claimed With Operation B, C, And D)	242104A	1.1 Hrs.
Additional Time To Replace The Stabilizer Disconnect Harness And Front Stabilizer Bar Disconnect (Can Be Claimed With Operation A, C And D)	242104B	1.1 Hrs.
Additional Time To Replace The Stabilizer Disconnect Harness And Body Harness (Can Be Claimed With Operation A, B And D)	242104C	0.8 Hrs.
Additional Time To Replace The Connector With A Service Pigtail and Replace the CHCM (Can Be Claimed With Operation A, B, And C)	242104D	1.8 Hrs.

Repair/Claim Coding

Causal Part:	2B325		
Condition Code:	X2		

Service Procedure

- 1. Is water or corrosion present in any of the following connectors: C1295A, C1295B, C1294A, and/or C1294B?
 - (1). Yes replace the front stabilizer bar disconnect harness and the front stabilizer bar disconnect. Refer to <u>WSM</u>, Section 204-01. Apply electrical grease or equivalent into all 4 connectors. Proceed to Step 2.
 - (2). No apply electrical grease or equivalent into all 4 connectors. Proceed to Step 2.
- 2. Is water or corrosion present in either side of connector C1415?
 - (1). Yes replace the front stabilizer bar disconnect harness and body harness. Apply electrical grease or equivalent into connector C1415. Proceed to Step 3.
 - (2). No apply electrical grease or equivalent into connector C1415. Proceed to Step 3.
- 3. Is water or corrosion present in connector C445?
 - (1). Yes replace connector C445 with a service pigtail kit and the <u>CHCM</u>. Refer to <u>WSM</u>, Section 204-01. Apply electrical grease or equivalent into connector C445. Proceed to Step 4.
 - (2). No apply electrical grease or equivalent into connector C445. Proceed to Step 4.
- 4. Reprogram the CHCM using the latest software version of the FDRS scan tool.

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article.

The inf	formation ormation	in this Tech with update	nical Service s. The most	e Bulletin (Ta recent infor	SB) was curr mation is ava	rent at the time ailable through	e of printing. Ford Motor	Ford Motor Company's	Company re on-line tech	serves the right to nical resources.	supersede