



Technical Service Bulletin

60 Panoramic sunroof opening outer perimeter seal is loose

60 24 70 2063187/5 April 11, 2024. Supersedes Technical Service Bulletin Group 60 number 23-68 dated October 9, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017 - 2024	All	Panoramic Sunroof
Q5, and SQ5	2018 - 2024		
A4 allroad, Q3, and Q8	2019 - 2024		
e-tron quattro	2019 2021 - 2023		
e-tron Sportback quattro	2020 - 2023		
e-tron S	2022 - 2024		
Q5 e quattro, SQ7, SQ8, and RS Q8	2020 - 2024		
Q5 Sportback, and SQ5 Sportback	2021 - 2024		
Q4 e-tron quattro, and Q4 Sportback e-tron	2022 - 2024		
Q4 e-tron RWD	2023 - 2024		
Q8 e-tron, Q8 Sportback e-tron, SQ8 e-tron, and SQ8 Sportback e-tron	2024		

Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised <i>Service</i> (Change in end stop adaptation instructions)



Technical Service Bulletin

		Revised <i>Required Parts and Tools</i> (Change in required roller tools)
4	10/09/2023	Revised <i>Warranty</i> (Generalize SRTs across all models)
3	03/31/2023	Revised Header (Add Q4 e-tron and Q4 Sportback e-tron) Revised <i>Warranty</i> (Add Q4 e-tron and Q4 Sportback e-tron)

Customer states:

One or a combination of the following symptoms:

- They hear wind noise in the roof area with the sunroof panel closed.
- They have seen water drip from the headliner area.
- The sunroof opening perimeter seal is distorted and/or not flush with the roof panel.

Technical Background

The adhesion of the sunroof opening perimeter seal to the roof panel may be compromised or have failed completely. There could possibly be any degree of detachment which could cause the symptoms specified in this TSB. Any detachment whatsoever discovered in the inspection is a possible point of entrance for wind and/or water into the cabin. Any detachment must be corrected by replacement of the sunroof opening perimeter seal.

Production Solution

Not applicable.

Service

1. Begin the inspection of the sunroof opening perimeter seal adhesion by fully opening the front sunroof glass panel (Figure 1).
2. Press the seal downwards and inwards with your fingers until the adhesive tape for the seal is visible (Figure 2). The foam adhesive tape may be stretched but it must not be loose or detached from the roof panel to any degree.
3. Figure 3 shows a properly adhered adhesive band.




Technical Service Bulletin

4. Repeat this procedure centimeter by centimeter over the entire length of the front sunroof opening. When this is completed, close the front sunroof panel.
5. Using the same inspection principle used in the inspection of the front portion of the sunroof opening perimeter seal check the seal adhesion in the rear portion of the sunroof opening (Figure 4).
6. Figures 5 - 8 clearly show that the adhesive tape has come loose from the vehicle body. The obvious color and shape difference at the point of contact revealing the gaps is evidence of detachment.
7. A gap in the attachment is revealed in the examples in Figures 5 - 8.
8. The locations where the adhesion is compromised or has failed is a possible entry point for water into the cabin. The area directly below these openings is outside the area of the sunroof drainage. If any adhesion is found to be compromised or failed to any extent replace the sunroof opening perimeter seal. Follow the procedure in ElsaPro explicitly to ensure proper seal adhesion paying particularly close attention to the adhesion surface preparation.
9. All vehicles for which this TSB applies *with the exception of* the Q4 e-tron models, will need the sunroof panel and rollershade end stop adaptation performed after reassembly using the sunroof panel and rollershade switches. Refer to TSB 2054505: *60 Sunroof glass panel or sunroof rollershade do not operate* for instructions. For Q4 e-tron models the sunroof panel and rollershade end stop adaptation is performed using the VAS tester in Guided Functions.

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	6042		
Damage Code:	0018		
Labor Operations:	Sunroof opening perimeter seal inspection	6042 0199	20 TU



Technical Service Bulletin

	Roof opening perimeter seal remove and reinstall	6042 19XX	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 10 TU)
	Road test prior to the service procedure	No Allowance	0 TU
	Road test after the service procedure	No Allowance	0 TU
Claim Comment:	As per TSB 2063187/5		




All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools


Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA



Technical Service Bulletin


<p>D 00940104 or equivalent surface preparation solvent (e.g. isopropyl alcohol)</p>	 <p>All Purpose Cleaner</p>	<p>0.2</p>
<p>D 355205A2 or equivalent adhesion promoter (e.g. 3M™ 111 Adhesion Promoter or AC77 Adhesive Primer)</p>	 <p>Bonding Agent</p>	<p>0.2</p>
<p>D 00950025 (or equivalent)</p>	 <p>Primer applicator</p>	<p>01</p>

Tool Number	Tool Description
-------------	------------------



Technical Service Bulletin

VAS1978/14A	 <p>Hot Air Blower</p>
T10563	 <p>Pressure Roller</p>
T40400	 <p>Roller</p>



Technical Service Bulletin

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2054505: *60 Sunroof glass panel or sunroof rollershade do not operate.*
- TSB 2056944: *60 Water entry into cabin from the sunroof area.*

All parts and service references provided in this TSB (**2063187**) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.