



Technical Service Bulletin

96 Lane change assist: side assist and exit warning system: unavailable. Sensor view restricted (DTC C12AA00)

91 24 01 2073683/1 April 16, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS 6	2021 - 2024	All	Not Applicable

Condition

Customer states:

The customer complains that driver assistance systems are permanently unavailable or there is a message in the instrument cluster, e.g.:

- Side assist and exit warning system: unavailable. Sensor view restricted due to surroundings.
- Audi pre sense: currently restricted. Sensor view restricted due to surroundings.
- Rear cross-traffic assist: currently unavailable. Sensor view restricted due to surroundings.

Workshop findings:

The following DTC may be stored in one or both of *the lane change assist control modules -J769-/-J770-*, (address word 003C / 00CF):

- **DTC C12AA00:** Restricted view

Technical Background

Radar reflections of the bumper carrier may cause interference in the lane change assist system.

Production Solution

Not applicable.

Service

Cover the holes and openings on both sides of the bumper carrier. To do so, please use the following covers:

- 4K0 807 245 / 4K0 807 246

Please use the following spreader rivet to secure the covers on the bumper carrier:



Technical Service Bulletin

- N 905 584 01 (2x per side)

In order to secure the covers, two holes (8 mm diameter) must be drilled on each side (left and right) of the bumper cover, as shown in the image below:




Figure 1: Illustration showing positioning of holes for spreader rivets.




Figure 2: Cover mounted on bumper carrier (left side).



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 Up to 48 Months/50,000 Miles.• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	6373		
Damage Code:	0010		
Labor Operations:	Remove and install rear bumper cover	6369 1900	See SRT with associated operations
	Modify bumper carrier	6350 5099	20 TU
Diagnostic Time:	GFF	0150 0060	Time stated on the diagnostic protocol (Max 50 TU)
	Charge battery	2706 8950	See SRT with associated operations
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2073443/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

The part numbers mentioned in this TSB may be different than the ones listed in ETKA. Only use parts listed in this TSB, this includes superseding part numbers!



Technical Service Bulletin

Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
4K0 807 245	Cover	1
4K0 807 246	Cover	1
N 905 584 01	Spreader Rivet	4

Additional Information

All parts and service references provided in this TSB (**2073683**) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.