Service Alert

Mazda North American Operations Irvine, CA 92618-2922



Subject:

RATTLE NOISE UNDER HOOD FROM HOOD PROP ROD

Service Alert No.: SA-023/24

Last Issued : 04/17/2024

BULLETIN NOTES

APPLICABLE MODEL(S)/VINS

2019-2024 Mazda3 2020-2024 CX-30

DESCRIPTION

The customer may report a rattling noise from the front of the vehicle under load. It may sound as if it is coming from the dashboard, but it is coming from the hood prop rod (aka lock-bonnet stay).

The prop rod diameter was increased in November 2022 production, but in some circumstances, the noise may still be encountered in vehicles after this production range. Follow the repair information below to confirm the noise and how to eliminate it.

REPAIR PROCEDURE

1. Watch the three videos below to better understand the noise.



Page **1** of **4**

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



- 2. Do the following to diagnose the noise:
 - a. Test drive the vehicle and duplicate the noise. It happens under load at between 2300-2800 RPM.
 - b. Pull over in a safe location, *remove* the hood prop rod, and then close the hood.
 - c. Test drive the vehicle and try to duplicate the noise again.

Was the noise eliminated?

- YES Continue to STEP 3 to repair the vehicle.
- **NO -** STOP. This information does not apply, diagnose the noise using other information found on MGSS.
- 3. Use felt tape from the Interior Noise Kit (see below) and install it in the two locations shown below.



Page 2 of 4

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



- 4. Reinstall the prop rod.
- 5. Confirm the noise was eliminated.

PARTS INFORMATION

Part Number	Description	Qty.	Notes
K001-W0-225	Interior Noise Kit	1	This repairs multiple vehicles, do NOT claim the kit for one repair.

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	А
Symptom Code	81
Damage Code	98

Page 3 of 4

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-023/24 Last Issued : 04/17/2024

Part Number Main Cause	CX-30: DGH9-56-651B Mazda3: BDTS-56-651B
Quantity	0
Operation Number / Labor Hours:	S0508ARX / 0.3

Page 4 of 4

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.