# Service Alert

## Mazda North American Operations Irvine, CA 92618-2922



Subject:

TAPPING / RATTLING NOISES HEARD FROM ENGINE (NEW VEHICLES OR VEHICLES THAT HAVE BEEN IN STORAGE)

Service Alert No.: SA-024/24

Last Issued: 04/19/2024

#### **BULLETIN NOTES**

This Service Alert supersedes the previously issued Service Alert(s) listed below. The changes are noted in Red text.

Previous Service Alerts:	Date(s) Issued:
SA-026/23	4/25/23
SA-023/22	04/26/22
SA-005/19	02/01/19
SA-015/18	03/22/18

#### APPLICABLE MODEL(S)/VINS:

NOTE: Vehicles with cylinder deaction have a "M" as the 8th digit in the VIN for the 2.5L with cylinder deactivation.

2021-2024 CX-5 (US spec) vehicles equipped with cylinder deactivation

2021 Mazda6 (US spec) vehicles equipped with cylinder deactivation

2021-2024 Mazda3 (US spec) vehicles equipped with cylinder deactivation

2021 CX-3 (US spec) vehicles equipped with cylinder deactivation

2021-2024 CX-30 (US spec) vehicles equipped with cylinder deactivation

2023-2024 CX-50 (US spec) vehicles equipped with cylinder deactivation

### **DESCRIPTION**

A tapping/rattling noise may be noticed from the valve train area. This operating condition can occur on new vehicles which have been delivered to Mazda dealers (due to loading and unloading from transport trucks or customers moving their vehicles in and out of their garages to wash the vehicle, etc.). This condition may also occur if the engine is not allowed to warm up after multiple cold starts.

#### **REPAIR PROCEDURE**

- 1. Check the engine oil level, correct if necessary.
- 2. Start the engine and let the engine idle to normal operating temperature with the hood open to verify the valve train tapping/rattling noise.
  - If no noise can be heard, no additional steps are necessary.
  - If a tapping/rattling noise can be heard from the valve train, run the engine for two (2) minutes without a load at

Page 1 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-024/24	Last Issued : 04/19/2024
Service Alert No.: SA-024/24	Last 155ueu . 04/15/2024

approximately 2,500 to 3,000 rpm (bleeding procedure), then go to the next step.

Page 2 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Service Alert No.: SA-024/24 Last Issued : 04/19/2024

- 3. With the engine at idle, listen for the valve train noise again.
  - If no further noise can be heard, the repair is complete and no additional steps are necessary.
  - If the noise continues, go to the next step.
- 4. Perform a vehicle road test for 3-5 miles.
  - If no further noise can be heard, the repair is complete.
  - If the noise continues, contact the Technical Assistance Hotline.

Page 3 of 3

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.