

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Vibrations in steering wheel above 60 Mph		Ref. No. TJ 36752.3.0	
Issuer (Dept.) Technical Service		Issue Date 4/23/24	Status Date 5/9/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA		Function Group 4661
Function Description Drive shaft		Page Page 1 of 3	

Attachment

File Name	File Size
TJ-36752.pdf	0.5946 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* New instructions under Service

If vibrations occur in the steering wheel, mostly noticeable at speeds between 100-130 kph or 60-80 mph, please follow advice under "Service".

CSC Customer Symptom Codes

Code	Description
40	Steering/Vibrations in the steering wheel
V7	Complete vehicle/Vibration/When driving above 45 MPH
V2	Steering wheel/Vibration/shimmy/When driving above 45 mph
V1	Tires/Vibration/out of round

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	ED	E400V6					2020-2023		-	202037-202317
536	EF	E400V2					2022-2023		-	202146-202317
536	ER	E400V12					2024-9999		0000001-0235118	202317-202408
539	ED	E400V6					2020-2023		-	202037-202317
539	EF	E400V2					2022-2023		-	202146-202317
539	ER	E400V12					2024-9999		0000001-0235118	202317-202408

Technical Journal 36752.3.0

SERVICE:

Please start by following TJ 36580 to first exclude that the vibrations do not emanate from the wheels or tires.

* Retain documentation from those procedures for future reference.

* If the issue still occurs **after the above has been ruled out**, replace the driver's airbag module according to VIDA instructions and re-evaluate the condition on a road test. Replacement airbags contain an oscillation damper that will lessen the vibration (see example photos in attachment TJ-36752.pdf).

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:

*VST OP number: 96401-2, 77006-0, 88425-2, and 09813

Note: TJ number must be stated in repair order text

VST Operation Number

VST Operation Number	Description
09813	Validation Road Test (0.5hr)
77006-0	Wheels x4 balance
96401-2	Troubleshooting wheels/tyres/hubs:V1
88425-2	Driver's airbag (SRS) remove-install/replace

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support needed", use function group 4661.

To view TJ attachment continue to next page. This TJ has one attachment.

TJ - 36752

Dampened airbag ID

