



Service Bulletin

Bulletin No.: 20-NA-136

Date: May, 2024

INFORMATION

Subject: Diagnostic Tips for DTCs Set at a Low Mileage for 9T65 Transmissions
Attention: The 9T65 Transmission Replacement Pilot Has Ended.

This bulletin only applies to vehicles with less than 19,000 km (12,000 miles) on the odometer. Vehicles over the mileage refer to SI diagnostics.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2021	2024	—	—	—	M3W
Cadillac	XT5						
	XT6						
Chevrolet	Blazer						M3V
	Traverse						
GMC	Acadia	M3W					

Involved Region or Country	United States, Canada, Middle East
-----------------------------------	------------------------------------

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Overview

The 9T65 transmission replacement pilot program has ended as of September 30, 2021, with the end of the pilot program mandatory transmission assembly replacement is no longer authorized per this bulletin. Instead refer to bulletin 20-NA-138 for current guidelines for replacement of transmission assemblies.

This bulletin is being revised to convey this change and to provide an enhanced diagnostic and repair strategy developed through the pilot program teardown and inspection learnings from returned transmissions. These strategy changes will keep with the intent of the replacement pilot program to reduce the number of days to complete the vehicle repair and reduce the number of repeat repair visits.

Unlike the replacement pilot program which was only for the US dealers this diagnostic and repair strategy can be used by all dealerships servicing vehicles with 9T65 transmissions.

If a customer is commenting on transmission operation concerns on a 9T65 transmission (RPO M3W and M3V), follow the steps below to determine repair strategy.

Please refer to these service publications for resolutions to customer comments prior to proceeding with this bulletin.

1. 18-NA-359 – Information on Flashing D in PRNDL and/or Transmission Slip/Flare on 1-2 Upshift with Zero to Very Light Throttle Input
2. 20-NA-060 – High Pitch Noise Heard When Vehicle is Decelerating
3. 21-NA-201 – Information on DTC P0747 Setting at Engine Shut Down When Transmission is in Park/Neutral with No Hydraulic/Mechanical Transmission Concern
4. 21-NA-038 – Humming Noise Heard Coming From Front End of Vehicle When Driving at Highway Speeds
5. 21-NA-118 - Vibration Type Noise Heard at Highway Speeds or with Engine Speed at 1,300-1,500 RPM
6. PIP5974 - GF9 9T45/50/60/65 Transmission 1-2-3-4-5-6 Clutch Snap Ring Popout Causing SES / DTC Code P0746 P0747
7. Torque converter shudder.
 - Refer to PIP5608H – TCC Shudder Surge Fish bite Chuggle
 - Refer to latest version of 08-07-30-035 – Information on Water or Ethylene Glycol in Transmission Fluid
 - Refer to *Torque Converter Diagnosis* in SI.
 - If not resolved, contact Technical Assistance (TAC). Refer to *PIP5621B: GM TAC Support On Vehicle Automatic Transmission Concerns That Can Be Duplicated*
8. In addition to the complaint, cause, and correction notes on the repair order, this other information is required to be noted:
 - DTCs found during vehicle diagnosis – include the DTC, what module it was in and if it was history or current. Search all modules including TCM, ECM, BCM, EBCM, IPC, and TRCM.
 - Oil level test findings – overfill, under-fill, and correct level. If over or under, estimate of how much fluid.
 - Oil pressure test results. Record actual pressure reading taken.

Step One — DTCs

1. Check all Modules for DTCs. Records of all DTCs, Current or History, and Module Located In/On Repair Order.


Step Two — Fluid Level and Condition Check

Note: Ensure the transmission has enough fluid in it to safely start the vehicle without damaging the transmission. With the vehicle off and the transmission fluid temperature at approximately 20–25°C (68–77°F), there must be at least enough fluid to drain out of the fluid level hole. This will ensure that there is enough fluid in the sump to fill the components once the vehicle is started.

1. Start the engine.
2. Depress the brake pedal and move the shift lever through each gear range, pausing for about 3 seconds in each range. Then move the shift lever back to PARK (P).
3. Allow the engine to idle 500–800 rpm for at least 3 minutes to allow any fluid foaming to dissipate and the fluid level to stabilize. Release the brake pedal.
4. Keep the engine running and observe the transmission fluid temperature (TFT) using the Driver Information Center (DIC) or a scan tool.


Caution: The transmission fluid level must be checked when the transmission fluid temperature (TFT) is at 85–95°C (185–203°F). If the TFT is not at this temperature, operate the vehicle or allow the fluid to cool as required. Setting the fluid level with a TFT outside this temperature will result in either an under or over-filled transmission. TFT 95°C under-filled, TFT 85°C over-filled. An under-filled transmission will cause premature component wear or damage. An over-filled transmission will cause fluid to discharge out the vent tube, fluid foaming, or pump cavitation.

5. Raise the vehicle on a hoist. The vehicle must be level, with the engine running and the shift lever in the PARK range.



6. While the vehicle is idling, remove the oil level set plug (1). Allow any fluid to drain:

- If the fluid is flowing as a steady stream, wait until the fluid begins to drip.
 - If no fluid comes out, add fluid until fluid drips out.
7. Record fluid level; overfilled, under-filled, correct on repair order and how much was needed to fill or came out:
- If fluid is overfilled, set correct level and retest.
 - If fluid is under-filled, inspect for external leaks. Refer to *Fluid Leak Diagnosis*.
8. If fluid level is correct, then check condition of the fluid.



5840393

- 8.1. Inspect the fluid color.
- The fluid should be red or dark brown.
 - It should be transparent so that objects or writing can be seen through it. Sample #1 is an example of acceptable fluid. Sample #2 is an example of very dark fluid. Sample #3 is an example of black fluid.
 - In addition to checking the fluid color and transparency, the fluid should be checked for an odor of burnt fluid. If the fluid is very dark, black, or has a burnt odor it would indicate clutch damage has occurred internally in the transmission and it would need to be removed from the vehicle and investigated.
- 8.2. Inspect the fluid for excessive metal particles or other debris.
- A small amount of “friction” material is a “normal” condition.
 - A small amount of “metal” from the manufacturing process is a “normal” condition. This is observed as fine silver streaks floating in the fluid.

- If large pieces and/or metal pieces are noted in the fluid, record on the repair order and it would indicate damage has occurred internally in the transmission and it would need to be removed from the vehicle and investigated.
 - Fluid that is cloudy or milky or appears to be contaminated with water indicates engine coolant or water contamination. Refer to the latest version of Corporate Service Bulletin Number 08-07-30-035 for testing and, if confirmed, find the source of the coolant/water and repair then follow SI document for “Engine Coolant/Water in Transmission” for proper transmission repair.
- 8.3. Inspect for external leaks. Refer to *Fluid Leak Diagnosis*.
- If fluid level and condition are ok, proceed to next step.

Step Three — Line Pressure Check

Warning:

Keep the brakes applied at all times in order to prevent unexpected vehicle motion. Personal injury may result if the vehicle moves unexpectedly.

Note: You may need to remove or disconnect components in order to gain access to the transmission line pressure test hole plug.

1. Remove the line pressure test hole plug. Refer to *Automatic Transmission Fluid Pressure Test Hole Plug Replacement* in SI.
2. Install the *GE-21867* Pressure Gauge (1).
3. Start the engine.
4. Verify the Transmission Fluid Pressure = Greater than 345 kPa (50 psi).
 - If pressure is below 50 psi, record on the repair order and follow SI document for “Fluid Pressure High of Low”.
 - If above 50 psi, proceed to next step.
5. Turn the engine OFF.
6. Remove the *GE-21867* Pressure Gauge.
7. Install and tighten line pressure test hole plug. Refer to *Automatic Transmission Fluid Pressure Test Hole Plug Replacement* in SI.

Step Four — Perform Road Test

Perform step 1-4 first in order to ensure the electronic transmission components are functioning properly. If these components are not checked, a simple electrical condition could be misdiagnosed.

1. Connect the scan tool.
2. Ensure the gear selector is in PARK and set the parking brake.

3. Start the engine.
4. Verify that the following scan tool data can be obtained and is functioning properly.
 - Refer to Control Module References for typical data values. Data that is questionable may indicate a concern.
5. Check the garage shifts.
 - 5.1. Apply the brake pedal and ensure the parking brake is set.
 - 5.2. Move the gear selector through the following ranges:
 - ⇒ PARK to REVERSE
 - ⇒ REVERSE to NEUTRAL
 - ⇒ NEUTRAL to DRIVE
 - ⇒ DRIVE to REVERSE
 - ⇒ REVERSE to DRIVE
 - 5.3. Pause 2 to 3 seconds in each gear position.
 - 5.4. Verify the gear engagements are immediate (less than 2 seconds to complete if transmission fluid temperature is above **20°C (68°F)** and not harsh. Note that these shifts may be almost imperceptible in some applications. Using the scan tool to monitor Transmission ISS, achieving 0 rpm can be used to check delay in these cases.

Note: Harsh engagement may be caused by any of the following conditions:

- High engine idle speed – Compare engine idle speed to desired idle speed.
- A default condition caused by certain DTCs that result in maximum line pressure to prevent clutch slippage.
- Incomplete adapting or incorrect adapting – Repeat maneuver multiple times to see if shift quality improves. If it does not and no DTCs were set, refer to SI document “Harsh Garage Shift”.

Note: Delayed engagement may be caused by any of the following conditions:

- Low idle speed – Compare engine idle speed to desired idle speed.
 - Low fluid level.
 - Cold transmission fluid temperature (TFT) – Use the scan tool to determine TFT.
 - Selector linkage – Inspect and adjust as necessary.
 - Incomplete adapting or incorrect adapting – Repeat maneuver multiple times to see if the delay improves. If it does not and no DTCs were set, refer to SI document “Harsh Garage Shift”.
6. Check Upshifts – The TCM calculates the upshift points based primarily on 2 inputs: throttle position

and vehicle speed. When the TCM determines that conditions are met for a shift to occur, the TCM commands the shift by varying current to the appropriate PC solenoids to control oncoming and off going clutch pressures.

- 6.1. Monitor the following scan tool parameters:
 - ⇒ Calc. Throttle Position
 - ⇒ Vehicle Speed
 - ⇒ Engine Speed
 - ⇒ Transmission ISS
 - ⇒ Transmission OSS
 - ⇒ Command Gear
 - ⇒ TCC PC Sol. Pressure Cmd.
 - ⇒ TCC Slip Speed
 - ⇒ TFP Switch 1
 - ⇒ TFP Switch 2
 - ⇒ TFP Switch 3
 - ⇒ TFP Switch 4
 - ⇒ PC Sol. 2 Pressure Cmd.
 - ⇒ PC Sol. 3 Pressure Cmd.
 - ⇒ PC Sol. 4 Pressure Cmd.
 - ⇒ PC Sol. 5 Pressure Cmd.
 - ⇒ Shift Solenoid 1 and 2
- 6.2. Place the gear selector in the DRIVE position.
- 6.3. Accelerate the vehicle using a steady throttle position between 15 and 20 percent. Hold the throttle steady.
- 6.4. As the transmission upshifts, there should be a noticeable shift feel or engine speed change within 1 to 2 seconds of the commanded gear change. The PC solenoid pressure command should change to “YES” for the oncoming clutch and the PC solenoid pressure command should change to “NO” for the off going clutch.
- 6.5. Note any harsh, soft, or delayed shifts or slipping. Note any noise or vibration.
- 6.6. The torque converter clutch (TCC) feel may not be noticeable. In many applications the TCC will apply after the 1-2 shift and TCC events will not be easily detected using engine speed. Monitor TCC PC solenoid pressure command while driving and check TCC slip speed when the pressure command indicates that the TCC is commanded to apply.
- 6.7. When the TCC applies, slip speed should be controlled to below 100 RPM when the transmission is not shifting, and the throttle

is held steady. If the TCC slip exceeds this value for more than 6 seconds after the TCC PC Sol. Pressure Command indicates that the TCC is commanded on:

⇒ Check for DTCs.

⇒ Refer to *Torque Converter Diagnosis* in SI.

Note: This transmission is equipped with an electronically controlled capacity clutch (ECCC), which allows operation of the clutch without fully locking to the torque converter cover. The clutch maintains a small amount of slippage, approximately 20 RPM, in 2nd, 3rd, 4th, 5th, and 6th gears, depending on the vehicle application. ECCC was developed to reduce the possibility of noise, vibration or chugge caused by TCC apply. Full lockup is available at highway speeds on some applications.

7. Part Throttle Step-in Downshifts:

- 7.1. Place the gear selector in the DRIVE position.
- 7.2. Accelerate the vehicle at light throttle (5-10 percent) until 3rd gear is just achieved.
- 7.3. Quickly increase throttle angle until commanded gear indicates that a downshift to 2nd gear is commanded.
- 7.4. Verify that the transmission downshifts within 2 seconds of the throttle movement.
- 7.5. Repeat steps 2 to 4 at higher speed to achieve 4th gear and then step in to command a 4th gear to 3rd gear downshift.
- 7.6. Repeat steps 2 to 4 at higher speed to achieve 5th gear and then step in to command a 5th to 4th gear downshift.
- 7.7. Repeat steps 2 to 4 at higher speed to achieve 6th gear and then step in to command a 6th gear to 5th gear downshift.
- 7.8. Note any harsh, soft, or delayed shifts or slipping. Note any noise or vibration.

8. Coasting Downshifts:

- 8.1. Place the gear selector in the DRIVE position.
- 8.2. Accelerate the vehicle to 6th gear with the TCC applied.
- 8.3. Release the throttle and apply the brakes.
- 8.4. Verify that the downshifts occur as commanded by monitoring gear ratio, which should change after commanded gear changes.
- 8.5. Note any harsh, soft, or delayed shifts or slipping. Note any noise or vibration.

9. Reverse:

- 9.1. With the vehicle stopped, move the gear selector to REVERSE.

- 9.2. Slowly accelerate the vehicle to a 10-15 percent throttle position.
- 9.3. Verify that there is no noticeable slip, noise, or vibration.

10. Road Test Results:

- 10.1. Diagnostic TIP: If completion of the above tests are inconclusive to isolate if the transmission shifting concern(s) are internal transmission or input/command, can use the control function feature in GDS2 to command all shifts. If when using GDS2 to command shifts and transmission shifts into each range commanded, the concern is generally an input/command concern, and not an internal transmission concern. If ranges are not completed when using GDS2 to command, then generally the concern is an internal transmission concern and not an input/command concern.
- 10.2. If noise or vibration concern is noted, follow *Noise and Vibration Analysis* in SI using Chassis Ears and PICO scope in diagnosis.
- 10.3. If upshifts and downshifts are harsh, soft, delayed, or slip, follow SI diagnosis for condition.

Step Five — DTC

If any of the following DTCs are Current or reset during the road test, record on the repair order and follow the instructions below for that DTC.

- P0796 Transmission Control Solenoid Valve 3 Stuck Off
- P0797 Transmission Control Solenoid Valve 3 Stuck On
- P2723 Transmission Control Solenoid Valve 5 Stuck Off
- P2724 Transmission Control Solenoid Valve 5 Stuck On

If any of the above first group of DTCs are current or reset on the road test the transmission must be removed from the vehicle and inspected for damage to the clutch plates. If hot spots or other evidence of a slipping clutch, then follow SI procedure for replacement of the affected clutch plates and replace **both** the solenoid body and valve body.

- P0746 Transmission Control Solenoid Valve 1 Stuck Off
- P0747 Transmission Control Solenoid Valve 1 Stuck On
- P2731 Transmission Control Solenoid Valve 6 Performance
- P2732 Transmission Control Solenoid Valve 6 Stuck Off

- P2733 Transmission Control Solenoid Valve 6 Stuck On
- P2820 Transmission Control Solenoid Valve 9 Stuck Off
- P2821 Transmission Control Solenoid Valve 9 Stuck On
- P187D Transmission Park Valve Stuck On
- P18AA Transmission Range Control Valve 1 Position Switch Circuit Stuck On
- P18AB Transmission Range Control Valve 1 Position Switch Circuit Stuck Off
- P18AC Transmission Range Control Valve 2 Position Switch Circuit Stuck On
- P18AD Transmission Range Control Valve 2 Position Switch Circuit Stuck Off
- P18AE Transmission Range Control Enable Valve Stuck Off

If any of the above second group of DTCs are current or reset on the road test and the transmission fluid is red, translucent, and doesn't have a burnt odor, then **only** replace both the solenoid body and valve body. If the transmission fluid is very dark or black, not translucent, and has a burnt odor, then in addition to replacing the solenoid body and valve body, the transmission should be removed from the vehicle and inspected for damage to the clutch plates, if found follow SI procedure to replace them.

- P0741 Torque Converter Clutch (TCC) System Stuck Off
- P0776 Transmission Control Solenoid Valve 2 Stuck Off
- P0777 Transmission Control Solenoid Valve 2 Stuck On
- P2817 Transmission Control Solenoid Valve 8 Stuck Off
- P2818 Transmission Control Solenoid Valve 8 Stuck On

If any of the above third group of DTCs are current or reset on the road test and the transmission fluid is red, translucent, and doesn't have a burnt odor, then **only** replace the solenoid body. If the transmission fluid is very dark or black, not translucent, and has a burnt odor, then in addition to replacing the solenoid body, the transmission should be removed from the vehicle and inspected for damage to the clutch plates, if found follow SI procedure to replace them.

- P2714 Transmission Control Solenoid Valve 4 Stuck Off
- P2715 Transmission Control Solenoid Valve 4 Stuck On
- P187D Transmission Park Valve Stuck On
- P187E Transmission Park Valve Stuck Off

If any of the above fourth group of DTCs are current or reset on the road test and the transmission fluid is red, translucent, and doesn't have a burnt odor, then **only** replace the valve body. If the transmission fluid is very dark or black, not translucent, and has a burnt odor, then in addition to replacing the valve body, the transmission should be removed from the vehicle and inspected for damage to the clutch plates. If found, follow SI procedure to replace them.

- P0721 Output Speed Sensor Performance
- P0722 Output Speed Sensor Circuit No Signal
- P0723 Output Speed Sensor Circuit Intermittent

If any of the above fifth group of DTCs are current or reset on the road test and the transmission fluid is red, translucent, and doesn't have a burnt odor, then follow SI diagnostic for the output speed sensor.

- P18A8 Transmission Park Control Solenoid Actuator Stuck Off
- P18E7 Transmission Park Valve Position Sensor 1 Performance
- P18E8 Transmission Park Valve Position Sensor 2 Performance
- P27EC Transmission Range Control Valve 1 Position Switch Performance
- P27F0 Transmission Range Control Valve 2 Position Switch Performance

Note: If P18A8 is set then also replace the Park inhibit Solenoid Actuator along with the solenoid body and valve body.

If any of the above sixth group of DTCs are current or reset on the road test and the transmission fluid is red, translucent, and doesn't have a burnt odor, then check vehicle battery health and state of charge per SI instructions, also check battery, TCM, and Transmission ground for voltage loss. If battery and grounds do not show problem and DTC is current, then replace both the solenoid body and valve body. If the transmission fluid is very dark or black, not translucent, and has a burnt odor, then in addition to replacing the solenoid body and valve body, the transmission should be removed from the vehicle and inspected for damage to the clutch plates. If found, follow SI procedure to replace them.

If any of the DTCs are not reproduced during testing and only seen in History, then perform the *Transmission Service Fast Learn Procedure*. If no DTCs, reset and return the vehicle to the customer.

Symptoms other than listed above should be diagnosed using SI procedures and repaired as necessary.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Note: EMISSION WARRANTY COVERAGE CODE E, E1 APPLIES TO LABOR OPERATION 846369.

Note: If transmission is removed from vehicle and internally inspected for clutch or hardware failure, use appropriate control valve body or control solenoid body labor operation for the DTC and include the clutch or hardware inspection and repair time as straight time to the labor operation.

Labor Operation	Description	Labor Time
8481048*	Perform Fluid Level and Oil Pressure Checks and Service Fast Learn	1.5 hrs
8463690***	Control Valve Body Replacement	Use Published Labor Operation Time
8463700	Control Valve Solenoid Body Replacement	
<p>*This is a unique Labor Operation for bulletin use only. This operation is only used if transmission assembly is not replaced.</p> <p>**Because the transmission is not to be disassembled for this bulletin, the 1.5 hours add time for "Disassemble, Inspect, Determine Repair and Re-assemble for Core Return" should not be claimed.</p> <p>***If valve body and solenoid body are replaced at the same time use this labor operation.</p>		

Version	13
Modified	<p>Released June 26, 2020</p> <p>Revised August 18, 2020 – Added the Warranty Information section.</p> <p>Revised September 25, 2020 – Added the 2021 Model Year.</p> <p>Revised May 26, 2021 - Update information in the Overview section, Step One-DTC section, Step Five DTC section and the Warranty Information section.</p> <p>Revised July 13, 2021 - Update information in the Overview section after Step 3 to Extend Pilot Program.</p> <p>Revised August 05, 2021 - Added the 2022 Model Year.</p> <p>Revised October 01,2021 - Add Attention statement, Update Overview and Warranty Information section.</p> <p>Revised November 23, 2021 – Updated #5 under Overview.</p> <p>Revised February 17, 2021 - Removed PIP5697B and Added 21-NA-201 in the Overview section.</p> <p>Revised July 20, 2022 - Remove P187E, P18E7 and P18E8 from the Step 5 - DTC section.</p> <p>Revised August 04, 2022 - Removed 2018 and 2019 from Model Year and Added 2023 to Model Year.</p> <p>Revised August 02, 2023 - Removed 2020 from Model Year and Added 2024 to Model Year.</p> <p>Revised May 03, 2024 - Added PIP5974 under Overview section.</p>

