

MAS004208 RU 24-17

RAPID UPDATE

FROM: Maserati TSO

TO: Maserati Network



Maserati

PERSONAL SERVICE LAB

MASTERS OF CARE

TECHNICAL SERVICE OPERATIONS

Rapid Update 725 GranTurismo Full Hardware Update



ATTENTION! This Rapid Update supercedes all the previous RUs listed on page 3 and is a regrouping/compiling of those Rapid Updates.

DATE: MAY 8, 2024

The Maserati GranTurismo listed in the attachment are involved in a Rapid Update to check and/or replace some HW components in order to guarantee the maximum experience for our Customers. It is very important for us to update all vehicles with the latest product improvement available and, over the last year, there has been a huge effort by everyone to improve the functionality of our vehicles, following reports and suggestions of Customers.

To facilitate daily work and time management, we thought of grouping some actions so that it is possible to better organize all the work necessary for each individual vehicle. The cycle time necessary to carry out the planned interventions ranges from a minimum of twenty minutes to a maximum of four hours for the few vehicles that need to carry out all the interventions indicated in the VIN list, in the hypothesis that all the preliminary checks give a negative result.

We remind you that **all** the Rapid Updates must be performed within the first workshop visit (not only this regrouping), regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

Please read and review this bulletin first before ordering parts and/or starting the procedure.

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.

Maserati North America
Aftersales Dept.

Overview – Automatically fill requests

Check on the attached VIN list which actions must be carried out for each VIN involved.


Complete VIN	VIN	Status	Modis Case Label	Previous RSU Numbers
ZAMBMVBB0RX405806	405806	85	HW Update 9	653-654-659-677-682
ZAMBMVBB0RX405807	405807	85	HW Update 23	653-677-682
ZAMBMVBB0RX412189	412189	96	HW Update 27	659-677-682-696
ZAMBMVBB0RX412173	412173	94	HW Update 1	696
ZAMBMVDB0RX411450	411450	96	HW Update 13	677-682-696
ZAMBMVBB0RX412159	412159	96	HW Update 13	677-682-696
ZAMBMVBB0RX412169	412169	95	HW Update 8	653-654-659-677-681-682-696

Modis Case Label for the automatic compilation of the claim

List of **Previous RSU Numbers** for each VIN

Example of VIN list

When the **SE** (Service Entry) is opened and the complaint for the campaign is created, Modis will automatically recognize the combination of actions and/or spare parts assigned to the VIN, automatically proposing the choice of the right case. Only one case is suggested, avoiding any errors.



TIP: It is advisable to open the complaint in a temporary state, limiting yourself to confirming the only option that the system will suggest. In this way it will be very clear to understand the list of activities to be carried out.

Cost Code: 23 - Service campaign Campaign #: 725

Component: 999000 M189 MULTIPLE HW UPDATE Repair technically authorized

Labour Code [0 Element inserted]

Code	Description	Hours
624026A	AIR PIPE CONNECTOR TAPING	0,45
190013A	BRANCH SERVICE CABLE CHECK	0,30
913108A	REAR LOKARY REPLACEMENT	1,20
670300546	RH REAR WHEELHOUSE GUARD	1
670300548	LH REAR WHEELHOUSE GUARD	1
675000324	HEAT SHIELD FIX NUT	2
675000531	RIVET VG 11 04816 511	4


ATTENTION: We recommend that you recheck the VIN list to avoid any errors regarding the updates to be performed. Please note that the VIN list reports exactly the same autofill in Modis.

If the request is submitted without any changes, it will automatically be evaluated and approved.

NOTE: The entry of the complaint is a self-declaration that all activities were carried out at the time of closure of the SE.

Operating Procedures

For operating procedures, refer to the Rapid Update Bulletins attached to this MAS in the **PROCEDURE.zip** file. To view them, unpack the file and select, within the folder of your preferred language, the MAS relating to the intervention to be carried out.



- Check the tightness of the engine bonnet locking hooks
MAS003712 RU 23-38 Rapid Update 653 Granturismo front hood striker bolt check
- Check Gap&Flush Fender Holder
MAS003732 RU 23-49 Rapid Update 654 Granturismo Door-fender gap & flush check
- Taping of air pipe connector
MAS003814 RU 23-63 Rapid Update 677 Granturismo Air Pipe Connector Taping
- Repositioning of the front wiring
MAS003863 RU 23-69 Rapid Update 681 Granturismo Front Wiring Repositioning
- Check service cable branch
MAS003864 RU 23-70 Rapid Update 682 Granturismo Branch Service Cable Check
- Check brake pad sensor connector
MAS003745 RU 23-47 Rapid Update 659 Granturismo brake pad connector check
- Replacement of rear wheelhouse
MAS004043 RU 24-08 Rapid Update 696 Granturismo Wheelhouse Replacement

Spare Parts

Most of the actions considered in this grouping do not require component replacements. However, for those actions for which they are foreseen, you will find all the necessary information below.

To replace the **rear wheelhouses (Ex. #696)**, please order the following PNs, referring to the spare parts catalogue and following the instructions contained in the attached Vin-List.

Ex #696 - MASERATI GRANTURISMO (M189) spare parts	PN	Qty
REAR WHEEL COMPARTMENT SHELTER DX.	670300546	1
REAR WHEEL COMPARTMENT SHELTER SX	670300548	1
HEAT SHIELD FIX NUT	675000324	2
RIVET VG 11 04816 511	675000531	4

To **reposition the front wiring section (Ex. #681)**, order the following PN, referring to the spare parts catalogue and following the instructions contained in the attached Vin-List.

Ex #681 - MASERATI GRANTURISMO (M189) spare parts	PN	Qty
Clamp on pin	673016173	2

Warranty Claim

Fill out the warranty claim as follows:

Description	Code
Rapid Update Number	725
Warranty code	23
Fault code	063
Component code	9.99.000
Operation code	
Check engine bonnet locking hooks	
▪ Rework (2 sides)	9.23.049.A (0.10h)
Gap&Flush Check	
▪ Check (2 sides)	9.20.001.A (0.10h)
▪ Gap&Flush tuning (1 side)	9.20.001.B (0.30h)
▪ Gap&Flush tuning (2 sides)	9.20.001.C (0.50h)
Taping of air pipe connector	
▪ Taping (2 sides)	6.24.026.A (0.45 h)
Repositioning of the front wiring	
▪ Tie cable application (2 sides)	8.60.001.B (0.30h)
Check service cable branch	
▪ Check	01.90.013.A (0.30h)
▪ Check + Rework	01.90.013.B (1.50 h)
Check brake pad sensor connector	
▪ Check (2 sides)	4.10.005.A (0.15h)
Replacement of rear wheelhouses	
▪ Replacement (2 sides)	9.13.108.A (1.20 h)

NOTE : Submission of the Warranty Claim is a *self-declaration* that the necessary parts have been replaced/reworked and that all forms have been updated at the time of SE closure.