



STAR ONLINE PUBLICATION



Case Number: S2408000053

Release Date: May 2024

Symptom/Vehicle Issue: Passenger Power Seat Does Not Operate

Customer Complaint/Technician Observation: The owner complains that the passenger power seat switch does not operate to move the seat. The technician observed no Diagnostic Trouble Codes (DTCs) and a passenger power seat that does not operate.

Repair Procedure: The F08 20 Amp passenger power seat fuse may become open if the power seat switch operation is commanding 3 motor seat actions at the same time. Fuses that become open should be replaced with a 25 Amp fuse as shown to resolve, no further service actions required.

Locate the rear fuse box left rear of the vehicle.



Remove the snap-on cover using the two levers located on the cap.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.


Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.




STAR ONLINE PUBLICATION




With the cover removed locate the 20A fuse (yellow) F08.



Remove the 20A (yellow) fuse using the yellow extractor.



Replace it with a 25A (white) fuse.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.