

REFERENCE:	TSB: 08-133-24 REV. A GROUP: 08 - Electrical	Date:	May 29, 2024	REVISION:	08-133-24
VEHICLES AFFECTED:	2022 (GU) Alfa Romeo Stelvio This bulletin applies to vehicles equipped with a Global Telematics Box Module (Sales Code RDG) and SiriusXM Guardian-Included Trial (B) (Sales Code RT1).	MARKET APPLICABILITY:			
		<input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH			
CUSTOMER SYMPTOM:	The customer may also experience one or more of the following: <ul style="list-style-type: none"> • Outdated vehicle data on customer's mobile app. • Connected Services maintenance popup displayed on the radio screen. • Connected Services battery maintenance popup displayed on the radio screen. 				
CAUSE:	TBM Software				

This bulletin supersedes Technical Service Bulletin (TSB) 08-133-24, date of issue May 25, 2024, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an updated LOP number.

Message display on the radio screen, "Uconnect Box requires service. Please visit an authorized dealer." [Fig. 1.](#)




Fig. 1
Battery Of Connected Services Messages

NOTE: "Uconnect Box requires service." message can be triggered by different reasons. For an issue on a new vehicle recently switched to customer mode, please follow the New Vehicle Preparation procedure to resolve the issue. For the customer vehicle with intermittent concerns, please check the TBM, antenna and instrument panel harness connections.

REPAIR SUMMARY:

This bulletin involves reprogramming the TBM with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-F5-93	Module, Global Telematics Box (TBM) - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	3.3 Hrs.
Failure code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

NOTE: The Tire Pressure Monitoring System (TPMS) warning light and "Service TPM System" message will be illuminated on the Instrument Panel Cluster (IPC) after the TBM2 software has been updated. The system will automatically update and the TPMS warning light will turn off once the system receives the updated tire pressures. The vehicle may need to be driven for up to 20 minutes above 15 mph (24 km/h) in order for the TPM system to receive this information.

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the TBM with the latest software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.