



Technical Service Bulletin

01 MIL on - 4.0TFSI Cylinder 1 or 6 Misfires - RS6 or RS7 - P03000, P030100, P030600

01 24 24 2071263/5 May 23, 2024. Supersedes Technical Service Bulletin Group 01 number 23-96 dated November 17, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS 6 Avant, and RS 7	2021 - 2023	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised <i>Warranty</i> (Updated Labor Operations)
4	11/07/2023	Revised header (Added MY 21 and MY23) Revised <i>Service</i> (Added SVM Codes)
3	08/31/2023	Revised <i>Warranty</i> (Updated Service number)

Customer states:

- MIL on or exhaust emissions warning light flashes or is intermittently illuminated.
- No noticeable differences in performance are noted while the MIL/ exhaust emissions warning is illuminated.
- The “Start System: Fault” may also appear in the instrument cluster.

Workshop findings:

The following DTCs with specified ambient conditions **must** be stored in the ECM, J623, (address word 0001):

- **P030000** (Misfire detected)
- **P030100** (Cylinder 1 Misfire detected)
- **P030600** (Cylinder 6 Misfire detected)

Ambient Conditions

- Engine speed below 1900 RPM
- Normed load value: less than 20%
- Engine oil temperature: below 75° C

NOTICE

If misfires for other cylinders or the ambient conditions outside the scope mentioned above are stored in the ECM, J623, (address word 0001), please continue with normal diagnosis process.



Technical Service Bulletin

Technical Background

The ECM software has been optimized.

Production Solution

Not applicable.

Service

SVM Update instructions:

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the ECM, J623 (address word 0001) using the SVM action code as listed in the table below, if necessary:

Model	Old Software Number	Old Software Version	New Software Number (or higher)	New Software Version (or higher)	SVM Code Input
MY21 RS 6 and RS 7	4K0907557F	0001-0002	4K0907557F	0003	01A297
MY22 RS 6 and RS 7	4K0907557G	0001-0002	4K0907557G	0003	
MY23 RS 6 and RS 7	4K0907557H	0001	4K0907557H	0002	

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.
Service Number:	2470
Damage Code:	0039



Technical Service Bulletin

Labor Operations:	Software update	0151 0010	See SRT with associated operations
	Software update	0151 0060	Max 50 TU
Diagnostic Time:	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB 2071263/5		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Tool Number	Tool Description
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10)

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2011732: *00 Software Version Management (SVM), operating instructions.*

All part and service references provided in this TSB (**2071263**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.