



SIB 64 05 21

2024-06-04

RATTLING NOISE PERCEPTIBLE IN VEHICLE INTERIOR WITH AC ACTIVATED

This Service Information Bulletin (Revision 4) replaces SI B64 05 21 **dated October 2022**.

What's New:

- Models added
- Claim Information section updated

MODEL

F97 (X3 M Sports Activity Vehicle (SAV))	F98 (X4 M Sports Activity Coupe (SAC))	G01 (X3 SAV)	G02 (X4 SAC)
G20 (3 Series Sedan)	G22 (4 Series Coupe)	G23 (4 Series Convertible)	G26 (4 Series Gran Coupe)
G42 (2 Series Coupe)	G80 (M3 Sedan)	G82 (M4 Coupe)	G83 (M3) Competition Convertible
G87 (M2 Coupe)			

SITUATION

A rattling/droning noise is heard in the vehicle interior when the air conditioning (AC) is activated. Vibrations are felt in the driver's footwell.

See attached video: [BV64 01 22_G20 Drone noise while driving](#)

MODEL

E-Series	Model Description	Production Date
G20	3 Series Sedan	From Start of Production

SITUATION

A rattling noise is heard in the vehicle interior when the air conditioning is activated.

CAUSE

The refrigerant line double pipe and a clamp on the return line of the internal heat exchanger are in line with each other (in the direction of travel, on the left (driver) side of the engine compartment below/behind the DME) and are making contact.

See attached video: [BV64 02 22_G20 Drone noise source](#)

CORRECTION

Insert a spacer between the coolant hoses underhood, and strips of felt tape in the area of contact between lines below the instrument panel.

PROCEDURE


For the situation described above, proceed as follows.




The hoses are contacting here (arrow).



Mount a spacer (part number 11 53 7 537 923) in the engine compartment between the coolant hose feed and coolant hose return. The coolant hoses have to be turned about 10 to 15 degrees in the direction of the bulkhead.



Close up view of spacer installed.



If the complaint still occurs after installing the spacer, the following must also be done:
Remove the trim panel for pedal mechanism.
See repair instructions REP 5145186



Tape the two heat exchanger lines with a felt strip (part number: 51 45 2 353 024) 4-5 inches (10-12 cm) long around each of the lines. Secure the lines together using a worm-type hose clamp (part number 07 12 9 952 117).

This prevents the lines moving in the aperture grommet.

See attached video:

[BV64 02 22_G20 Drone noise source](#)

Then remount the trim panel for pedal mechanism and reassess the vehicle.

PARTS INFORMATION

Obtain and confirm the part numbers for your specific vehicle by entering the chassis number in either ETK or AIR which takes into account specific equipment and/or options.

Part Number	Description	Quantity
51 45 2 353 024	Felt tape	25cm max
07 12 9 952 117	Hose Clamp	1
11 53 7 537 923	Spacer (originally for E83 vehicles)	1

CLAIM INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

Defect Code:	6453003900	Refrigerant line of Air conditioning Unpleasant noises
---------------------	-------------------	---

Obtain the flat rate unit (FRU) allowances for the following that applies.

Labor Operation	Description	Labor Allowance
12 90 150	Remove and install control unit box (For access) (Main work)	As applicable
Or:		
12 90 650	Remove and install control unit box (For access) (Plus work)	As applicable
And, as necessary:		
51 00 001*	Body equipment / Localizing body complaint(s) (Work time)	WT FRU
Or		
00 58 500*	Diagnosis Worktime Flat Rate (See below*)	2 FRU
And:		
64 99 000	Work time to install the clamp and felt strip	2 FRU
And, if necessary:		
51 45 684	Removing and installing trim panel for pedal assembly	As applicable
And:		
64 99 000	Work time to tape the two heat exchanger lines with a felt strip (includes the 2 FRU above to install the clamp and felt strip)	4 FRU

If you are using a Main labor code for another repair, use the Plus code labor operation 12 90 650 instead of
Copyright ©2024 BMW of North America, Inc.

For the above, only claim Work time labor operation code 64 99 000, one time, for either 2 FRU or 4 FRU as applicable for the repair that as performed.

Or, if the

Engine compartment repair was performed prior to the March 2022 Bulletin update.

Obtain the flat rate unit (FRU) allowances for the following that applies.

Labor Operation	Description	Labor Allowance
51 45 184	Removing and installing trim panel for pedal assembly (Main work)	As applicable
Or:		
51 45 684	Removing and installing trim panel for pedal assembly (Plus work)	As applicable
And, as necessary:		
51 00 001*	Body equipment / Localizing body complaint(s) (Work time)	WT FRU
Or		
00 58 500*	Diagnosis Worktime Flat Rate (See below*)	2 FRU
And:		
64 99 000	Work time to tape the two heat exchanger lines with a felt strip	2 FRU

If you are using a Main labor code for another repair, use the Plus code labor operation 51 45 684 instead of 51 45 184.

Work time labor operation codes 51 00 001 and 00 58 500 are not considered a Main labor operations.

And, as needed:

Sublet – Bulk Materials (RO and Claim Comments Required)

Sublet Code 4	See the sublet reimbursement calculations below	Reimbursement for the repair-related bulk material (Do not use the BMW part number for claim submission)
----------------------	---	--

Sublet reimbursement calculation for claiming the applicable repair-related bulk material (BMW part numbers) is at the dealer net price amount for the quantity used plus your center’s handling.

Enter this material cost in sublet and itemize the amount on the repair order and in claim comment section

Based on which one applies to your center, please refer to **SI B01 01 20** or **B01 07 20** for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

BMW Group’s AIR Application Resource for Flat Rate Labor Operation Codes

To obtain the corresponding flat rate unit (FRU) allowance information from the BMW Group AIR application resource, start by entering the the Chassis Number (last seven (7) characters of the VIN), and click on the “Search” icon. If the “Vehicle Selection” window displays two or more model possible vehicle choices, select the applicable Model, or enter the full VIN (17 characters) instead to proceed. Click on the “Flat Rate Units” button and enter a flat rate labor operation code number “without spaces” in the field to the right, click on the “Flat Rate Units” button.

corresponding FRU allowances.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections
Parts inquiries	Submit an IDS ticket to the Parts Department

Supporting Materials

Videos

[64 01 22](#)

[64 02 22](#)

