



Technical Service Bulletin

57 Power closing door latch is intermittently inoperative, door adjustment is required

57 24 45 2058159/6 June 17, 2024. Supersedes Technical Service Bulletin Group 57 number 23-10 dated June 13, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q7	2017 - 2025	All	Power door closing latch
SQ7	2020 - 2025		

Condition

REVISION HISTORY		
Revision	Date	Purpose
6	-	Revised header (Add Model Year 2025) Revised <i>Warranty</i> (Modify warranty table)
5	06/13/2023	Revised header (Add Model Year 2024)
4	01/19/2022	Revised header (Add Model Year 2023)

Customer states:

- The power closing door latch system intermittently does not work, and the electronic parking brake warning is displayed in the instrument cluster.
- The door closes and latches properly otherwise.

Workshop findings:

- The door striker stops in the pre-latch position and the door is not closed via the power closing door system.
- No relevant DTCs are stored in the door control modules.

Technical Background

The door latch requires counter-pressure from the door/door seal, in order to generate a reliable signal for the door control module that the customer wants to close the door. If the door striker is adjusted in such a way that does not provide enough counter-pressure for the latch, the door control module does not recognize the door latch signal long enough or at all. Hence the door will not be closed.

Production Solution

Not applicable.



Technical Service Bulletin

Service

Before performing any repairs as outlined in this TSB, please check any applicable TSBs (e.g. TSB 2051540: 57 Power closing door latch is intermittently inoperative for MY18) to ensure that the door control modules have the latest software levels installed. Perform any software update related TSBs prior to proceeding with this TSB.

If the customer concern persists with the latest door control module software installed, perform the following steps:

1. Check the door striker to latch alignment and perform any adjustments necessary to center the striker to the latch.
2. At the same time, adjust the door striker inward as far as possible (at least 0.5 mm) (Figure 1). The front door can be flush or slightly under flush to the rear door without causing a wind noise concern (Figure 2).



Figure 1. Adjust door striker inward by at least 0.5 mm.



Technical Service Bulletin



Figure 2. The front door can be flush or slightly under flush to the rear door.

3. Recheck the functionality of the power closing door latch system. If after the striker adjustment the door closes properly, do not proceed with any additional repairs.



Technical Service Bulletin

4. If the customer concern persists, install a new outer door seal with an inward offset of 1.0 mm when compared to the original door seal location (Figure 3).



Tip: Mark the position of the original outer door seal before replacing it.





Technical Service Bulletin

Figure 3. Install the new outer door seal with an inward offset of 1.0 mm.

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Damage Code:	0016		
Service Number:	5741 5841		
Labor Operations:	Front striker plate adjust	5725 1500	See SRT with associated operations
	Rear striker plate adjust	5825 1500	See SRT with associated operations
	Front door outer seal remove + reinstall	5765 1955	See SRT with associated operations
	Rear door outer seal remove + reinstall	5864 1950	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Battery charge	2706 8950	See SRT with associated operations
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2058159/6		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.	
Part Number	Part Description
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual
4M0837911C	Front outer door seal

Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2051540: *57 Power closing door latch is intermittently inoperative.*

All part and service references provided in this TSB (**2058159**) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.