



# Technical Service Bulletin

---

**93 PSS HV Charger: Q5 PHEV warning message on the instrument cluster (DTC B200000 in 00C6)**  
01 24 26 2074344/1 June 21, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5 e quattro	2024	All	Not Applicable

## Condition

### Customer states:

- A warning message is displayed on the instrument cluster.

### Workshop findings:

The following DTC and symptom code is logged in *High Voltage Battery Charger control module -J1050-*, (address word 006C):

- **DTC B200000:** Control module faulty (**symptom 1049088**) active/static.

## Technical Background

Not applicable.

## Production Solution

Not applicable.

## Service

1. Explain to the customer that a solution is in development. A statement pertaining to the availability of this solution is expected to be available by CW 31/24. No repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*).

### Workaround

1. If this PSS applies, please delete the DTC in the *High Voltage Battery Charger control module -J1050-*, (address word 006C) following the instructions in the attachment "q5instructions.pdf".
2. Please inform the customer to use the following procedure when charging with the ULK (Universal Charging Cable) until the new software is available.



# Technical Service Bulletin

- a. When charging on 110V set the ULK to charge at 50% power (Figure 1). The charging power can be changed by long pressing the button above the Audi rings on the ULK.



Figure 1: ULK at 50% charge power.

- b. When charging on 220V 100% charge power can be selected.
- c. Public level 2 charging infrastructure is not affected as they will always charge at 220V.

## Warranty

<b>Claim Type:</b>	<ul style="list-style-type: none"> <li>• 110 Up to 48 Months/50,000 Miles.</li> <li>• G10 for CPO Covered Vehicles – Verify Owner.</li> <li>• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li> </ul>		
<b>Service Number:</b>	9352		
<b>Damage Code:</b>	039		
<b>Diagnostic Time:</b>	GFF	0150 0010	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
	Road test prior to the service procedure	No allowance	0 TU



# Technical Service Bulletin

---

	Road test after the service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB 2074344/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

**Replacing parts or performing other procedures then specified in this PSS will not fix this complaint.  
Replaced parts and associated labor cost will be debited!**

## Additional Information

All part and service references provided in this TSB (**2074344**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.