



Technical Service Bulletin

87 PSS: HVAC control head lighting flickers intermittently

87 24 76 2071176/3 June 21, 2024. Supersedes Technical Service Bulletin Group 87 number 23-58 dated October 9, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron, and Q4 Sportback e-tron	2022 - 2024	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header (Add affected software level) Revised <i>Condition</i> (Add affected software level) Revised <i>Service</i> (Solution target date extended)
2	10/09/2023	Revised header (Add Model Year 2022) Revised <i>Condition</i> (MY 2022 added to bulletin application)
1	08/04/2023	Initial publication

This bulletin applies to 2022 – 2024 Q4 with software 0460 and 0465 (address word 0008) only.

Customer States:

The lighting on the buttons for the front A/C display control head will occasionally flicker. During these episodes the control head will not accept any input.

Workshop Findings:

While this symptom is sporadic in nature, it is possible to reproduce.

Technical Background

During the routine LIN communication between the front air conditioning control head (E87) and the 08 – HVAC Electronics control module (J979) a dissonance can occur in the communication LIN and results in sporadic flickering of the control head lighting.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.



Technical Service Bulletin

Service

1. Explain to the customer that a solution is expected to be available by the end of the 1st quarter 2025 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*). As soon as further information is known, this TSB will be updated.



Tip: A key cycle restores normal operation.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (**2071176**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information an parts bulletins. Please check the repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.