

**Troubleshooting: Front window Pane Reversed – Closes and/or Opens Incorrectly (55/24)**

Model Line: **Macan (95B)**

Model Year: **As of 2019**

Concerns: **Front window pane**

Cause: **Customers complain that the front left or right window pane can be reversed or cannot be opened/closed when ONE touch is pressed.**  
 Moreover, the following fault memory entries can also be stored in the fault memory of the front driver's side / passenger's side door control unit:

- 00083F – Power windows motor, mechanical fault

The complaints indicate that the front power window gets unavoidably sluggish; in **very rare cases**, there is a defect in the power window motor.

Action: Re-normalize the power windows and carry out troubleshooting. Then fix the fault.




**Information**

Replacing components without prior troubleshooting is not expedient.

**Overview of causes for front power windows malfunctions**

- Deformed/damaged window shaft seal ⇒ *Overview of causes for front power windows malfunctions -1-* in the window guide
- Resistance inside the front power windows mechanism ⇒ *Overview of causes for front power windows malfunctions -2-* due to contamination or lack of lubrication
- Dirty window pane ⇒ *Overview of causes for front power windows malfunctions -3-* / high friction on the window pane ⇒ *Overview of causes for front power windows malfunctions -3-*
- Faulty power windows motor ⇒ *Overview of causes for front power windows malfunctions -4-*



*Overview of causes for front power windows malfunctions*

- 1 – Window shaft seal
- 2 – Front power windows mechanism
- 3 – Front window pane
- 4 – Power windows motor

### Required parts and materials as needed

Parts Info:

Required parts for troubleshooting described in this technical information on the front power window:

Part No.	Designation – Location	Quantity as needed
97053755700	⇒ Door trim panel holder – Door trim panel on front door	8 pieces per door

Parts and materials required for individual troubleshooting must be determined using the corresponding Workshop Manual and the Parts Catalogue (PET2).

## Required Tools

- Tools:
- **P90999 - PIWIS Tester 4**
  - Battery charger with a current rating of **at least 90 A**, e.g., **VAS 5908 90A battery charger**. For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ *Workshop Manual '270689 Charging battery and vehicle electrical system'*
  - Torque wrench, 2-10 Nm (1.5-7.5 ftlb.), e.g., **V.A.G 1783 - Torque wrench, 2-10 Nm (1.5-7.5 ftlb.)**

## Re-normalizing front power windows and performing troubleshooting

### NOTICE

Control unit coding will be aborted if the driver's key is not detected

- **If the driver's key is not detected in the vehicle, coding cannot be started or will be interrupted.**
- ⇒ **Place the driver's key with the back facing down into the front left storage compartment in the center console to ensure a continuous radio link between the vehicle and the driver's key.**

- Work Procedure: 1 Connect the battery charger.  
⇒ *Workshop Manual '270689 Charging battery and vehicle electrical system'*
- 2 Check the front power windows function and confirm the fault pattern.
- 3 Remove the door trim panel, but leave the electric plug connections plugged in.  
⇒ *Workshop Manual '705919 Removing and installing front door trim panel'*
- 4 Restore factory setting to the affected door control unit and re-normalize front power windows.
- 4.1 Select "Front driver's side door" or "Front passenger's side door" in the control unit selection screen ('Overview' menu).
- 4.2 Select **Coding/programming**.
- 4.3 Select the **Restore factory settings / coding function (or new part coding)** and confirm with •F12" ('Next').
- The PIWIS Tester displays the message: Coding successful. Press •F12" to continue.
- 4.4 Select **Service/repairs**.
- 4.5 Select **the normalization power windows** function. Press •F12" to continue.
- Follow the instructions and notes of the PIWIS Tester. Press •F12" to continue.
- 4.6 Fulfil all **conditions to be checked manually** and tick them off. •F12" .
- 4.7 To start the **power windows** press •F8" ('Execute'), taking note of the warning message 'Normalization run'.

Assessment		Action
(✓)	The PIWIS Tester displays the message: Normalization run performed <b>successfully</b> .	Continue with Step ⇒ 5.
(✗)	The PIWIS Tester displays the message: Normalization run <b>cancelled</b> .	Continue with Step ⇒ 9.

- 5 Go back to the **Overview**.
- 6 Read out and delete all control unit fault memories.
  - 6.1 Press •F7" in the control unit selection screen ('Overview' menu) to call up the Additional menu.
  - 6.2 Select the function "Read all fault memories and delete if necessary" and press •F12" ('Next') to confirm.
- 7 Exit the diagnostic application, switch off the ignition, disconnect the PIWIS tester from the vehicle.
- 8 Check the front power windows function again.

Assessment		Action
(✓)	Front power windows no longer have <b>any</b> malfunctions after normalization.	A defect in the power windows motor can be ruled out. Then continue with Step ⇒ 9.
(✗)	Front power windows <b>still</b> have malfunctions after normalization.	<p>Replace the power windows motor and re-program the front driver's side door / front passenger's side door control unit. ⇒ <i>Workshop Manual '645419 Removing and installing power windows motor'</i></p> <p>⇒ <i>Workshop Manual '577355 Replacing front door control unit'</i></p> <p>Install the door trim panel. ⇒ <i>Workshop Manual '705919 Removing and installing front door trim panel'</i></p> <p>Then continue with Step ⇒ 10.</p>

- 9 Check the front power windows environment for unwanted resistance.

Assessment		Action
(✓)	<ul style="list-style-type: none"> <li>The window shaft seal is clean, undamaged and installed in the correct position</li> <li>Window pane is clean and free of friction-enhancing deposits</li> <li>Power windows mechanism has no blockages or contamination and is sufficiently lubricated</li> </ul>	Install the door trim panel. ⇒ <i>Workshop Manual '705919 Removing and installing front door trim panel'</i> Then continue with Step ⇒ 11.
(x)	The window shaft seal is dirty.	Clean the window shaft seal. Then continue with Step ⇒ 10.
(x)	The window shaft seal is damaged.	Replace the window shaft seal. ⇒ <i>Workshop Manual '644819 Removing and installing front window shaft seal'</i> Then continue with Step ⇒ 10.
(x)	The window shaft seal is not installed in the correct position.	Install the window shaft seal correctly. ⇒ <i>Workshop Manual '644819 Removing and installing front window shaft seal'</i> Then continue with Step ⇒ 10.
(x)	Window pane has dirt or deposits that increase friction.	Clean the window pane and remove friction-increasing deposits. Then continue with Step ⇒ 10.
(x)	The front power windows mechanism has blockages or contamination or is not sufficiently lubricated.	Clean, repair and lubricate the front power windows mechanism. If irreparable, replace the front power windows mechanism. ⇒ <i>Workshop Manual '645219 Removing and installing front power windows'</i> Then continue with Step ⇒ 10.

- 10 Check the front power windows function again and continue troubleshooting if necessary.
- 11 Switch off and disconnect the battery charger.
- 12 End of action.

**Labor position and PCSS encryption**



**Information**

Select the PCSS encryption of the cause accordingly.

Labor position:

APOS	Labor operation	I No.
64549590	Power windows motor troubleshooting	
64541901	Removing and installing power windows motor	
64541902	Removing and installing power windows motor	
70591901	Removing and installing front door trim panel	
70591902	Removing and installing front door trim panel	
57732551	Re-programming front door control unit	
57732552	Re-programming front door control unit	
64485501	Removing and installing front window shaft seal	
64485502	Removing and installing front window shaft seal	
64521901	Removing and installing front power windows mechanism	
64521902	Removing and installing front power windows mechanism	

PCSS encryption:

Location (FES5)	6454	Power windows motor
Damage type (SA4)	1611	Not functioning

Location (FES5)	6454	Power windows motor
Damage type (SA4)	1711	Sluggish, jams, too little play

Location (FES5)	5773	Front door control unit
Damage type (SA4)	1611	Not functioning

Location (FES5)	6452	Front power windows mechanism
Damage type (SA4)	1611	Not functioning

Location (FES5)	6452	Front power windows mechanism
Damage type (SA4)	1711	Sluggish, jams, too little play

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2024 Porsche Cars North America, Inc.