



Service Bulletin

Bulletin No.: 24-NA-005

Date: July, 2024

TECHNICAL

Subject: Headlamps Flashing and/or DTC P0606 Set in Lighting Control Module

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500HD/ 3500HD	2024	2024	—	—	—	—
GMC	Sierra 2500HD/ 3500HD	2024	2024				

Involved Region or Country	North America, Middle East, Israel, Australia/New Zealand
Condition	Some customers may comment on the headlamps flashing and/or the windshield wiper pausing while wiping. Technicians may find DTC P0606 in the Lighting Control Module set current or in recent history.
Cause	The causes of the condition may be that a low battery state of charge can cause voltage diagnostics to fail in the Lighting Control Module. If the battery goes below the threshold in the Lighting Control Module during a cranking event or battery discharged that needs a jump start, the Lighting Control Module may go into a reset every 8-10 seconds, causing the headlamps to flash.
Correction	DO NOT replace the Lighting Control Module for this condition. A new calibration has been released for the Lighting Control Module. Reprogram the Lighting Control Module with the updated software.

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Caution: Before downloading the update files, be sure the computer is connected to the internet through a network cable (hardwired). DO NOT DOWNLOAD or install the files wirelessly. If there is an interruption during programming, programming failure or control module damage may occur.

- Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.

- Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to www.gmdesolutions.com for further information. If not available, connect a fully charged 12V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.
- Follow the on-screen prompts regarding ignition power mode, but ensure that anything that drains excessive power (exterior lights, HVAC blower motor, etc) is off.
- Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.

Important: The service technician always needs to verify that the VIN displayed in the TLC left side drop down menu and the top center window match the VIN plate of the vehicle to be programmed prior to using Service Programming System 2 (SPS2) for programming or reprogramming a module.

- For the TLC application, service technicians need to always ensure that the power mode (ignition) is "ON" before reading the VIN from the vehicle's VIN master module and that they do not select a VIN that is already in the TLC application memory from a previous vehicle.
- If the VIN that shows up in the TLC top center window after correctly reading the VIN from the vehicle does not match the VIN plate of the vehicle, manually type in the VIN characters from the vehicle VIN plate into the TLC top center window and use these for programming or reprogramming the subject module with the correct vehicle VIN and software and/or calibrations.
- The Engine Control Module (ECM) is the master module (for VIP vehicles) that TLC reads to

determine the VIN of the vehicle. If the VIN read from the vehicle by TLC does not match the VIN plate of the vehicle, the ECM also needs to be reprogrammed with the correct VIN, software and calibrations that match the vehicle's VIN plate.


- The Body Control Module (BCM) is the master module (for GEM vehicles) that TLC reads to determine the VIN of the vehicle. If the VIN read from the vehicle by TLC does not match the VIN plate of the vehicle, the BCM also needs to be reprogrammed with the correct VIN, software and calibrations that match the vehicle's VIN plate.

Caution: Be sure the VIN selected in the drop down menu (1) is the same as the vehicle connected (2) before beginning programming.


The screenshot displays the Techline Connect SPS2 interface. At the top, the 'Techline Connect' header shows the version '1.8.0.2 Production'. Below this is a navigation bar with tabs for 'DASHBOARD', 'GDS2', 'SI', and 'SPS2'. The 'SPS2' tab is active. On the right side of the navigation bar, there are buttons for 'Connect Vehicle', 'Support', 'RPO', and a search bar for 'Search Service Manuals'. The main content area is titled 'Welcome to Service Programming System 2'. It features a 'VIN:' dropdown menu (labeled with a circled '1') showing '1GNSKGM1K2B100170'. To the right of this dropdown, a vehicle status box (labeled with a circled '2') displays '2021 • Chevrolet • Suburban - 4WD'. Below the VIN dropdown, there are fields for 'Model: Suburban - 4WD', 'Type: -', 'Make: Chevrolet', 'Year: 2021', and 'Job Card:'. To the right of these fields, there are buttons for 'Auto Detect New Vehicle' and 'Manually Enter Vehicle'. On the far right, there is a 'Diagnostic Tool Ready!' section with 'J2534' and a 'Selected Programming Process' dropdown set to 'Reprogram'. At the bottom left, there are buttons for 'Print' and 'Settings'. At the bottom right, there are buttons for 'Auto Detect Tool' and 'Manual'.

5743643

Important: If the vehicle VIN DOES NOT match, the message below will be shown.




5877000



Important: Techline Connect screen shown above.
Important: If the same calibration/software warning is noted on the TLC Summary screen, select OK and follow screen instructions. After a successful programming event, the WCC is located in the Service Programming System dialogue box of the SPS Summary screen. Record the WCC on the job card. No

further action is required. Refer to the Warranty Information section of this bulletin.
1. Reprogram the Lighting Control Module. Refer to *K219 Lighting Control Module: Programming and Setup*.

5644477



5644478

Note: The screenshot above is an example of module programming and may not be indicative of the specific module that is being programmed. Module selection and VIN information have been blacked out.

Important: To avoid warranty transaction rejections, you **MUST** record the warranty claim code provided on the Warranty Claim Code (WCC) screen shown above on the job card. Refer to callout 1 above for the location of the WCC on the screen.

- Record the SPS Warranty Claim Code on the job card for warranty transaction submission.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2811105*	K219 Lighting Control Module Reprogramming with SPS	Use Published Labor Operation Time

Important: *To avoid warranty transaction rejections, carefully read and follow the instructions below:

Labor Operation	Description	Labor Time
Labour Time [Top] Labour Operation Code: Additional labour op code information: SPS Warranty Claim Code:		

- The Warranty Claim Code must be accurately entered in the “Warranty Claim Code” field of the transaction.
- When more than one Warranty Claim Code is generated for a programming event, it is required to document all Warranty Claim Codes in the “Correction” field on the job card. Dealers must also enter one of the codes in the “Warranty Claim Code” field of the transaction, otherwise the transaction will reject. It is best practice to enter the FINAL code provided by SPS2.

6125814

Warranty Claim Code Information Retrieval

The screenshot shows the 'Warrant Claim Code' window, which is part of a larger application. The window has a title bar with tabs: 'Common', 'Diagnostics', 'Logging', 'Warrant Claim Code' (selected), and 'Local Cache'. Below the tabs is a table with five columns: VIN, Module, Function, Warranty Claim Code, and Job Card. The table contains four rows of data:

VIN	Module	Function	Warranty Claim Code	Job Card
[REDACTED]	K73 - Telematics Communication Interface Control Module	Programming & Service Activation	[REDACTED]	test
[REDACTED]	K9 - Body Control Module	Programming	[REDACTED]	test
[REDACTED]	K5 - Automatic Level Control Module Ignition	Off	[REDACTED]	test driver
[REDACTED]	K56 - Serial Data Gateway Module	Programming	[REDACTED]	test driver

At the bottom right of the window are 'Ok' and 'Cancel' buttons. A red circle with the number '2' points to the 'Warranty Claim Code' tab. Another red circle with the number '1' points to the 'Settings' button at the bottom left of the main application window.

If the Warranty Claim Code was not recorded on the Job Card, the code can be retrieved in the SPS2 system as follows:

1. Open TLC on the computer used to program the vehicle.
2. Select and start SPS2.
3. Select Settings (1).

4. Select the Warranty Claim Code tab (2).

The VIN, Warranty Claim Code and Date/Time will be listed on a roster of recent programming events. If the code is retrievable, dealers should resubmit the transaction making sure to include the code in the SPS Warranty Claim Code field.

Version	2
Modified	Released January 10, 2024 Revised July 16, 2024 – Revised Correction and Service Procedure with programming instructions and revised Warranty Information with SI Labor Operation.

