



Bulletin No.: PIT6169

Published date: N/A

# Preliminary Information

## PIT6169 K45 Powertrain Control Module Fails Key Provisioning Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Traverse	2024	All	All	LK0	All
GMC	Acadia	2024	All	All	LK0	All


Involved Region or Country	North America
Condition	<p>During any module programming event that is followed by Key Provisioning (aka Serial Data Authentication Configuration/SDAC) the K45 PCM has the potential to fail key provisioning and U1962 will set.</p> <p>If this occurs it is not possible to recover the Powertrain Control Module (PCM) and it will need to be replaced.</p>
Cause	Software bug in the K45 PCM.

**Correction:**

**Note:** This condition will only present itself after a module programming event (any module) that is followed by Key Provisioning (Serial Data Authentication Configuration).

This condition will not occur on every programming event but may occur at times.

If you see the screen below at the end of programming you will need to access the SPS logs to determine if the PCM has locked up .





Take a photo or screenshot of the screen showing the ECU \$10 log and save it.  
The PCM is on parts restriction. Follow PIP5970 to obtain a replacement.  
The screenshot or photo of the log will be needed by PQC for authorization of a replacement PCM.  
If you are unable to locate the SPS failure logs and need assistance with this call TCSC at 800-828-6860.  
If ECU \$10 is not found in the log follow SI diagnostics for vehicle concern.

Warranty Information

Version History

Version	1
Modified	05/07/2024 - Created on.



© 2024 General Motors. All Rights Reserved.