



Bulletin No.: PIC6557

Published date: 06/11/2024

Preliminary Information

PIC6557 Super Cruise Unavailable Message

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Equinox EV	2024	All All	All	All
Cadillac	CT5	2025	All All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UKL
Condition	<p>Customers may notice a Super Cruise Unavailable, Adaptive Cruise Unavailable or a Service Driver's Assist message on the DIC.</p> <p>This could happen immediately upon startup or within 30 minutes of the drive cycle .</p> <p>This issue may recover after an ignition cycle or it may not.</p> <p>Technician may find the following DTC's setting in the K124 Image Processing Module (IPCM), see list below.</p>
Cause	Software

Correction:

Dealers are asked to verify the customers concern and wait until engineering provides a resolution.

If any of the DTCs listed below are set do not replace the controller.

Advise the customer that engineering is working on a solution for this concern.

U053C sym00
U023B sym00
U1624 sym00
B1DD0 sym57
B0126 sym82
U164E sym00

If none of these DTC's are setting, follow normal SI Diagnostics.
This PI will be converted to a bulletin when a resolution is available.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2887698	Verify DTCs are setting in the Image Processing Module and SuperCruise is unavailable	.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	06/11/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.