

167 Air Conditioning Evaporator Leaking

Topic number	LI83.30-P-077763
Version	12
Function group	83.30 - Air conditioning
Date	8/2/24
Validity	167
Reason for change	Remedy

Complaint

Customer concern of Air Conditioning not cooling.

Cause

Possible refrigerant leak at the evaporator.

Remedy

Perform the following measures :

1. Initial Quick Test
2. Create a short video of the actual pressures via AC machine, showing the engine running, and hold a copy of the VIN/RO in view as well.
3. Picture of the forming gas check being performed with VIN/RO in view.
4. OBS recording of XENTRY AC actual values of compressor request to be on and current value. (Instructions in Attachments)
5. Video recording of the leak being found via sniffer at the R/F AC drain after removing the under dash panel. (see attached videos)
6. If the evaporator is found to be leaking via sniffer, another video needs to be uploaded (or a continuation if only making the video after checks), showing the expansion valve being checked for leaks.
7. If no leaks are found with the sniffer at the expansion valve, spray soapy water mix on the expansion valve and check for leaks. Upload a video showing the spray test and VIN.
8. If the vehicle is produced AFTER June 2023, a TIPS case is required for replacement. Please open a TIPS case in the HV/LV inbox labeled "167 Evaporator Suspected of Leaking" with all attachments.
9. For vehicles produced during or prior to June 2023, a TIPS is not necessary. However, parts from repairs on such vehicles may be requested back for analysis at the QEC. Therefore, please follow parts disposition in NetStar. Repairs where parts are not returned per parts disposition instructions, or parts found to be NTF (no trouble found) are subject to debit.

NOTE:

- Please see the list of WIS documents for forming gas leak check and recharging of the system.

XENTRY Tips

- All documents, with the exception of videos need to be uploaded for the warranty claim. Videos are only needed if a TIPS case is opened.
- Ensure that a full vacuum is pulled on the system for at least 30 minutes after replacement
- Condenser replacement is NOT authorized as a suitable repair in lieu of the dryer not being available.

Attachments

File	Description
Expansion valve leak.mkv	
Leak at drain hose.mkv	
OBS screen recording installation instructions for XENTRY.pdf	

WIS-References

Document number	Title	Note
AR83.30-P-1760ME	Drain, evacuate and recharge air conditioning, check for proper operation and check for leaks	Performing drain and refill
AR83.30-P-1761ME	Check air conditioning system for leakage	Must be done for all leak checks
AR83.30-P-1785ME	Flush air conditioning	Only to be performed if debris is found in the system
SI83.30-P-0021A	Service Information: Damage code	Notes for damage code to be used.

Symptoms

Body > Air conditioning > Air conditioning > Insufficient cooling output

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
	Damage Code		8343204	Submit all claims under this damage code
540650	Battery Maintainer			
541011	Quick Test			
826455	Extra work for left wiper			(only with code 874)
826456	Extra for right wiper			(only with code 874)
826890	Check wiper angle			(only if required)
831232	Video and pictures as required in Li			Up to 0.7hr allowable time
831762	AC drain/fill/check			
832975	R&R cowl			