

## HIGH VOLTAGE COOLANT HEATER (HVCH) INOPERATIVE-MALFUNCTION (PHEV) DTC B1DC5-64

### Customer Voice:

- Poor passenger compartment heating performance and/or slow to warm up
- EV mode being unavailable

### Technical Description:


- DTC B1DC5-64 HVCH (Overheat detected) stored in the HVAC Module for one of the following reasons:
  - No or low flow of coolant in the cooling system
  - Air in the cooling system
  - Auxiliary passenger compartment coolant pump issue
  - Coolant hose incorrectly installed or faulty.

### Status:

- If DTC B1DC5-64 is stored, Do not renew the HVCH . This indicates that the HVCH has had an overheat prevention event and will not operate for that drive-cycle.
- If DTC B1DC5-93 (High Voltage Coolant Heater #1 - No Operation) is also stored and cannot be erased, then the HVCH should be replaced.
- Follow TOPIx DTC help text and workshop manual repair guidance.

### Range Rover

- 19-24MY Range Rover
- 19-24MY RR Sport



E318436

Refer to SSM 76146