

SERVICE ACTION H504/N906 – BODY CONTROL MODULE (BCM) RENEW – USA ONLY

SERVICE ACTION H504/N906 - BODY CONTROL MODULE (BCM) RENEW – USA ONLY	
AFFECTED MODELS	18-20MY F-PACE, 20MY I-PACE, 20MY XE, and 20-22MY XF 17-21MY Range Rover(L405), 19-22MY Range Rover Sport (L494), 19-20MY Range Rover Velar, 20MY Range Rover Evoque 17-20MY Discovery
VOLUME AFFECTED	76 US
REPAIR	A concern has been identified on certain JLR vehicles, where the Body Control Module (BCM) does not fully meet US importation requirements. The requires BCM replacement with a new component which fully meets the US importation requirements.
REPAIR TIME	0.7hrs. + DIDO
CAMPAIGN LAUNCH	Launched on July 26th, 2024
NOTES	The BCM being replaced must be secured at the retailer, for return to JLR via the Priority Return Request (PRR) process. An EPQR must be submitted to facilitate the PRR process. Please refer to the bulletin instructions when published for parts return instructions.